



भारत सरकार GOVERNMENT OF INDIA
खान मंत्रालय MINISTRY OF MINES
भारतीय खान ब्यूरो INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक के कार्यालय
OFFICE OF THE REGIONAL
CONTROLLER OF MINES



BY REGD POST A/

D

Phone: 0674-2352463

Tele Fax: 0674-2352490

E-mail:

ro.bhubaneshwar@ibm.gov.in

Plot No.149, Pokhariput

BHUBANESWAR-751020

दिनांक -

24/07/2024

प्रेषिति-

श्री हिरक मजूमदार, नोमीनटेड ओनर
M/S रूंगटा संस(पी) लिमिटेड,
Rungta office, Main Road, Barbil
Dist. Keonjhar,
Odisha - 758035

विषय-

ओडिशा राज्य के सुंदरगढ़ जिले में स्थित आपकी ओराघाट लौह अयस्क खदान 82.961 हे० में खनिज संरक्षण एवं विकास नियमावली 2017 के नियमों के उल्लंघन के संबंध में-

महोदय

The following provisions of Mineral Conservation and Development Rules, 2017 were found violated during inspection of the above mine on 02.07.2024 by undersigned accompanied by Sri A. S. Mahapatra, Agent cum Sr.V.P (Mining), Shri S.C. Pradhan, Mines Manager & Shri Abhijit Sen, Sr. V.P (Geology).

| Rule | Nature of Violation observed | | | | | | | | | | |
|------------|--|------------|-------------------|--------|------|--------|---------|--------|---------|-----------|---------|
| 11(1) | Mining operations should have been undertaken in accordance with the Mining Plan/ Review of Mining Plan. The Review of Mining Plan was approved vide letter no. BBS/SNG/IRON/2187/RMP/2022-23 dated 10.01.2023 and following deviation was observed during inspection 1. The proposed mineral production of ROM 7350000 MT in 2023-24 but production of ROM reported 5449579.070 MT which is approximately 74% of proposal. 2. During mine visit it was observed that that bench parameters are not as per proposal. The benches not developed as per proposal. The maximum height of bench was proposed 9 meter and minimum width 9-12 meter but bench height in Kusum pit in many places 12-14 meter and width also less than proposal. The bench height between BP13-BP14 is 15 meter. 3. The proposal for garland drain was given in 2023-24 for 230 m but it was observed garland drain not done and existing drain is filled with silt and boulder. | | | | | | | | | | |
| 33 | The holder of a mining lease shall, on or before the 30th day of June every year submit plan and section as per Rule to the authorised officer but it was observed that the surface plan & surface geological plan submitted are not submitted as per actual field position and the bench parameters shown in plan is not surveyed properly. The plan is also not matching with the drone data submitted. | | | | | | | | | | |
| 45(5)(b) | While scrutiny of Monthly returns April-May'24 few discrepancies observed 1. It was observed that the ex-mine price for the CLO below 62%Fe is less than the Ex-mine price of fines 60-62%fe in the month of April'24. 2. It was observed that the ex-mine price of fines above 65%Fe is mentioned as Rs3680.19/- and fines 60-62% Fe Rs 3912/- in the month of May'24. This shows low grade ore Ex-mine price is more of Rs 230/-. 3. The Iron Ore dispatch to Rungta Mines limited is mentioned as domestic sale. | | | | | | | | | | |
| | While scrutiny of Annual returns 2023-24 few discrepancies observed 1.As per the table Ex-mine price of 55-58% fe (fines) is more than Ex-mine price of 60-62%Fe & above 65%fe. <table border="1"> <thead> <tr> <th>FE%(Fines)</th> <th>Ex-Mine Price(Rs)</th> </tr> </thead> <tbody> <tr> <td>55-58%</td> <td>4529</td> </tr> <tr> <td>60-62%</td> <td>3929.86</td> </tr> <tr> <td>62-65%</td> <td>4631.54</td> </tr> <tr> <td>Above 65%</td> <td>4417.30</td> </tr> </tbody> </table> 2. The Ex-mine price of CLO below 62%Fe is less than the Ex-mine price of all the grade(except 60-62%fe fines) of fines as mentioned in the return. 3. The Iron Ore dispatch to M/S Rungta Mines limited is mentioned as domestic sale. | FE%(Fines) | Ex-Mine Price(Rs) | 55-58% | 4529 | 60-62% | 3929.86 | 62-65% | 4631.54 | Above 65% | 4417.30 |
| FE%(Fines) | Ex-Mine Price(Rs) | | | | | | | | | | |
| 55-58% | 4529 | | | | | | | | | | |
| 60-62% | 3929.86 | | | | | | | | | | |
| 62-65% | 4631.54 | | | | | | | | | | |
| Above 65% | 4417.30 | | | | | | | | | | |

2 इस संदर्भ में आपका ध्यान आकर्षित किया जाता है कि उपरोक्त नियमों का उल्लंघन खनिज संरक्षण एवं विकास नियमावली 2017 के नियम 62 के अंतर्गत दंडनीय अपराध है। एवम इस नियम का उल्लंघन की अनुपालना नहीं होने पर खनिज संरक्षण एवं विकास नियमावली 2017 के नियम 11(2) एवम 45(7)(क) के अंतर्गत

1/36418/2024

- (क) खान की सारी खनन संक्रियाए बंद की जा सकती है।
(ख) आपके विरुध अभियोग दायर किया जा सकता है ।
(ग) खनन पट्टे को निरस्त करने की सिफारिस राज्य सरकार से की जा सकती है।
- 3 अतः आपको सलाह दी जाती है कि आप उपरोक्त उल्लंघनो का अतिशिघ्र सुधार करे एवम इसके सुधार की सूचना इस पत्र के जारी होने से 45 दिन के भितर इस कार्यालय को सूचित करे।

भवदीय

(राजेश कुमार दास)
उप खान नियंत्रक
भारतीय खान ब्यूरो, भुवनेश्वर

Copy forwarded for kind information to:

- (1) The Director of Mines, Directorate of Mines, Government of Odisha, Heads of Department Building, Bhubaneswar-751 001
(2) The Controller of Mines (EZ), Indian Bureau of Mines, CP-13, Sector V Salt Lake City, Kolkata- 700 091.

(राजेश कुमार दास)
उप खान नियंत्रक
भारतीय खान ब्यूरो, भुवनेश्वर