1/36884/2024



भारत सरकार GOVERNMENT OF INDIA खान मंत्रालय MINISTRY OF MINES भारतीय खान ब्यूरो INDIAN BUREAU OF MINES क्षेत्रीय खान नियंत्रक के कार्यालय OFFICE OF THE REGIONAL CONTROLLER OF MINES



## BY REGD POST A/

D

Phone: 0674-2352463 Tele Fax: 0674-2352490

ro.bhubaneshwar@ibm.gov.i

Plot No.149, Pokhariput BHUBANESWAR-751020

दिनांक -30/07/2024

प्रेषिति-

Smt Geetarani Mohanty, Owner, 380,BOMIKHALCUTTACK PURI ROAD, BHUBANESWAR.

Dist- Khodha, Odisha-751010

e-mail: geetarani.mines@gmail.com,

ओडिशा राज्य के **सुंदरगढ़** जिले में स्थित आपकी ओराघाट लौह अयस्क खदान 82.961 हे॰ में खनिज सरक्षण एवं विकास विषय-

नियमावली 2017 के नियमों के उलंघन के संबंध मे-

महोदय

The following provisions of Mineral Conservation and Development Rules, 2017 were found violated during inspection of the above mine on 03.07.2024 by undersigned accompanied by Shri Promod kumar sahoo, Mines Manager & Shri Pradeent Mohanatra Geologist

Mines Ma	es Manager & Shri Pradeept Mohapatra, Geologist.			
Rule	Nature of Violation observed			
11(1)	Mining operations should have been undertaken in accordance with the Mining Plan/ Review of Mining Plan.  The Review of Mining Plan was approved vide letter no. BBS/SNG/IRON/2187/RMP/2022-23 dated 10.01.2023 and following deviation was observed during inspection  1. During mine visit it was observed that the south pit was not developed as per proposal. The benches(3-4 benches) in south pit was proposed along lease boundary pillar(ML11-ML13) but benches not developed accordingly  2. The last modification done to developed benches in common boundary from ML1-ML20 (common			
45(5)(b)	boundary working with PTA proposed) but no development observed.  While scrutiny of Monthly returns April-May'24 few discrepancies observed  1. It was observed that the ex-mine price for the CLO 62-65%Fe(10-40mm) is approx. Rs 600/-less than the Ex-mine price of CLO 60-62%fe(5-18mm) and fines of 60-62%Fe is Rs 130/- less than fines of 60-62%Fe in the month of April'24.This shows low grade Ex-mine price is more.  2. It was observed that the ex-mine price for the CLO 62-65%Fe(10-40mm) is approx. Rs 1925/-less than the Ex-mine price of CLO 60-62%fe(5-18mm) in the month of May'24.			
45(5)(c)		ice of 60-62% fe (fines Ex-Mine Price(Rs) 3082.93 3513.93 3500.00 price of CLO 62-65%F	c) is more than Ex-mine pric CLO FE% Below 62% any size 62-65%(5-18mm) 62-65%(10-40mm) Se(size 10-40mm) is less the	Ex-Mine Price(Rs  4592.91  6070.77  3000.00  an the Ex-mine price of all the
48(1)	grade of CLO and also grade of fines more than 55-58% fe as mentioned in the return.  The holder of a mining lease or the holder of a prospecting licence or 1 [composite licence] shall keep a record in Form-J of all shafts or boreholes but during mine visit it was observed that the form-J was not maintained as per Rule and the nomenclature of bore holes is not matching with the log box and as marked in geological plan and section.			

- इस संदर्भ में आपका ध्यान आकर्षित किया जाता है कि उपरोक्त नियमों का उल्लंघन खनिज संरक्षण एवं विकास नियमावली 2017 के नियम 62 के अंतर्गत दंड्नीय अपराध है1 एवम इस नियम का उल्लंघन की अनुपालना नहीं होने पर खनिज संरक्षण एवं विकास नियमावली 2017 के नियम 11(2) एवम 45(7)(क) के अंतर्गत
  - (क) खान की सारी खनन संक्रियाए बंद की जा सकती है1
  - (ख) आपके विरुध अभियोग दायर किया जा सकता है 1
  - (ग)खनन पट्टे को निरस्त करने की सिफारिस राज्य सरकार से की जा सकती है1
- अत: आपको सलाह दी जाती है कि आप उपरोक्त उल्लंधनो का अतिशिघ्र सुधार करे एवम इसके सुधार की सूचना इस पत्र के जारी होने से 45 दिन के भितर इस कार्यालय को सूचित करे1

1/36884/2024

भवदीय

(राजेश कुमार दास) उप खान नियंत्रक भारतीय खान ब्यूरो, भुवनेश्वर

## Copy forwarded for kind information to:

- (1) The Director of Mines, Directorate of Mines, Government of Odisha, Heads of Department Building, Bhubaneswar-751 001
- (2) The Controller of Mines (EZ), Indian Bureau of Mines, CP-13, Sector V Salt Lake City, Kolkata- 700 091.

(राजेश कुमार दास) उप खान नियंत्रक भारतीय खान ब्यूरो, भुवनेश्वर