



भारत सरकार GOVERNMENT OF INDIA  
खान मंत्रालय MINISTRY OF MINES  
भारतीय खान ब्यूरो INDIAN BUREAU OF MINES  
क्षेत्रीय खान नियंत्रक के कार्यालय  
OFFICE OF THE REGIONAL  
CONTROLLER OF MINES



BY REGD POST A/D  
Phone: 0674-2352463  
Tele Fax: 0674-2352490  
E-mail:  
ro.bhubaneshwar@ibm.gov.in  
Plot No.149, Pokhariput  
BHUBANESWAR-751020

दिनांक -

02/05/2025

प्रेषिति-

Sri Vishal Atha, Nominated Owner,  
Roida-II Iron Ore Mines,  
M/s. Narbheram Power & Steel Pvt. Ltd.,  
Avani Signature, 6th Floor, 91A/1, Park Street,  
Kolkata, West Bengal-700016,  
Email – [npspl@athagroup.in](mailto:npspl@athagroup.in)

विषय- ओडिशा राज्य के केउंझर जिले में स्थित आपकी रोइदा -II लौह आयेस्क खदान 74.867 Ha (as per RoR)/74.702 Ha (as per DGPS) में खनिज संरक्षण एवं विकास नियमावली 2017 के नियमों के उल्लंघन के संबंध में-

महोदय

The following provisions of Mineral Conservation and Development Rule, 2017 were found violated in respect of the above said mine during inspection on 10.04.2024 by the undersigned, in presence the mine officials Sri Sadananda Rana(Mines Agent), Sri Prasanta Kumar Mohanty (Mines Manager) and Sri Atanu Bandopadhyay (Geologist).

Rule	Nature of Violation observed
11(1)	<p>Mining operations should have been undertaken in accordance with the Mining Plan/ Review of Mining Plan. The Modification of Mining Plan was approved vide letter no. MPM/A/04-ORI/BHU/2021-22 dated 31.05.2021 and following deviation were observed during inspection</p> <ol style="list-style-type: none"> <li>In 2022-23 total 11 nos core bore holes &amp; in 2023-24 14 bore holes proposed in which 9 nos and 13 nos core bore holes in respective years 2022-23 &amp; 2023-24 were drilled.</li> <li>During the mine visit it was observed that the proposed bench parameters are not followed and bench height in both the quarry (Quarry-6 &amp; Quarry-2) in many places more than proposed bench height and some places it more than 20 meter. The bench width is less than bench height and proposal given in Mining plan.</li> </ol>

- इस संदर्भ में आपका ध्यान आकर्षित किया जाता है कि उपरोक्त नियमों का उल्लंघन खनिज संरक्षण एवं विकास नियमावली 2017 के नियम 62 के अंतर्गत दंडनीय अपराध है। एवम इस नियम का उल्लंघन की अनुपालना नहीं होने पर खनिज संरक्षण एवं विकास नियमावली 2017 के नियम 11(2) के अंतर्गत
  - खान की सारी खनन संक्रियाएं बंद की जा सकती हैं।
  - आपके विरुद्ध अभियोग दायर किया जा सकता है।
  - खनन पट्टे को निरस्त करने की सिफारिस राज्य सरकार से की जा सकती है।
- अतः आपको सलाह दी जाती है कि आप उपरोक्त उल्लंघनों का अतिशिघ्र सुधार करें एवम इसके सुधार की सूचना इस पत्र

I/31058/2024

के जारी होने से 45 दिन के भितर इस कार्यालय को सूचित करे।

भवदीय

(राजेश कुमार दास)  
उप खान नियंत्रक  
भारतीय खान ब्यूरो, भुवनेश्वर

Copy forwarded for kind information to:

(1) The Director of Mines, Directorate of Mines, Government of Odisha, Heads of Department Building, Bhubaneswar-751 001

(2) The Controller of Mines (EZ), Indian Bureau of Mines, CP-13, Sector V Salt Lake City, Kolkata-700 091.