

उलंघन पत्र - Speed post/Email

भारत सरकार, खान मंत्रालय
 GOVERNMENT OF INDIA, MINISTRY OF MINES
 भारतीय खान ब्यूरो, क्षेत्रीय खान नियंत्रक कार्यालय- भुवनेश्वर
 INDIAN BUREAU OF MINES, OFFICE OF REGIONAL CONTROLLER OF MINES- BHUBANESWAR
 प्लॉट नं-149, पो खरी पुट - भुवनेश्वर Plot no.149, Pokhariput, Bhubaneswar PIN-751020, Phone-
 0674-2352 463 /490, ईमेल- ro.bhubneshwar@ibm.gov.in

File No. MCDR-MiFLOFE/35/2023-BBS-IBM_RO_BBS

Bhubaneswar, 18/11/2024

To,
 Shri Rajkumar Mishra,
 Nominated Owner,
 Badampahar Iron Ore Mine
 GM Iron and Steel Company Limited
 At/Po- Badampahar, Dist- Mayurbhanj,
 Odisha-757047
 E-mail: gmsteelbmpr@gmail.com

Subject: Violation of provisions of MCDR, 2017, in respect of your Badampahar Iron Mine (30ORI10021) over an area of 129.61 Ha in Village, Dhangudimuta, Tahsil: Kusumi, Mayurbhanj district of Odisha State.

Sir,

The following provisions of MCDR 2017 were found violated in your above mine during inspection carried out on 16th October 2024 by the undersigned in presence of the mine officials S/Sri Harendra Narayan Das, Agent, Rajesh Kumar, Mines Manager and Susanta Kumar Mohanta, Geologist

11(1)	Mining operations in the mining lease are not being carried out in accordance with as per the proposal given in Modification in Review of Mining Plan vide letter No. MCDR-MiFLOFE/35/2023-BBS-IBM_RO_BBS dated 03.08.2023 to the extent given below: 1. During year 2023-24 it was proposed to carryout mining operations in pits viz. Peak, Bapet and Chmpajharan Quarry . However during inspection it was observed that no work was carried out in Champajharan Quarry
31(4)	No up to date plan was found maintained during inspection.
19(1) & (2)	1. Log books duly authenticated by the manager or mining engineer in respect of each machine showing date-wise account of hours worked, hours not worked, reasons for non-working, consumption of fuel or energy and lubricants and output of the machine during the corresponding working hours was not found maintained during inspection. 2. The summary of operation of each machine in the log book at the end of each month bringing out the percentage availability and percentage utilisation of the machine, average hourly performance and average fuel or energy consumption per hour was not included in the Log Books.

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of Mineral Conservation and Development Rules, 2017.

03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.

04. You are advised to rectify the violation immediately and intimate the position to this office within a period of 45 (Forty five) days from the date of issue of this letter.

Yours faithfully

(Vikram Deshpande)
 Assistant Controller of Mines
 Indian Bureau of Mines

Copy forwarded for kind information to:

- The Controller of Mines (EZ), Indian Bureau of Mines, Kolkata-790001.
- The Director of Mines, Directorate of Mines, Government of Odisha, Heads of Department Building, Bhubaneswar-751001

(Vikram Deshpande)
 Assistant Controller of Mines
 Indian Bureau of Mines

