Violation letter



भारत सरकार /GOVERNMENT OF INDIA खान मंत्रालय/ MINISTRY OF MINES भारतीय खान ब्यूरो /INDIAN BUREAU OF MINES क्षेत्रीय खान नियंत्रक कार्यालय/ OFFICE OF THE

REGIONAL CONTROLLER OF MINES



दूरभाष: (080) 39505368 / 29720499 Email ID: ro. bangalore@ibm.gov.in. 29, इंडस्ट्रियल सबर्ब 11 स्टेज, तुमकुर रोड,

गोरगुंटापाल्या येशवंतपुर, बेंगलुरु -560022

सं.E- 3863 - MCDR-MiFL0FE/11/2023-BNG-IBM_RO_BNG

दिनांक: 20.11.2024

सेवा में Shri Syed Ahmed

Nominated Owner, ZEENATH ML NO. 2120 IRON ORE MINE ZEENATH HOUSE COWL, BAZAR BELLARY

ztco2000@yahoo.com, transitsurveys@gmail.com

বিষয/Sub: Violation of provisions of MCDR, 2017 in respect of your Dharmapura Iron ore mine (ML No. 2309) over an extent 36.42Ha, located in Ramgad Village, Sandur Taluk, Bellary District, Karnataka State.

महोदय/Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 read with Mineral Conservation and Development (Amendment) Rules, 2021 were found violated during the mining operation for the year 2023-24 in your above said mine during inspection on 24.10.2024 for examination of Review Of Mining Plan submitted Under Rule 17(2) Of MCR, 2016 and also for MCDR and SDF validation by Dr. Omkesha Murthy, Regional Mining Geologist along with Shri Ashish Kumar Behra, AMG of this office.

Rules	Nature of Violations observed
11(1)	The Mining operations required to be carried out in accordance with the
	approved Modified to the approved Mining Plan document vide letter no.
	279/68/89/BNG dated 29/11/2022, However, during the inspection deviations
	were observed in mining operation vis-à-vis approved document and are as
	follows:
	1. For the year 2023-24, it was proposed to mine the reef ore between
	section line BB' and DD', however, during the inspection it is observed
	that there is no Production & Development carried out at the proposed
	location and the same was verified by Updated plans and also on the
	drone image submitted in the DDMS portal.

- 02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR (Amendment), 2021
- 03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.
- 04. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty-Five) days from the date of issue of this letter.

भवद)य/Yours faithfully,

Signed by Sudhakara T L Date: 27-11-2024 11:26:01 Copy for kind information to:

- 1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
- 2. The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560001.