



भारत सरकार

खान मंत्रालय

भारतीय खान ब्यूरो,

क्षेत्रीय खान नियंत्रक कार्यालय, रायपुर

द्वितीय तल, जी० एस० आई० फील्ड प्रशिक्षण केन्द्र, महालेखाकार कार्यालय परिसर,  
पोस्ट-विधानसभा, रायपुर-492005 (छत्तीसगढ़)फोन एवं फैक्स-0771-2282530, 2285590/95 ई-मेल: [ro.raipur@ibm.gov.in](mailto:ro.raipur@ibm.gov.in)

प्रेषिति-

श्रीमती लालमती सिंह,  
पट्टेदार, सहगांव चुनापथर खान,  
EWS-93, वैशाली नगर, भिलाई,  
जिला- दुर्ग, छत्तीसगढ़-490023  
ईमेल-[rstc12@gmail.com](mailto:rstc12@gmail.com)

विषय : छत्तीसगढ़ राज्य के दुर्ग जिले में स्थित आपके सहगांव चुनापथर खान 4.82 हैक्टर (खान कोड-38CHG05021) में खनिज संरक्षण एवं विकास नियमावली 2017 (यथा संशोधित) के नियमों के उल्लंघन के संबंध में |

महोदय,

आपकी उपरोक्त खान का निरीक्षण दिनांक 16.07.2024 को अधोहस्ताक्षरी द्वारा श्री मनोज कुमार, भूविज्ञानी एवं श्री संतोष कुमार सिंह, खनन अभियंता की उपस्थिति में किया गया तथा खान के निरीक्षण के उपरांत पाया गया कि आपने खनिज संरक्षण विकास नियमावली 2017 (यथा संशोधित) के निम्नलिखित नियमों का उल्लंघन किया है |

नियम	उल्लंघन के प्रकार का विस्तृत ब्यौरा
11(1)	<p>The Mining operations required to be carried out in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines. However, during inspection of the mine, mining operations observed not carried out in your aforesaid mine in accordance with the Review of Mining Plan (RMP) approved dated 24.03.2022 to the extent indicated below: -</p> <ol style="list-style-type: none"> <li>Exploration was proposed to be carried out by drilling of 03 nos. of core bore holes up to the depth of 100 meter each in the ML area in the year 2022-23; whereas, no borehole has been drilled so far.</li> <li>There was proposal of fencing of 10 meter length along the lease boundary during the year 2023-24 in between pillar no. BP-1 to BP-2. Whereas, no such fencing has been found erected as envisaged.</li> <li>There was proposal of construction of 10 meter garland drain along the lease boundary during the year 2023-24 in between pillar no. BP-10 to BP-11. Whereas, no such garland drain has been found constructed.</li> </ol> <p>Hence, above are observed to be against the systematic &amp; scientific development of the mine and also against the protection of environment in the mine.</p>
31(4)	<p>The Plans &amp; sections have not been maintained up to date within three months as required under this rule for Category 'A' mines; and the same was not made available during the inspection.</p>
45(7)	<p>In annual return submitted for financial year 2023-24 following discrepancies are observed;</p> <ol style="list-style-type: none"> <li>At Part-I, Para-03 (10), date of transfer is furnished as 01/01/1970, whereas lease has not been transferred any time.</li> <li>At Part-I, Para-12, the lease area (surface area) utilization at the end of the year</li> </ol>

	<p>(hectares) is furnished incorrectly.</p> <p>iii. At Part-V, Para-01, the exploration activities at the beginning of the year are not furnished.</p> <p>iv. At Part-V, Para-06, the details of mining machineries reported incompletely as details about excavators are not furnished.</p> <p>v. At Part-V, Para-02, closing stock of ROM ore at mine-head is furnished incorrectly without any base.</p> <p>vi. At Part-VI, Para-03(ii), closing stock at mine-head of the cement grade limestone is reported as 26475 Tonnes. However, such substantial quantity of limestone was not observed properly stacked at the mine head.</p> <p>vii. At Part-V, Para-03, ex-mine price (₹-Tonne) of the cement grade limestone despatched is furnished incorrectly as it does not match with the sale value of the mineral reported in Para-05.</p> <p>The above discrepancies may be construed as providing incomplete or wrong or false information in the submitted annual returns.</p>
55	The part time Mining Engineer (Shri Sontosh Kumar Singh) as appointed does not possess the requisite qualification as required under this rule.

02. इस संदर्भ में आपका ध्यान आकर्षित किया जाता है कि उपरोक्त नियमों का उल्लंघन खनिज संरक्षण एवं विकास नियमावली 2017 (यथा संशोधित) के नियम 62 के अंतर्गत दंडनीय अपराध है एवं उपरोक्त नियमों का अनुपालन नहीं होने पर आपके विरुद्ध अभियोग याचिका दायर किया जा सकता है एवं खनिज संरक्षण एवं विकास नियमावली 2017 के नियम 11(2) एवं 45(7) के अंतर्गत खान की समस्त खनन संक्रियाएं बंद की जा सकती है ।

03. It is also brought to your notice that non-compliance Rule 45(7) of MCDR, 2017 (as amended) attracts the following provisions under which:

(i) The mining operation may be suspended.

(ii) Action may be initiated for prosecution under this rule.

(iii) Termination of the mineral concession may be recommended.

04. अतः आपको यह सलाह दी जाती है कि आप उपरोक्त नियमों का उल्लंघन का अतिशीघ्र सुधार करें एवं इस पत्र के जारी होने के 45 दिन के अंदर इस कार्यालय को सूचित करें।

भवदीय,

प्रसान्त कुमार साहू  
सहायक खान नियंत्रक  
भारतीय खान ब्यूरो

प्रतिलिपि: सूचनार्थ:- (ईमेल द्वारा)

1. खान नियंत्रक (मध्य), भारतीय खान ब्यूरो, नागपुर-440001 ।
2. संचालक, भौमिकी एवं खनिकर्म, इंद्रावती भवन, द्वितीय तल, डी ब्लॉक, अटल नगर, छत्तीसगढ़ । ईमेल- [dgm.cg@nic.in](mailto:dgm.cg@nic.in)

हस्ता/-  
सहायक खान नियंत्रक  
भारतीय खान ब्यूरो

I/37015/2024

**N.O.O**

प्रतिलिपि: सूचनार्थ एवं आवश्यक कार्यवाही हेतु:- (ईमेल द्वारा)

1. Director (Statistics) & In-charge MMS Division, Indian Bureau of Mines, Nagpur: to refer back the Annual Return for the year 2023-24 for rectification as pointed out above under rule 45(7) of MCDR, 2017.

हस्ता/-  
सहायक खान नियंत्रक  
भारतीय खान ब्यूरो