

I/14620/2023



**GOVERNMENT OF INDIA**  
**MINISTRY OF MINES**  
**INDIAN BUREAU OF MINES**  
**OFFICE OF THE REGIONAL CONTROLLER OF MINES**



Jabalpur, Dated: 04/08/2023

To,  
**Smt. Ratna Singh**  
W/o Shri Sudhir Singh Tomar  
Krishna Nagar, Satna-485001  
[Email: rajstonecrusher15@gmail.com](mailto:rajstonecrusher15@gmail.com)

Sub.: Violation of provisions of Mineral Conservation and Development Rules, 2017, in respect to **Aber Limestone Mine (17.408 ha), Mine Code – 38MPR35284 Distt-Satna (M.P)..**

Madam,

The following provision of Mineral Conservation and Development Rules 2017 were found violated in your above mentioned mine during the inspection by the undersigned on 08/07/2023 in presence of your representative Shri. Sudheer Singh Tomar.

<b>Rule No</b>	<b>Nature of violation observed in detail</b>
<b>Rule 11(1)</b>	<p><i>No holder of a mining lease shall commence or carry out mining operations in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines or prepared and certified in accordance with the system established by the State Government pursuant to the proviso to clause (b) of sub-section (2) of section 5.</i></p> <ol style="list-style-type: none"> <li>1. Only 289220 Tonnes of Limestone was produced against the proposed production of 392400 Tonnes during 2022-2023 which distorting the proposal by 26%.</li> <li>2. Bench width of about 3 meters is observed; against to maintain more than 6 meters (Bench height), thus benches are not systematically developed as proposed.</li> <li>3. For the proposal year the Waste dumping proposed in between E 500656 to E 500756 whereas the actual dumping found deviation in the approved location.</li> </ol>
<b>Rule 31(4)</b>	<p><i>The plans and sections required under these rules shall be maintained up to date within three months in case of category 'A' mines as referred to in clause (a) of sub-rule (2) of rule 55, and within twelve months in the case of any other mine</i></p> <p>The updated plans and sections are not available during the inspection.</p>
<b>Rule 45(7)</b>	<p><i>If it is found that the holder of a mining lease or the person or company engaged in trading or storage or end-use or export of minerals, as the case may be, has submitted incomplete or wrong or false information in monthly or annual returns or fails to submit a return within the date specified; then, –</i></p> <p>(a) in the case of mining of minerals by the holder of a mining lease, the Regional Controller of Mines or the authorized officer of the State Government may -</p>

I/14620/2023

	<p><i>i. Order suspension of all mining operations and dispatches in the mine and to revoke the order of suspension only after ensuring proper compliance;</i></p> <p><i>ii. take action to initiate prosecution under these rules;</i></p> <p><b>Refer PART V</b></p> <p><b>S.No 5. Trees planted- survival rate</b></p> <p>It is reported that 3000 no of trees planted during the reporting year where as plantation found during the inspection is very low compared to the reported.</p> <p><b>Refer: PART VI</b></p> <p><b>S.No 5. Sales- Despatches effected for Domestic Purpose and for exports</b></p> <p>The sale value details Furnished against Shri.Satish Kumar Pandey Shri Prabhakar Narayan Pandey ( ST id – 3133) are incorrect.</p>
<p><b>Rule 34A(2)</b></p>	<p><i>Every lessee, other than those covered under sub-rule (1), shall submit soft copy of high resolution Georeferenced Ortho-rectified Multispectral satellite images of the leased area and upto hundred metres outside the lease boundary taken in the month of April to June of every year, to the Controller General on or before 1st day of July of the that year in the standards formats such as GeoTIFF along with metadata or any other format as may be specified by the Indian Bureau of Mines in this regard.</i></p> <p>The Submitted satellite data is not as per the SOP issued by the IBM refer the annexure for necessary corrections required.</p>

2. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of Mineral Conservations and Development Rules, 2017.
3. Non compliance of rule 11(1) of MCDR, 2017 may lead to suspension of mining operation under the provision of rule 11(2) of MCDR-2017.
4. You are advised to rectify the above violations immediately and intimate the position to this office within a period of 45 days from the date of issue of this letter.

Yours faithfully

(Kathroju Naveen)  
Sr. Asst. Controller of Mines,  
Jabalpur Region, IBM

Copy to:

1. The Controller of Mines (CZ), Nagpur, IBM
2. The Director of Geology & Mining, Government of Madhya Pradesh, Khanij Bhavan, Arera Hills, Bhopal (MP). (All Lease Boundary Pillars not found established to deleniate the lease area on the field).
3. The District Collector, Satna.

( Kathroju Naveen)  
Sr.Asst. Controller of Mines,  
Jabalpur Region,  
IBM