



भारत सरकार /Government of India
खान मंत्रालय/Ministry of Mines
भारतीय खान ब्यूरो /Indian Bureau of Mines
Office Of Regional Controller of Mines



Violation Letter
Speed Post/Email

दूरभाष: (080) 39505368 / 29720499

Email ID: ro. bangalore@ibm.gov.in

29, इंडस्ट्रियल सबर्ब, II स्टेज, तुमकुर रोड,

गोरगुंटापाल्या येशवंतपुर,

बेंगलुरु -560022

No: MCDR-MiFLOFE/13/2022-BNG-IBM_RO_BNG Mine-code: 30KAR03139 Dated: 17/12/2024

To,

Dr. Meda Venkataiah,

Nominated Owner & Director

Iyli Gurunathappa iron ore Mine

M/s. Ramgad Minerals & Mining Limited

Baldota Enclave, Abheraj Baldota Road

Hospet, Vijayanagara District-583 203

Karnataka

Email Id- meda.venkataiah@mspllimited.com, debesh.das@mspllimited.com

lohith.kumar@rmml.in

विषय/Subject: **Violation of provisions of MCDR 2017 read with MCDR(Amendment),2021 in respect of your Iyli Gurunathappa Iron ore mine, ML 2593 over an extent of 20.23 ha, in Ramgad Village, Sandur Taluk , Ballari District of Karnataka State.**

Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 read with Mineral Conservation and Development (Amendment) Rules, 2021 were found violated in your above mine during inspection on 27.11.2024 by the undersigned in presence of Shri Debesh Gobinda Das, Mines Manager & Mining Engineer, Shri Lohith Kumar D R, Geologist and other mine officials:

Rules	Nature of Violations observed
11 (1)	<p>The Modifications to the Approved Mining was approved by IBM vide letter no. 279/624/99/BNG dated 31/07/2023 for the period 2023-24. The deviations observed in mining operation vis-à-vis approved document are given below.</p> <ol style="list-style-type: none"> It is observed from drone data and during inspection that benches at section D-D' from 901 to 892 mRL with 9m maximum height and 10 m minimum width is not maintained as per the proposal and actual bench height (899 to 884 mRL, N-1676224, E-655123) is more. It is observed from drone data and during inspection that the vertical extent (mRL) at South eastern portion of pit, at Section E-E' (N-1676175, E-655261) have been developed till 875 mRL for the year 2023-24 which is beyond the proposed maximum vertical limit of 883 mRL.

	iii. It is observed from drone data and during inspection that the 10 m lifts/stages is not maintained systematically at Sec HB-HB' (N-1676431, E-654979) of Backfill dump (BF-1) from 914 to 894 mRL as per the proposal.
--	--

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017.

03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.

04. You are advised to rectify the above violations immediately and intimate the position to this office **within 45 (Forty-Five) days** from the date of issue of this letter.

भवदीय/Yours faithfully,

(Sandeep Kumar Singh)

Senior Assistant Controller of Mines

Indian Bureau of Mines

Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560001.

(Sandeep Kumar Singh)

Senior Assistant Controller of Mines

Indian Bureau of Mines