MCDR REPORT

1.0 GENERAL

SN	Particulars	Details
1 (a)	Name of the Mine	VARADA BAUXITE MINES/SURVEY
		NO140/P
10)	Name of Inspecting Officer &	MOHAMMAD NIMAR/DEPUTY
1(b)	Designation	CONTROLLER OF MINES
	Accompanying Mines	MAULIK N PATEL
1(c)	Representatives	MICERCITIE
1d)	Type of Inspection	STAR RATING
1e)	Date of Inspection	10/12/2024
2	Total Lease Area (Ha) with	1.2242 Ha
	breakup of Non-forest and forest	1.2242 110
	land	
3	Minecode	07GUJ07124
4	IBM Registration Number under	IBM/10188/2012
	rule 45 of MCDR, 1988	
5	Name of the lessee, Address,	M/S;GUJARAT CALCINE
	phone, email and fax number	BAUXITE&REFRACTORIES
6	Village	MEVASA
7	Taluka/Mandal	KALYANPUR
8	District	DEV BHOOMI DWARKA
9	Pincode	361315
10	State	GUJARAT
11	Post office	BHATIA
12	Nearest police station	BHATIA
13	Nearest Railway station	BHATIA
14	Date of Grant of Mining Lease	16/08/1996
15	Date of Execution	26/11/1996
16	Date of opening of Mine	1/1/1997
17	Date of first Renewal, if	25/11/2016 TO25/11/2036 20YEARS
	applicable and its period & expiry	
18	Date of second Renewal, if	
	applicable and its period & expiry	
19	Date of submission of renewal	Lease valid up to 25/11/2046
	application if Mining Operations	
	are continuing under deemed	
20	extension	LANDON O MORRONA
20	Name of the Nominated Owner	JAYESH G KOTECHA
	with Address, phone, email, fax	AT-PO/JAM RAVAL TA;KALYANPUR DI;DEV BHOOMI DWARKA /DATE OF
	number and date of appointment	APPOINMENT;1/04/2010
71	Name of the Mine Agent - ith	
21	Name of the Mine Agent with	JAYESH G KOTECHA
	Address, phone, email, fax	AT-PO/JAM RAVAL TA;KALYANPUR DI;DEV BHOOMI DWARKA /DATE OF
	number and date of appointment	APPOINMENT;1/04/2010
22	Name of the Mines Manager with	MAULIK N PATEL
~ ~	Address, phone, email, fax	BE MINING
	number and date of appointment	

	in mines	
23	Name of the Mining Engineer, Qualification and total experience with Address, phone, email, fax number and date of appointment in mine	MAULIK N PATEL BE MINING with Experience of 7 years
24	Whether Geologist and Mining Engineer appointed in mines satisfy the rule 42 & carrying out their duties as per rule 43 & 44.	YES, Alipriya Bhakta
25	Date of Approval of Mining Plan/ Modified Mining Plan with five- year period and specific condition in approval letter, if any.	22/03/2021
26	Date of Approval of Scheme of Mining/Modified Scheme of Mining with five-year period and specific condition in approval letter, if any.	684(4)(1)MP-329/2020-21 Dated 22/03/2021
27	Mineral(s) granted in lease and proved for mining	BAUXITE
28	Method of Mining(Opencast, Underground)	Opencast
29	Category (Fully Mechanised, Others or Manual)	MECHANISED
30	Captive/Non Captive	CAPTIVE

Scientific Mining: Compliance of proposals of approved mining plan/scheme of mining. – **Exploration**

SN	Item	Proposals (2023-24)	Actual work	Remarks
1a	Backlog of previous year	Nil	Nil	
1b	Exploration over lease area for	Ni	1.2242	
	Geological axis 1 or 2.		Ha(Total	
			Lease is	
			explored in	
			G1 Level	
1c	Exploration Agency &	Nil	Nil	
	Expenditure in lakh Rupees			
	during the year			
1d	Balance area to be explored to	Nil	Nil	
	bring Geological axis in 1 or 2			
1e	Balance reserves as on	38,829 Ton	65038 Ton	
	01.04.2024			
1f	General remarks of inspecting	Total lease area	is explored in G1	level. However
	officer on geology, exploration	there is proposal of digging 1 pit of 4m x 4m upto		
	etc.	lithomargic clay, which was not done. Violation		
		under Rule 11(1) is being issued.	

2.0 Development

SN	Item	Proposals (2023-24)	Actual work	Remarks
			(2023-24)	

2a	Location of development w.r.t. lease area	Pit 1, South	Nil	
2b	Separate benches in topsoil,	Not proposed in	Nil	-
	overburden and mineral	topsoil, overburden		
	(Rule 15)	Mineral – 3.0 m		
2c	Stripping ratio or ore to OB	Nil	Nil	
	ratio			
2d	Quantity of topsoil	Not proposed	Not applicable	-
	generation in m3			
2e	Quantity of overburden	Not proposed	Not applicable	
	generation in m3			
2f	General remarks of	During inspection found	d that no Developm	ent work
	inspecting officer on	carried out in the mine due to Environmental		
	development of pit w.r.t.	Clearance issue		
	type of deposit etc.			

3.0 Exploitation

SN	Item	Proposals (2023-	Actual work (2023-24)	Re
		24)		mai
				ks
За	Number of pits proposed for production	Pit 1, South	Nil, pit dimension 150 x 50 x 2.5 m	-
3b	Quantity of ROM mineral production proposed	10120 MT	Nil	-
3c	Recovery of salable/usable mineral from ROM production	10120 MT	Nil	
3d	Quantity of mineral reject generation	Not proposed	Not applicable	
3e	Grade of mineral reject generation and threshold value declared	Not proposed	Not applicable	
3f	Quantity of sub-grade mineral generation	Not proposed	Not applicable	
3g	Grade of sub-grade mineral generation	Not proposed	Not applicable	
3h	Manual / Mechanised method adopted for segregating from ROM	Manual	Nil	-
3i	Any analysis or beneficiation study proposed & carried out for sub-grade mineral and reject	Not proposed	Not applicable	
3j	Provision of drilling & blasting in mineral benches	Not proposed	Not applicable	
3k	Provision of mining machineries in mineral benches	Excavator, Dumper	Nil	
31	Whether height of benches in overburden and mineral suitable for method of	Not proposed in topsoil, overburden Mineral – 2.5 m	Mineral – 2.5 m	

	mining proposed in MP/SOM			
3m	Total area covered under excavation/pits	0.829 Ha	0.712 Ha	
3n	Ore to OB ratio for the pit/ mine during the year	Not proposed	Not applicable	
30	Total area put in use under different heads at the end of year	0.9470 На	0.912 Ha	
3р	Production of ROM mineral during last five-year period, as applicable	24483	Nil	
3q	General remarks of	No production has b	een made due to Environme	ntal
	inspecting officer on	Clearance issue. Dispatch of 667.510 T has been		
	method of mining etc.	made during the yea	r.	

4.0 Solid Waste Management-Dumping

4.0 3	4.0 Solid Waste Management-Dumping					
SN	Item	Proposals (2022-23)	Actual work	Remarks		
4a	Separate dumping of topsoil, OB & mineral	Not proposed	Not Applicable	-		
41-	reject (Rule 32, 33)	Nickaran	NI-4 A1:11-			
4b	Location of topsoil, OB & mineral reject dumps	Not proposed	Not Applicable	-		
4c	Number of dumps within lease area and outside lease area	Not proposed	Not Applicable	-		
4d	Location of dumps w.r.t. ultimate pit limit (Rule 16)	Not proposed	Not Applicable	-		
4e	Number of active & alive dumps	Not proposed	Not Applicable	-		
4f	Number of dead dumps	Not proposed	Not Applicable	-		
4g	Number of dumps stabilished	Not proposed	Not Applicable			
4h	Whether Retaining wall or garland drain all along dumps are there	Not proposed	Not Applicable			
4i	Length of Retaining wall or garland drain all along dump	Not proposed	Not Applicable			
4j	Number of settling ponds	Not proposed	Not Applicable			
4k	Specific comments of inspecting officer	No work done towards D proposal was there.	Dumping of solid wa	iste as no		

5.0 Solid Waste Management-Backfilling

				
SN	Item	Proposals (2023-24)	Actual work	Remarks
5a	Status on part or full	Not proposed	Not Applicable	
	extraction of mineral from			
	mined out area before			

	starting backfilling			
5b	Area under backfilling of	Not proposed	Not Applicable	
	mined out area			
5c	Concurrent use of topsoil	Not proposed	Not Applicable	
	for restoration or			
	rehabilitation of mined out			
	area (Rule 32)			
5d	Total area fully reclaimed &	Not proposed	Not Applicable	
	rehabilitated			
5e	General remarks of	No work done towards	Backfilling of solid v	vaste as no
	inspecting officer on	proposal was there		
	backfilling, reclamation etc			

6.0 Progressive Mine Closure Plan

	<u>Progressive Mine Closure Pl</u>			
SN	Item	Proposals (2023-24)	Actual work (2023-24)	Remarks
6a	Whether Annual report on PMCP submitted on time and correctly - Rule 23E(2).	Yes	Submitted along with AR 2023-24 on 26-06-2024	
6b	Management of worked/mined out benches i) Area available for rehabilitation (ha) ,Water Reservoir ii) Afforestation done (ha) iii) No. of saplings planted during the year iv) Cumulative no. of plants v) Any other specific method of rehabilitation vi) Cost incurred on watch & care during the year	(1) 1840M^2 (2) 0.0050HA (3) 10 (4) 40 (5) NO (6) 1000RS	(1) Nil (2) Nil (3) 10 (4) 40 (5) NO (6) 1000RS	
6c	Compliance on reclamation and rehabilitation by backfilling i) Voids available for backfilling (L X B X D) ii) Void filled by waste/tailings iii) Afforestation on the backfilled area iv) Rehabilitation making water reservoir v) Any other specific means	1840M^2	Nil	

6d	Compliance of Rehabilitation of waste land within lease i) Afforestation ii) Area rehabilitated (ha) iii) Methof of rehabilitation	Not proposed	Not Applicable	
6e	Compliance of Environmental monitoring (core zone & buffer zone)	Yes	Yes, Through outside agency	
6f	General remarks of inspecting officer on PMCP compliance & progressive	PMCP work done as prop	posed.	

7.0 Mineral Conservation

SN	Item	Proposals (2023-24)	Actual work	Remarks
7a	ROM Mineral dispatch or grade-wise sorting within lease area	10120 MT	Nil	
7b	Method of grade-wise mineral sorting i.e. manual or mechanical	Manual	Manual	
7c	Different grade of mineral sorted out at mines	Not proposed	Not Applicable	
7d	Any beneficiation process at mines	Not proposed	Not Applicable	
7e	General remarks of inspecting officer on Mineral conservation & beneficiation issues	No production has been made due to Environmental Clearance issue. Dispatch of 667.510 T has been made during the year. No mineral conservation issue found.		

8.0 Environment

SN	Item	Proposals (2023-24)	Actual work (2023-24)	Remarks
8a	Separate removal and utilization of topsoil (Rule 32)	Not proposed	Not Applicable	
8b	Concurrent use or storage of topsoil	Not proposed	Not Applicable	
8c	Separate dumps for overburden, waste rock, rejects and fines (Rule 33)	Not proposed	Not Applicable	-
8d	Use of overburden, waste	Not proposed	Not Applicable	-

	rock, rejects and fines dumps for restoring the land to its original use			
8e	Phased restoration, reclamation and rehabilitation of lands affected by mining operations (Pits, dumps etc)	Not proposed	Not Applicable	-
8f	Baseline information on existence of plantation & additional plantation done (Rule 41)	10 saplings on 50m2 during the year	10 saplings on 50m2 during the year. Total 40	
8g	Survival rate	60%	60%	
8h	Water sprinkling on roads to control airborne dust	Through water tanker	No work done	
8i	General remarks of inspecting officer on aesthetic beauty in and around mines are	No production has been made due to Environmental Clearance issue. Dispatch of 667.510 T has been made during the year. No Environmental issue found.		

9.0 Compliance of Rule 45

9.0 C	ompliance of Rule 45			
S. N.	Item	COMMENTS		Remarks
	Status of submission of Online Monthly and Annual returns	Monthly and Annual Returns submitted within stipulate time.		ipulate time.
S. N.	Item			Remarks
9b	Scrutiny of Annual return for information on Mining Engineer, Geologist and Manager	Yes	ME- Maulik N Patel Geo - Alipriya Bhakta	
9c	Scrutiny of Annual return on land use pattern for area under pits, reclaimed area, dumps etc.	Covered under current (O-C) Workings 0.712, Occupied by plant, buildings, residential, welfare buildings and roads 0.200, Work done under progressive mine closure plan during the year 0.200		
9d	Scrutiny of Annual return on afforestation	10	10	
9e	Scrutiny of Annual return on mineral reject generation (Grade & quantity)	Nil	Nil	
9f	Scrutiny of Annual return on ROM stock and/or graded ore	ROM- 36185.235 Cement 34623.440 Abrasive 562.123 Refractory - 332.162	ROM- 36185.235 Cement 34623.440 Abrasive 562.123 Refractory - 332.162	

9g	Scrutiny of Annual return on sale value, Ex. Mine price & production cost	Ex Mine Price Refractory - 891.67/-	Ex Mine Price Refractory - 891.67/-
9i	Scrutiny of Annual return on fixed assets	Nil	Nil
9k	Scrutiny of Annual return on mining machineries	Nil	Nil

- 10- Details of violations observed during current inspection and compliance position of earlier violation pointed out:-
- a) वर्ष 2023-24 में खान 2022-23 के तारक मूल्यांकन हेतु निलंबित की गई थी ।
- b) वार्षिक विवरणी के साथ surface geological plans and sections जमा नहीं किए गए है।
- c) इस वर्ष वार्षिक विवरणी 2023-24 मे निम्नलिखित त्रुटियाँ पाई गयी
 - 1. लीज़ क्षेत्र 1.2241 ha है परंतु वार्षिक विवरणों मे 1 ha ही दर्शाया गया है।
 - 2. surface geological plans and sections जमा नहीं किए गए है।

नियम 33 एवं 45(5)(सी) हेतु कारण बताओ नोटिस जारी किया जा रहा है।

- d) खान दिनांक 31-12-. से अस्थायी रूप से बंद है जिसकी नोटिस निर्धारित प्रारूप मे जमा की गई है
- e) ड्रोन डाटा की जांच करने पर यह पाया गया की SOP के अनुसार नहीं है अतः DDMS पोर्टल पर रिटर्न कर दिया गया है।
- f) खान की मैपिंग रजिस्ट्रेशन नंबर मे नहीं हो पाने के कारण खान का तारक मूल्यांकन ऑनलाइन मोड मे जमा नहीं किया जा सका है इसीलिए ऑफलाइन मे कार्यालय मे जमा करा दिया गया है । उक्त संबंध मे कार्यालय मे मेल भी किया गया है