



भारत सरकार **GOVERNMENT OF INDIA**
खान मंत्रालय **MINISTRY OF MINES**
भारतीय खान ब्यूरो **INDIAN BUREAU OF MINES**
क्षेत्रीय खान नियंत्रक के कार्यालय **OFFICE OF THE**
REGIONAL CONTROLLER OF MINES

**BY EMAIL/ SPEED POST**

Phone: 0674-2352463

Tele Fax: 0674-2352490

E-mail:

ro.bhubaneswar@ibm.gov.inPlot No.149, Pokhariput
BHUBANESWAR-751020**To**

The Kashvi International Pvt.Ltd.
1234/ P Govindaprasad Bomikhal Bhubaneswar
E-Mail: groupkashvi@gmail.com

Date: 06.12.2024

Sub: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Jaribahal Iron Ore Mines (30ORI08120) over an area of 107.440 Ha situated in Keonjhar district of Odisha State--Reg

Sir,

The following provisions of MCDR 2017 were found violated in your above mine during inspection carried out on 7th November 2024 by the undersigned in presence of the mine officials.

Rule	Nature of Violation observed
11(1)	<p>Mining operations are not being undertaken in accordance with the Mining Plan/ Modification of Mining Plan.</p> <p>The following deviation was observed during inspection</p> <p>1. In FY 2023-24, the development has not achieved as per the Proposal in area 2424949N/335909E to 2424954N/335982E and 2425032N/336167E to 2425038N/336215E.</p> <p>2. Height and width of the benches are not maintained in Block A and Block B as per the approved Mining Plan.</p>
37(2)	<p>1. Management of western lower part of Overburden Wastes Dump No.2 has not been proper due to non-development of terraces to reduce the dump height and not suitable protective measures to prevent the escape of material therefrom & dump stabilization.</p> <p>2. Management of western part of BF-1(Dump No.4) has not been proper due to non-development of terraces to reduce the dump height and not suitable protective measures to prevent the escape of material therefrom & dump stabilization.</p>

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of Mineral Conservation and Development Rules, 2017.

03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.

04. You are advised to rectify the violation immediately and intimate the position to this office within a period of 45 (Forty five) days from the date of issue of this letter.

Yours Faithfully,

(सुजीत कुमार जेना)

कनिष्ठ खानन भूबैग्यानिक

भारतीय खान ब्यूरो, भुवनेश्वर

Copy forwarded for kind information to:

- (1) The Controller of Mines (EZ), Indian Bureau of Mines, CP-13, Sector V Salt Lake City, Kolkata 700 091.
- (2) The Director of Mines, Directorate of Mines, Government of Odisha, Heads of Department Building, Bhubaneswar-751 001

Yours Faithfully,

(सुजीत कुमार जेना)
कनिष्ठ खानन भुवैयानिक
भारतीय खान ब्यरो, भुवनेश्वर