

VOILATION LETTER
Registered AD/Speed post/Email



भारत सरकार / Government of India
खान मंत्रालय / Ministry of Mines
भारतीय खान ब्यूरो / Indian Bureau of Mines
क्षेत्रीय खान नियंत्रक का कार्यालय / Office of the Regional Controller of Mines
भवन सं. 61, भारतीय सर्वेक्षण परिसर, सर्वे चौक, देहरादून (उत्तराखण्ड) 248001/
Building no. 61 survey of India campus, Dehradun (U.K.) 248001
Tel- 0135-2676350 / 2671896, E-mail – ro.dehradun@ibm.gov.in

File No.: MCDR-MiFLOLST/7/2022-DDN-IBM_RO_DDN Mine Code: 38HPR10044

Date: 31.12.2024

सेवा में / To,

M/s Jakra Mines & Minerals
Village: Kamrau, Tehsil: Paonta Sahib
District: Sirmour (173029), Himachal Pradesh
Email: jalamsingh@rediffmail.com

विषय / Subject: The violation of provisions of the Mineral Conservation and Development Rules, 2017, in relation to the Barwas Limestone Mine covering an area of 8.91 hectares in Sirmour District, Himachal Pradesh.

महोदय / Sir,

The undersigned conducted an inspection of your mine on **28.11.2024**, in the presence of your mine representative, **Shri Rohit Thakur**. During the inspection, the following provisions of the **Mineral Conservation and Development Rules, 2017 (MCDR 2017)** were found violated in your mine. The following discrepancies have been observed during the inspection:

Rule No	Nature of violation observed in detail
---------	--

Rule 11(1) Mining operations under mining lease: No holder of a mining lease shall commence or carry out mining operations in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines or prepared and certified in accordance with the system established by the State Government.

However following discrepancies have been observed w.r. to the Review and Updation of mining plan with PMCP vide letter No. 614(2)/MS-B-193/11-DDN, dated 13.09.2021 to the following extent.

- i. *It was proposed to maintain benches in mineral with a height of 6 meters and a width of 8 meters but the same was not maintained.*
- ii. *During the inspection, it was observed that the retaining walls (80m), wire fencing (50m) and the check dams were not found in place as per the approved Review of Mining Plan.*

Rule 42 Restoration of flora: Every holder of prospecting license, prospecting license cum mining lease or a mining lease shall carry out prospecting or mining operations, as the case may be, in accordance with applicable laws and in such a manner so as to cause least damage to the flora of the area held under prospecting license, prospecting license cum mining lease or mining lease and the nearby areas.

Against the proposal for plantation of 50 saplings for year 2024-24; no fresh plantation has been seen in the field.

Rule 45 Monthly and Annual returns (7): If it is found that the holder of a mining lease or the person or company engaged in trading or storage or end-use or export of minerals, as the case may be, has submitted incomplete or wrong or false information in daily or monthly or annual returns or fails to submit a return within the date specified.

- i. *It has been observed that you have submitted incomplete information by not providing the registration number of purchasers of mineral in the Annual returns.*
- ii. *You mentioned the part time geologist in annual return therefore you are requested to submit the details and notice of appointment of geologist as per Rule 55 of MCDR (2017).*

-
2. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of Mineral Conservations and Development Rules, 2017.
 3. The mining operations can be suspended under the rule 11(2) & 45(7)(a) of MCDR-2017, if compliance of rule 11(1) & 45(7)(a) of MCDR-2017 is not found satisfactory.
 4. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty-Five) days from the date of issue of this letter.

Yours faithfully,

नितिन /Nitin
कनिष्ठ खनन भू-विज्ञानी/Junior Mining Geologist
भारतीय खान ब्यूरो/Indian Bureau of Mines

प्रतिलिपि सूचनार्थ प्रेषित :-

- 1) खान नियंत्रक (उत्तर), भारतीय खान ब्यूरो, उदयपुर। (zo.udaipur@ibm.gov.in)
- 2) निदेशक उद्योग निदेशालय, हि. प्र. सरकार, उद्योग भवन, शिमला (हि. प्र.). (geologicalwing@gmail.com)
- 3) गार्ड फाइल

नितिन /Nitin
कनिष्ठ खनन भू-विज्ञानी/Junior Mining Geologist
भारतीय खान ब्यूरो/Indian Bureau of Mines