

Violation Notice Letter

BY REGD. PARCEL

By e-mail

भारत सरकार / GOVERNMENT OF INDIA

खान मंत्रालय / MINISTRY OF MINES

भारतीय खान ब्यूरो / INDIAN BUREAU OF MINES

**क्षेत्रीय खान नियंत्रक कार्यालय / OFFICE OF THE REGIONAL CONTROLLER OF
MINES, VIJAYAWADA**

File No.: AP/VNZR/MN-A2/Hyd.

Date : 21/02/2025

To: Shri/M/s. Mr
MANVENDRA MOR,
Nominated Owner, R B S S D
& F N DAS,
SHREERAMNAGAR
,SHREERAMNAGAR,
GARIVIDI, Avagudem
Village & Mandal,
VIZIANAGARAM district,
Andhra Pradesh,- 535101

Subject : Violation of provisions of MCDR, 2017 in respect of your Avagudem Manganese Mine over an extent of 13.868 ha. situated in Avagudem Village, Garividi Mandals, Vizianagaram District of Andhra Pradesh State

The following provisions of Mineral Conservation and Development Rules, 2017 (MCDR, 2017) were found violated in the above mine during analysis of the submitted drone data for the F.Y. 2022-23 & 2023-24 and accordingly the field inspection was carried out by the undersigned on 18/02/2025 in presence of the mine official Shri A. Vishwanath Naidu, HoD (Mines).

Summary of Violations :

Items for Reporting	As Per Plan	Actual	Deviati on	Rule	Reason
Development - Opencast: Location of development w.r.t. lease area	In between UTM c o-ordinates N230960 to N231067 and E768176 to E768304	In between UTM c o-ordinates N2030986 and E768173 to E768466	Excess develop ment has been pointed out.	Rule 11(1),	Contravention of Rule 11(1) of MCDR, 2017 has been pointed out.
Exploitation - Opencast Mine: Whether height of benches in Overburden & mineral suitable for method of mining proposed in mining plan	Height: OB/Waste: 3.0 m Mineral/Ore: 4.0 m Width: OB/Waste: Minimum 10.0 m Mineral/Ore: Minimum 10.0 meters	Height: OB/Waste: 3.0 m to 10.0 m Mineral/Ore: 3.0 m Width: OB/Waste: 2.0 m to 20 meters Mineral/Ore: 1.0 m to 3.0 meters	Bench height and width are not maintained. Deviation has ben pointed out.	Rule 11(1),	Contravention of Rule 11(1) of MCDR, 2017 has been pointed out.
OB / Waste Dumps details: Separate dumping of topsoil, OB & mineral rejects, fines, tailings (Rule 36,37)	Proposal has been given in the approved document for separate dumpin	Dumpin g has been done in between UTM c o-ordinates (i) N2030875 to N	Deviati on has been pointed out.	Rule 11(1),	Contravention of Rule 11(1) of MCDR, 2017 has been pointed out.

	g of OB /Waste in between UTM coordinates N2030945 to N2031114 and E768025 to E768166	2030986 and E768063 to E768177 (ii) N2030963 to N2031158 and E768024 to E768094 (iii) N2031075 to N2031211 and E767990 to E768140 (iv) N2031083 to N2031170 and E768106 to E768270 without any approved proposals.			
OB / Waste Dumps details: Location of Topsoil, OB/Waste, Mineral Reject dumps, Tailings and Fines	In between UTM coordinates OB /Waste: N2030945 to N2031114 and E768025 to E768	In between UTM coordinates OB /Waste: (i) N2030875 to N2030986 and E768063 to	Deviation has been pointed out.	Rule 11(1),	Contravention of Rule 11(1) of MCDR, 2017 has been pointed out.

	166	E76817 7 (ii) N 203096 3 to N2 031158 and E76 8024 to E76809 4 (iii) N 203107 5 to N2 031211 and E76 7990 to E76814 0 (iv) N 203108 3 to N2 031170 and E76 8106 to E76827 0 Miner al/Ore: N20308 54 to N 203088 4 and E 768181 to E768 248 without any app roved p roposals .			
OB / Waste Dumps details: Number of active & Inative dumps	OB/Wa ste: 01 no.	OB/Wa ste: 04 nos. Mi neral/O re: 01 no.	Deviati on has been pointed out.	Rule 11(1),	Contravention of Rule 11(1) of MCDR, 2017 has been pointed out.

<p>Annual Return: Status of Approval of FMPCP u/r 24, 25 of MCDR,2017</p>	<p>As per the exec uted mining lease deed, the mining lease will be expired on 06/1 2/2025.</p>	<p>In accor dance with the Rule 24(1) of MCDR, 2017, the lessee has to submit the Final Mine Closure Plan prior 2 years of the expiry of the mining lease. FMCP has not been su bmitted .</p>	<p>Deviati on has been pointed out</p>	<p>Rule 24(1),</p>	<p>Contravention of Rule 24(1) of MCDR, 2017 has been pointed out.</p>
<p>Annual Return: Notices and Returns for the lease area submitted or not where fine applicable</p>	<p>Appoint ment notice of the Manage r (Mines) is not su bmitted .</p>	<p>Appoint ment notice has not been su bmitted .</p>	<p>Deviati on has been pointed out.</p>	<p>Rule 46,</p>	<p>Contravention of Rule 46 of MCDR, 2017 has been pointed out.</p>

02. In this connection, it is brought to your notice that the violation of aforesaid rule constitutes an offence, punishable under Rule 62(1) of MCDR, 2017 as well as Fine may be imposed as specified under Schedule-III of rule 62(2) of MCDR, 2017 Amended up to 21st January 2024. 03. The mining operations and dispatches can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory. 04. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

Yours faithfully,

(Shaival Kartikeya, VIJAYAWADA)
Senior Mining Geologist

Esigned by: Shaival
Date: 24/02/2025 01:46:50 PM