

**Violation Notice Letter**

**BY REGD. PARCEL**

**By e-mail**

**भारत सरकार / GOVERNMENT OF INDIA  
खान मंत्रालय / MINISTRY OF MINES  
भारतीय खान ब्यूरो / INDIAN BUREAU OF MINES  
क्षेत्रीय खान नियंत्रक कार्यालय / OFFICE OF THE REGIONAL CONTROLLER OF MINES,  
GOA**

**File**

**Date : 09/04/2025**

**No.:** MCDR-MiFL0FE/1/2023-GOA-IBM\_RO\_GOA

To: Shri/M/s. Mr SANDEEP  
SHYAMKUMAR  
SHRIVASTAVA, Nominated  
Owner, MINERALS &  
METALS, 34, AUSHUTOSH  
, NAPEAN SEA ROAD ,,  
MUMBAI, Talawane Village  
& Mandal, SINDHUDURG  
district, Maharashtra,- 400036

**Subject :** Violation of provision of Mineral Conservation and Development Rules, 2017 in respect of your TALAVANE(30MSH28028) over an extent of 74.45 ha in Talawane in SINDHUDURG, Maharashtra

महोदय/Sir, The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mine during the inspection on 19.03.2025 by the undersigned in the presence of Sakharam Kavatankar - Agent, Cletus D'souza - Mine Manager and Victor Fernandes - Geologist, :

**Summary of Violations :**

Items for Reporting	As Per Plan	Actual	Deviati on	Rule	Reason
Development - Opencast: Location of development w.r.t. lease area	Pit : PIT 1 & Directio n : E-W	No working in Pit 1, mine being worked in PIT 2 at the time of inspecti on	Deviati on found	Rule 11(1),	At the time of inspection, deviation in location of development w.r.t. approved plan document was observed
Development - Opencast: Quantity of overburden generation in m3	41931.00	0	41931.00	Rule 11(1),	Development work was not done for the year FY 2023-24.
Progressive Mine Closure Plan: Compliance of Rehabilitation of waste land within lease i) Afforestation ii) Area rehabilitated (ha) iii) Method of rehabilitation	Retaini ng wall - 2530m Garland Drain - 2460m Fencing - 652m	Retaini ng wall - 200m Garland Drain - 150m	Deviati on found	Rule 11(1),	Planned Rehabilitation activities not completed as per approved document
Annual Return: Notices and Returns for the lease area submitted or not where fine applicable	.	Intimati on of re opening of Mine not sub mitted	Deviati on Found	Rule 29,	As per records mine was reopened in November 2024, but intimation of reopening of mine was not submitted to this office within prescribed timeline as per Rule 29
Bench Parameters	Maxim um height	Bench p aramete rs are	Deviati on found	Rule 11(1),	During the inspection it was observed that bench in Pit 2 (on south side) and in Pit 1

	of 6m and min imum 9m width	not mai ntained properl y			(Near BP-8) were found unsystematic and not maintained properly as per approved document
--	---	------------------------------------	--	--	---

02. It is brought to your notice that violation of the above Rules constitutes an offence punishable under Rule 62 of MCDR (Amendment) 2021, notified dated 03.11.2021. 03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory. 04. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty-Five) days from the date of issue of this letter.

Yours faithfully,

(ABHIMANYU OGRA, GOA)  
SR. ACOM

 Signed by: ABHIMANYU Date: 09/04/2025 06:31:40 PM
--