

**Violation Notice Letter**

**BY REGD. PARCEL**

**By e-mail**

**भारत सरकार / GOVERNMENT OF INDIA  
खान मंत्रालय / MINISTRY OF MINES  
भारतीय खान ब्यूरो / INDIAN BUREAU OF MINES  
क्षेत्रीय खान नियंत्रक कार्यालय / OFFICE OF THE REGIONAL CONTROLLER OF MINES,  
GOA**

**File No.:** MCDR-MiFL0FE/2/2024-GOA-  
IBM\_RO\_GOA

**Date :** 21/04/2025

To: Shri/M/s. Mr Sandeep  
Shyamkumar Shrivastava,  
Nominated Owner, The  
Deccan Minerals Pvt. Ltd.,  
16th Floor, Central Wing,  
NIRMAL ,Nariman point,  
MUMBAI, Sateli Tarf Satarda  
Village & Mandal,  
SINDHUDURG district,  
Maharashtra,- 400021

**Subject :** Violation of provision of Mineral Conservation and Development Riles, 2017  
in respect of your Sateli Iron Ore Mine (30MSH28024) over an extent of 40.37 ha in  
Sateli Tarf Satarda in SINDHUDURG, Maharashtra

महोदय/Sir, The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mine during the inspection on 29.03.2025 by the undersigned in the presence of Shri Nitin Patil- Agent, Shri Bhagwant Alias Tushar Falari- Mining Engineer and Shri Harshvardhan Patil-Geologist :

**Summary of Violations :**

Items for Reporting	As Per Plan	Actual	Deviati on	Rule	Reason
Development - Opencast: Location of development w.r.t. lease area	Workin g in FY 24-25, planned along section 9-9, 8-8, A-A and B-B	At the time of inspecti on, working was obs erved along section 15-15 a nd 14-14	Deviati on found	Rule 11(1),	At the time of inspection, deviation in location of development for current year i.e. FY24-25 w.r.t. approved plan document was observed
Bench Parameters	Bench of maxi mum height of 6m and min imum 8m width to be main tained	Bench p aramete rs are not mai ntained properl y	Deviati on found	Rule 11(1),	During the inspection it was observed that bench near BP3 were found unsystematic and not maintained properly as per approved document
Mineral Stack	Mineral to be stacked at desig nated place	Fines were found stacked at undes igned place	Deviati on found	Rule 11(1),	During the inspection, fines were found stacked at undesigned place and within the 7.5m safety barrier limit between BP 17 and BP 18

02. It is brought to your notice that violation of the above Rules constitutes an offence punishable under Rule 62 (1) of MCDR (Amendment) 2021, notified dated 03.11.2021. 03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory. 04. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty-Five) days from the date of issue of this letter.

Yours faithfully,

(ABHIMANYU OGRA, GOA)  
SR. ACOM

Esigned by: ABHIMANYU  
Date: 21/04/2025 11:58:01 AM