



भारत सरकार / Government of India
 खान मंत्रालय / Ministry of Mines
 भारतीय खान ब्यूरो / Indian Bureau of Mines
 क्षेत्रीय खान नियंत्रक का कार्यालय / Office of the Regional Controller of Mines
 भवन सं. 61, भारतीय सर्वेक्षण परिसर, सर्वे चौक, देहरादून (उत्तराखण्ड) 248001/
 Building no. 61 survey of India campus, Dehradun (U.K.) 248001
 Tel- 0135-2676350 / 2671896, E-mail – ro.dehradun@ibm.gov.in

VIOLATION LETTER
E-MAIL / REGD A.D.



File No.: MCDR-MiFLOLST/10/2023-DDN-IBM_RO_DDN Mine Code: 38HPR10037

Date: 31.12.2024

To,
 M/s Rajendra Singh
 Village: Ranfau, Post: Andheri
 Tehsil: Sangrah
 District: Sirmour Himachal Pradesh
 Email: shersinghpaonta@gmail.com

The undersigned conducted an inspection of your mine on **27.11.2024**, in the presence of your mine representative, **Shri Ravi**. During the inspection, the following provisions of the **Mineral Conservation and Development Rules, 2017 (MCDR 2017)** were found violated in your mine. The following discrepancies have been observed during the inspection:

Rule No	Nature of violation observed in detail
---------	--

Rule 11(1) Mining operations under mining lease: No holder of a mining lease shall commence or carry out mining operations in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines or prepared and certified in accordance with the system established by the State Government.

However following discrepancies have been observed w.r. to the Review and Updation of mining plan with PMCP vide letter No. 614(2)/MS-B-216/12-DDN, dated 26/07/2022 to the following extent.

- i. It was proposed to maintain benches in mineral with a height of 5 meters and a width of 7 meters but the same was not maintained.*
- ii. During the inspection, it was observed that retaining/parapet walls and fencing were not found in place as proposed in the approved Review of Mining Plan.*
- iii. During the inspection, it was observed that garland drains were not found along both dump D1 and D2.*

Rule 42 Restoration of flora: Every holder of prospecting license, prospecting license cum mining lease or a mining lease shall carry out prospecting or mining operations, as the case may be, in accordance with applicable laws and in such a manner so as to cause least damage to the flora of the area held under prospecting license, prospecting license cum mining lease or mining lease and the nearby areas.

It has been observed that, against the proposal of 180 saplings, only 100 saplings have been planted.

Rule 55 Employment of geologists and mining engineers: Every holder of a mining lease shall employ, in case of

- i. Category 'A' mines, a whole-time mining engineer and a geologist;*
- ii. Category 'B' mines, a part-time mining engineer and a part-time geologist;*

You are requested to submit the details of Geologist posted in the Mine as per Rule 55 of MCDR and submit the notice of appointment of Geologist.

2. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of Mineral Conservations and Development Rules, 2017.
3. The mining operations can be suspended under the rule 11(2) of MCDR-2017, if compliance of rule 11(1) of MCDR-2017 is not found satisfactory.
4. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty-Five) days from the date of issue of this letter.

Yours faithfully,

नितिन /Nitin
कनिष्ठ खनन भू-विज्ञानी/Junior Mining Geologist
भारतीय खान ब्यूरो/Indian Bureau of Mines

प्रतिलिपि सूचनार्थ प्रेषित :-

- 1- खान नियंत्रक (उत्तर), भारतीय खान ब्यूरो, उदयपुर। (zo.udaipur@ibm.gov.in)
- 2- निदेशक उद्योग निदेशालय, हि. प्र. सरकार, उद्योग भवन, शिमला (हि. प्र.). (geologicalwing@gmail.com)
- 3- गार्ड फाइल

नितिन /Nitin
कनिष्ठ खनन भू-विज्ञानी/Junior Mining Geologist
भारतीय खान ब्यूरो/Indian Bureau of Mines