

I/37901/2024

भारत सरकार
खान मंत्रालय
भारतीय खान ब्यूरो
क्षेत्रीय खान नियंत्रक कार्यालय
कर्मयोगी भवन, चतुर्थ माला, ब्लॉक-2, सी विंग,
सेक्टर-10A, गांधीनगर, गुजरात, 382010



Tel- 079 29750358 /29750359; ई-मेल/ E-mail: ro.gandhinagar@ibm.gov.in

पत्रावली संख्या: गुज/जूना/चू.प- 305 Mine code 38GUJ08351 ID

दिनांक:

सेवा में : अंबुजा सीमेंट लि
अंबुजानगर, तालुका - कोडीनार,
जिला - गिर सोमनाथ, गुजरात - 362 715
e mail – maheshkumar.jain@adani.com

विषय: गुजरात राज्य के गिर सोमनाथ जिले की सूत्रापाडा तालुका में स्थित आपकी सिंगसर चूनापत्थर खान, क्षेत्रफल- 728.1156 हे. में खनिज संरक्षण एवं विकास नियमावली, 2017 के नियमों का उल्लंघन।

महोदय,

आपकी उपरोक्त खान का स्टार रेटिंग/एम.सी.डी.आर निरीक्षण अधोहस्ताक्षरी द्वारा दिनांक 15-07-2024 को महेंद्र सिंह (खान प्रबन्धक), श्री विकास तिवारी (भूविज्ञानी) हितेश जाधव(खनन अभियंता) एवं अन्य की उपस्थिति में किया गया तथा उक्त निरीक्षण के समय खनिज संरक्षण एवं विकास नियमावली, 2017 के निम्नलिखित नियमों का उल्लंघन पाया गया-

नियम सं./Rule No	उल्लंघन के प्रकार का विस्तृत ब्यौरा/ Detailed description of the type of violation									
11(1)	The following work is not being done as per the Approved Review of Mining plan No 684(4)(1)/MP-311/2020-21 dated 29-01-2021:- At point no 8.3.5 in PMCP proposal, there was proposal of plantation of 3000 saplings, However it was observed that only 770 saplings have been planted which is less than that of proposed quantity.									
34(A)	In the Digital Aerial Images submitted under Rule 34(A), it is observed that the processed Drone survey output data submitted to Indian Bureau of Mines is not as per the SOP issued in this regard. The deviations in the drone data submitted is as follows:-									
	<table border="1"> <thead> <tr> <th>Sl. No</th> <th>Data type</th> <th>Check Point parameters as per SOP</th> <th>Submitted in proper format (Yes/No)</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>Excavated Area, Subgrade dump, Backfilled, reclaimed and rehabilitated area</td> <td>.shp (UTM in WGS 84)</td> <td>No</td> <td>The geometry given in shape file is line instead of polygon.</td> </tr> </tbody> </table>	Sl. No	Data type	Check Point parameters as per SOP	Submitted in proper format (Yes/No)	Remarks	1	Excavated Area, Subgrade dump, Backfilled, reclaimed and rehabilitated area	.shp (UTM in WGS 84)	No
Sl. No	Data type	Check Point parameters as per SOP	Submitted in proper format (Yes/No)	Remarks						
1	Excavated Area, Subgrade dump, Backfilled, reclaimed and rehabilitated area	.shp (UTM in WGS 84)	No	The geometry given in shape file is line instead of polygon.						
45(5) (c) read with 45(7)	The following deficiencies have been found in the scrutiny of the annual return submitted by you for the year 2023-24 – 1. In PART-II (Employment and Wages) at point 2 given details regarding									

I/37901/2024

	<p>days particulars are not summing up to 366 days total days in financial year 2023-24.</p> <p>2. In PART-VII: COST OF PRODUCTION, components for calculation of cost/T is not matching with the details given in other parts like 3. Employment and salary-wages paid, PART-II A (Capital Structure) and PART-III (Consumption of Materials).</p>
--	---

1. In this connection, it is brought to your kind notice that :-
 - a) the above violations constitute an offence punishable under Rule 62 of MCDR 2017 and/or;
 - b) Mining operations can be suspended as per rule 11(2) of MCDR 2017 in case of non-compliance of above rules as these violations also affects provisions of Rule11(1) of MCDR 2017 and/or;
 - c) You are advised to rectify the above violation of above Rules immediately and intimate the compliance position to this office, within a period of 45 days for violated rules from date of issue of this letter.
2. In case of violation of Rule 34(A), you are advised to rectify the above violations immediately and upload data online on DDMS portal **within 45 (Forty Five) days** from the date of issue of this letter
3. In case of violation of Rule 45,
 - a) You are also liable to pay such amount as prescribed under MCDR 2017 for delay of each day as per **Schedule-II**, read with Rule **45(7A)** in case of non-compliance of various provisions of Rule 45.
 - b) As per provision of Rule **45(7) and/or45(7A)(ii)** the Regional Controller of Mines may take appropriate action including order of suspension of **all mining operations and dispatches** on non-compliance of various provisions of Rule 45.
4. In context to the violations of Rule 45, this letter has been considered as show cause notice where you are advised to rectify above violation immediately. You are therefore directed to show cause within a period of **30 days** for violations of Rule 45 from the date of issue of this letter as to why the action under Rules **45(7) and/or 45(7A)** shall not be taken against you. No further notice will be given to you in this regard.
5. This letter is being issued with the approval of Regional Controller of Mines.

भवदीय

Signed by Mohammad Nimar

Date: 19-08-2024 11:19:52

Reason: Approved (मोहम्मद निमर)

उप खान नियंत्रक
भारतीय खान ब्यूरो

प्रतिलिपि सूचनार्थ हेतु प्रेषित/ Copy for favor and information:-

1. Controller of Mines(NZ), Udaipur
2. Commissioner of Geology and Mining, Gandhinagar
3. DDG, MMS Division, Nagpur
4. Guard File

उप खान नियंत्रक
भारतीय खान ब्यूरो