

I/38029/2024

भारत सरकार
खानमंत्रालय
भारतीय खान ब्यूरो
क्षेत्रीय खाननियंत्रायक का कार्यालय
माखूपुरा औद्योगिक क्षेत्र, अजमेर
ई-मेल: ro.ajmer@ibm.gov.in



Government of India
Ministry of Mines
Indian Bureau of Mines
Office of the Regional Controller of
Mines. Makhupura Industrial Area,
Ajmer- 305002
Ph-145-2695165/2695476 Fax-
2695202

संख्या: 4620/MCDR-MiFLOPbZn/7/2023-AJM-IBM_RO_AJM

दिनांक: /01/2024

खान एजेंट,

जावरमाला सीसा-जस्ता खान,
मेसर्स हिंदुस्तान जिंक लिमिटेड,
तहसिल: गिरवा, जिला: उदयपुर
राजस्थान: 313901
(e-mail: radha.raman@vedanta.co.in, Shashi.Shukla@vedanta.co.in)

विषय: राजस्थान राज्य के उदयपुर जिले में स्थित आपकी जावरमाला सीसा-जस्ता खान में खनिज संरक्षण एवं विकास नियमावली, 2017 के उल्लंघन के संदर्भ में।

महोदय,

The following provision of Mineral Conservation and Development Rules, 2017 (hereinafter referred as MCDR, 2017) were found violated in your above said mine during inspection on 11/07/2024 by undersign in presence of Sri Nandlal Swami, Mine Manager and Sri Shashi Bhushan Shukla, Geologist of your mine.

Rule	Status and extent of violation
11(1)	<p>Mining operations have not been carried out in accordance to Modification of Review of Mining Plan approved on 15/07/2021 to the extent given below for the year 2023-24:</p> <p>(1) A total of 80 exploratory bore holes with 18000 meters of drilling was approved to drill during the year 2023-34. However, against the mentioned target 97 exploratory bore holes with 13443.00 meters of drilling has been achieved. Resulting shortfall in drilling meters.</p> <p>(2) An area of 0.20 Hectare of G3 level was approved to explore during the year 2023-24. However, as reported during the mine inspection an area of 0.10 Hectare of G3 level has been explored.</p> <p>(3) A total of 4300 meters of lateral and vertical development was approved at different levels. However, against the mention target development of 1921.02 meters have been achieved.</p> <p>(4) As per approved document mill tailing was approved to store in extension of existing old rehabilitated tailing dam and Baroi tailing dam. However, it is observed during the inspection that mill tailing has been stored over non-approved area i.e. on the rehabilitated old tailing dam.</p> <p>(5) Tailing quantity of 410400 tons was proposed to backfill in stope out area. However, against the mention target only 233820 tons of tailing was backfilled in the stope out area.</p>
31(4)	<p>As per rule plans and sections are required to maintain up to date showing respective proposal of approved mining plan for various activities. During inspection it is observed that the details of various proposals and the plantation carried out in the lease area is not updated on the maintained surface plan.</p>

02. इस संदर्भ में आपका ध्यान आकर्षित किया जाता है कि उपरोक्त नियम का उल्लंघन खनिज संरक्षण एवं विकास नियमावली, 2017 के नियम 62 के अंतर्गत दंडनीय अपराध है एवं उपरोक्त नियम के उल्लंघन की अनुपालन नहीं होने पर खनिज संरक्षण एवं विकास नियमावली, 2017 के अंतर्गत:

(क) आपकी खान कि सारी संक्रियाए बंद की जा सकती है।

(ख) आपके विरुद्ध अभियोग दायर किया जा सकता है।

(ग) राज्य सरकार को खनन पट्टे कि समाप्ति की सिफारिश जा सकती है।

03. अतः आपको सलाह दी जाती है कि आप परोक्त नियम के उल्लंघन का अतिशीघ्र सुधार करें एवं सुधार की स्थिति कि सूचना इस पत्र के जारी होने कि दिनांक से 45 (पैंतालीस) दिनों के भीतर इस कार्यालय को सूचित करे।

भवदीय

(दिलीप जैन)

वारिष्ठ खनन वैज्ञानिक

भारतीय खान ब्यूरो, अजमेर

प्रतिलिपि सूचनार्थ प्रेषित:

1. खान नियंत्रक (उत्तर) भारतीय खान ब्यूरो, उदयपुर। (email द्वारा)
2. निदेशक, खान एवं भूविज्ञान विभाग, राजस्थान सरकार, उदयपुर।
3. खनि अभियंता, खान एवं भूविज्ञान विभाग, राजस्थान सरकार, उदयपुर।
4. रक्षित पत्रवली।

वारिष्ठ खनन वैज्ञानिक

भारतीय खान ब्यूरो, अजमेर