

Violation Notice Letter

BY REGD. PARCEL

By e-mail

**भारत सरकार / GOVERNMENT OF INDIA
खान मंत्रालय / MINISTRY OF MINES
भारतीय खान ब्यूरो / INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक कार्यालय / OFFICE OF THE REGIONAL CONTROLLER OF MINES,
AJMER**

File

Date : 04/06/2025

No.: MCDR-MiFL0LST/5/2022-AJM-IBM_RO_AJM
MCDR-MiFL0LST/5/2022-AJM-IBM_RO_AJM

To: Shri/M/s. Mr Jayakumar
Krishnaswamy, Nominated
Owner, M/s NU Vista
Limited, Equinox Business
Park, Tower -3, East wing, 4th
Floor, ,LBS Road, Kurla
(West), Mumbai, Deh Village
& Mandal, NAGAUR district,
Rajasthan,- 400070

Subject : Violation of provision of Mineral Conservation and Development Riles, 2017
in respect of your NAGAURLIMESTONE MINE 032016 BLOCK
3B1A(38RAJ20013) over an extent of 267.6288 ha in Deh , NAGAUR, Rajasthan

Sir, The following provisions of the Mineral Conservation and Development Rules, 2017
were found violated in your above mine during the virtual inspection carried out by the
undersigned on 12/02/2025.

Summary of Violations :

Items for Reporting	As Per Plan	Actual	Deviati on	Rule	Reason
Development - Opencast: Location of development w.r.t. lease area	Pit : Quarry -1 & Direction : South-North	Develo pment in Quarry -1 has not been done as proposa l.	Deviati on obse rved in the drone data sub mitted by the Lessee.	Rule 11(1),	Development has not been carried out as per approved mine plan.
OB / Waste Dumps details: Location of Topsoil, OB/Waste, Mineral Reject dumps, Tailings and Fines	Stack lid.: Reject Dump- 1 Type of Stack: Stack for mineral reject	OB/Min eral rej ect/Min eral storage is found stacked at the norther n side of the pit which is not as per pro posed location .		Rule 11(1),	Dumping has not been carried out as per approved mine plan.
Environment: Plantation & Survival rate	Plantati on : 1951, Survial Rate : 75	No satis factory plantati on has been found in the drone image s ubmitte d by	0.000	Rule 11(1),	No satisfactory plantation has been found in the drone image submitted by lessee.

		lessee.			
Annual Return: Whether incomplete or false or wrong returns submitted (Rule 45(7))	To be s ubmitte d as per MCDR, 2017	In Part VI, point no. 2, the ROM p roducti on and closing stock have been reporte d as 119 269.1 tonnes and 479 92.520 tonnes, respecti vely. In point no. 3(ii), the grad e-wise p roducti on has been reporte d as 712 76.580 tonnes a ccordin g to the recover y. If the total amount of ROM has	0.000	Rule 45(7),	In Part VI, point no. 2, the ROM production and closing stock have been reported as 119269.1 tonnes and 47992.520 tonnes, respectively. In point no. 3(ii), the grade-wise production has been reported as 71276.580 tonnes according to the recovery. If the total amount of ROM has been sorted, then the closing stock of ROM at the mine head should be zero. Justify the same.

		been sorted, then the closing stock of ROM at the mine head should be zero. Justify the same.			
Garland drain and retaining wall	Garland drain: 247m Retaining wall: 242m	Garland drain: NIL Retaining wall: NIL		Rule 11(1),	Garland drain and retaining wall have not been established.

In this context, your attention is drawn that violation of the above rules is a punishable offense under Rule 62 of Mineral Conservation and Development Rules, 2017 and non-compliance of the above rules is punishable under Mineral Conservation and Development Rules, 2017: i) All operations at your mine may be suspended. ii) Prosecution may be initiated against you. iii) Termination of mining lease may be recommended.

Esigned by:  Kamal
Date: 04/06/2025 04:15:19 PM

Yours faithfully,

(Kamal Kumar Singh, AJMER)
JMG