



**भारत सरकार GOVERNMENT OF  
INDIA**  
**खान मंत्रालय MINISTRY OF MINES**  
**भारतीय खान ब्यूरो INDIAN BUREAU OF MINES**  
**क्षेत्रीय खान नियंत्रक कार्यालय**  
**OFFICE OF THE REGIONAL CONTROLLER  
OF MINES**



Date: 11.08.2025

To,  
Shri Vishal Atha, Nominated Owner  
M/s Narbheram Power & Steel Pvt. Limited.  
Shiromani Flat No 8 60 1 Ballygunge  
Circular Road, Kolkata - 700019  
Email: npspl@athagroup.in

Subject: Violation of provisions of MCDR, 2017, in respect of your Roida-II Iron Ore Mine (30ORI08124) over an area of 74.702 Ha (74.867 Ha as per DGPS) in Tanto village, Barbil Tahsil of Keonjhar District of Odisha State - reg.

महोदय,

The following provision of MCDR 2017 were found violated in your above mine during the inspection carried out on 28<sup>th</sup> July 2025 by the undersigned in presence of the mine officials S/Shri Sadanand Rana (Mines Agent), Prasanta Kumar Mohanty (Mines Manager) and Atanu Bandopadhyay (Geologist).

Rule	Nature of Violation / उल्लंघन के प्रकार का ब्योरा
11(1)	Mining operations in the mining lease are not being carried out in accordance with as per the proposal given in Modification of Mining Plan vide letter No. MPM/A/04-ORI/BHU/2021-22 dated 31.05.2021 to the extent given below:  (1) During FY 2024-25 there was a proposal of Dump 2 for dumping OB. However, during inspection no such dumps were found to be existing.  (2) During inspection it was observed that ROM was stacked all over Pit-2 and Pit-6 thus preventing systematic development of the Pits.  (3) During FY 2024-25 it was proposed to carry out mining operations by forming benches of 6m height and 8-14m width. However, during inspection was observed that mining operations were carried out by forming benches with height and width more than that proposed specifically in Pit-2.
31(4)	During inspection it was observed that the upto date plans and sections were not found to be maintained.

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of Mineral Conservation and Development Rules, 2017.

03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.

04. You are advised to rectify the violation immediately and intimate the position to this office within a period of 45 (Forty five) days from the date of issue of this letter.

भवदीय

( विक्रम देशपांडे )  
सहायक खान नियंत्रक  
भारतीय खान ब्यूरो

प्रतिलिपि -सुचनार्थ एवम आवश्यक कारवाई हेतु सादर प्रेषित।

1. खान नियंत्रक (पूर्वञ्चाल ), भारतीय खान ब्यूरो, कोलकता Email- zo.kol@ibm.gov.in
2. निदेशक खान, उड़ीसा सरकार, विभागीय प्रमुख भवन, यूनिट- v भूबनेश्वर 751001  
Email [directorofmines@orissaminerals.gov.in](mailto:directorofmines@orissaminerals.gov.in)

( विक्रम देशपांडे )  
सहायक खान नियंत्रक  
भारतीय खान ब्यूरो