

**INDIAN BUREAU OF MINES
MINERALS DEVELOPEMMENT AND REGULATION DIVISION**

MCDR inspection REPORT

Hyderabad regional office

Mine file No : AP/NLG/LST-12/HYD

Mine code : 38APR14006

- (i) Name of the Inspecting : RK13) A.V.Ramesh Kumar
Officer and ID No.
- (ii) Designation : Assistant Mining Geologis
- (iii) Accompanying mine : Mine was not in operation since 2014.
Official with
Designation
- (iv) Date of Inspection : 04-JUN-25
- (v) Prev.inspection date : 09-JUL-14

PART-I : GENERAL INFORMATION

1. (a) Mine Name : RAMAPURAM
- (b) Registration NO. :
- (c) Category : A Mechanised
- (d) Type of Working : Opencast
- (e) Postal address
State : TELANGANA
District : NALGONDA
Village : RAMAPURAM
Taluka : MELLACHERUVU
Post office : RAMAPURAM
Pin Code : 508246
FAX No. : 040-23300091
E-mail : works@bheemacements.co.in
Phone : 040-23311413
- (f) Police Station : RAMAPURAM
- (g) First opening date : 16-APR-86
- (h) Weekly day of rest : SAT
2. Address for : M/S BHEEMA CEMENTS LIMITED
correspondance : RAMAPURAM, MELLACHERUVU (M)
SURYAPET DISTRICT-508248
3. (a) Lease Number : APR0064
- (b) Lease area : ~~000~~ 40.47 HA
- (c) Period of lease : 50 YEARS
- (d) Date of Expiry : ~~09-07-2043~~
09-07-2043
4. Mineral worked : LIMESTONE Main

5. Name and Address of the

Lessee : COROMANDEL CEMENTS LTD
P.B.NO.8, JAGGAIHPET
NALGONDA TELANGANA
Phone:08654-22347,22954
FAX :08683-54731

Owner : S.CHANDRA MOHAN
COROMANDAL CEMENTS LTD., 6-
3-652/C/A, FLAT: 5,
KAUTILYA, SOMAJIGUDA,
HYDERABAD.-82 HYDERABAD
TELANGANA
Phone: 040-23300091
FAX : 040-23311413

Agent : C.K.RAO
RAMAPURAM(P.O) NALGONDA
DISTRICT. NALGONDA
TELANGANA
Phone:
FAX :

6. Date of approval of Mining Plan/Scheme of Mining	:	Modif.of approved Mining Plan	28-OCT-99
		Renewal under rule 22 MCR1960	27-NOV-02
		Modif.of approved Mining Plan	05-DEC-03
		Mining Scheme rule 12 MCDR1988	09-MAY-07
		Mining Scheme rule 12 MCDR1988	31-MAY-07
		Modif.approved Mining Scheme	10-NOV-09
		Mining Scheme rule 12 MCDR1988	03-OCT-12
		Mining Scheme rule 12 MCDR1988	11-NOV-16

PART - II : OBSERVATION/COMMENTS OF INSPECTING OFFICERS

Exploration :

Sl.No.	Item	Proposals	Actual work	Remarks
1a	Backlog of previous year	As the mine was issued an order of suspension of mining operations in the year 2014 for not having any valid document, there were no proposals for exploration/mining etc.	No exploration was carried out in the year 2024-25.	The mine was issued order of suspension on 28.11.2024. Since then the mine is not in operation. Further, the lessee company was recommended to NCLAT in the year 2018 and in 2020 NCLAT issued an order for implementation of its resolution plan. The lessee vide their letter dated 19.10.2024 has informed that they are approaching DMG, Telangana with a request for implementation of the resolution plan and still some legal issues are pending at Hon'ble NCLAT.
1b	Exploration over lease area for geological axis 1 or 2	No proposal	No exploration carried out in the year 2024-25	A total of 6 boreholes have been drilled in the lease area covering approximately an extent of 18 ha under G-1 level. Rest 22 ha is under G-4 and yet to be explored.
1c	Exploration Agencies and Expenditure in lakh rupees during the year	None	None	None

1d	Balance area to be explored to bring Geological axis in 1 or 2	None	None	Approximately 22 ha to be explored under G-1 level.
1e	Balance reserve as on 01/04/20	---	---	The reserves as on 1-4-2025 are 39.91 Million tonnes.
1f	General remarks of inspecting officers on geology, exploration etc	---	---	The area falls under Narji Limestone with dark and light grey limestone.

Development :

Sl.No.	Item	Propasals	Actual work	Remarks
2a	Location of development w.r.t.lease area	As the mine is under suspension since 2014, there is no proposal for exploration/mining.subsequently the lease was recommended for termination under rule 12(10) of MCR,2016 in the year 2019.	No mining operations were noticed on the day of inspection.An old waterlogged pit was noticed.as per the earlier report, a single pit of dimensions 450 mx 400mx23m was reported.	The State Government vide its G.O.Ms No.2 sdated 08.01.2019 has issued an order stating the revival of the mining lease under rule 20(6) of MCR,2016.In the said order it was mentioned that as the lessee company was facing financial problems, it was referred to NCLAT.further stated that the mining lease is revived subject to the conditions that full payment of mineral revenue dues and fulfilment of the conditions as per Govt.memo dated 13.06.2017 read along with letter 09.07.2018 issued by NCLAT.

2b	Separate benches in topsoil, overburden and minerals (Rule 15)	None	None	None
2c	Stripping ratio or ore to OB ratio	None	None	None
2d	Quantity of topsoil generation in m3	None	None	None
2e	Quantity of overburden generation in m3	None	None	None
2f	General remarks of inspecting officers on development of pit w.r.t. type of deposit etc	None	None	None

Exploitation:

Sl.No.	Item	Propasals	Actual work	Remarks
3a	Number of pit proposed for production	As there was no valid document, no proposal was made for exploitation.	None	None
3b	Quantity of ROM mineral production proposed	None	None	None
3c	Recovery of sailable/usable mineral from ROM production	None	None	None
3d	Quantity of mineral reject generation	None	None	None

3i	Any analysis or beneficiation study proposed and carried out for sub grade mineral and rejects.	None	None	None
3j	Provision of drilling and blasting in mineral benches	None	None	None
3l	Whether height of benches in overburden and mineral suitable for method of mining proposed in MP/SOM	None	None	On the day of inspection the pit was waterlogged.
3m	Total area covered under excavation/pits	None	None	None
3n	Ore to OB ratio for the pit/mine during the year.	None	None	None
3o	Total area put in use under different heads at the end of year	None	None	None
3p	Production of ROM mineral during the last five year period as applicable	None	None	None
3q	General remarks of inspecting officers on method of mining etc.	None	None	None

Solid Waste Management - Dumping:

Sl.No.	Item	Proposals	Actual work	Remarks
4a	Separate dumping of topsoil, OB and mineral rejects (Rule 32.33)	None	None	None

4b	Location of topsoil, OB and mineral reject dumps	None	None	None
4c	Number of dumps within lease area and outside of lease area	None	None	None
4e	Number of active and alive dumps.	None	None	None
4i	Length of Retaining wall or garland drain all along dumps	None	None	None
4j	Number of settling ponds	None	None	None
4k	Specific comments of inspecting officer on waste dump management	None	None	None

Solid Waste Management - Backfilling:

Sl.No.	Item	Propasals	Actual work	Remarks
5a	Status of part or full extraction of mineral from mined out area before starting backfilling.	None	None	None
5b	Area under backfilling of mined out area	None	None	None
5c	Concurrent use of topsoil for restoration or rehabilitation of mineral out area (Rule 32)	None	None	None
5d	Total area fully reclaimed and rehabilitated	None	None	None

5e	General remarks of inspecting officers on backfilling and reclamation etc.	None	None	None
----	--	------	------	------

Progressive Mine Clousre Plan:

Sl.No.	Item	Propasals	Actual work	Remarks
6a	Whether Annual report on PMCP submitted on time and correctly. Rule 23 E(2).	None	None	None
6b	Area available for rehabilitation (ha) .	None	None	None
6c	afforestation done (ha).	None	None	None
6d	No. of saplings planted during the year	None	None	None
6e	Cumulative no .of plants	None	None	None
6i	Compliance on reclamation and rehabilitation by backfilling (ii) Voids filled by waste / tailings	None	None	None
6m	Compliance of rehabilitation of waste land within lease (i)afforestation	None	None	None
6o	Compliance of rehabilitation of waste land within lease (iii)Method of rehabilitation	None	None	None

6q	General remarks of inspecting officers on PMCP compliance and progressive closure operations etc.	None	None	None
----	---	------	------	------

Mineral Conservation:

Sl.No.	Item	Propasals	Actual work	Remarks
7a	ROM Mineral dispatch or grade-wise sorting within lease area	None	None	None
7b	Method of grade-wise mineral sorting i.e. manual or mechanical.	None	None	None
7c	Different grade of mineral sorted out at mines.	None	None	None
7d	Any beneficiation process at mines	None	None	None
7e	General remarks of inspecting officer on Mineral conservation and beneficiation issues	None	None	None

Environment:

Sl.No.	Item	Propasals	Actual work	Remarks
8a	Separate removal and utilization of topsoil (Rule 32)	None	None	None

8c	Separate dumps for overburden, waste rock, rejects and fines (Rule 33)	None	None	None
8d	Use of overburden, waste rock, rejects and fines dumps for restoring the land to its original use	None	None	None
8e	Phased restoration, reclamation and rehabilitation of lands affected by mining operations (Pits, dumps etc)	None	None	None
8f	Baseline information on existence of plantation and additional plantation done (Rule 41)	None	None	The mining lease was having scanty bushy/thorny type of vegetation.
8g	Survival rate	None	None	None
8h	Water sprinkling on roads to control airborne dust	None	None	None
8i	General remarks of inspecting officer on aesthetic beauty in and around mines area	None	None	None

Compliance of Rule 45:

Sl.No.	Item	Proposals	Actual work	Remarks
--------	------	-----------	-------------	---------


9a	Status of submission of Monthly and Annual returns	None	None	The mine was issued an order of suspension in the year 2014 and was recommended for termination to State Government in the year 2019. The mine was inspected as per the instructions issued by CCOM(MDRD) vide letter no.I-11011(1)/1/2025 - CCOM-MDR dated 24.04.2025.
9b	Scrutiny of Annual return for information on Mining Engineer, Geologist and Manager	None	None	None
9c	Scrutiny of Annual return on land use pattern for area under pits, reclaimed area, dumps etc.	None	None	None
9d	Scrutiny of Annual return on afforestation	None	None	None
9f	Scrutiny of Annual return on ROM stock and/or graded ore	None	None	None
9g	Scrutiny of Annual return on sale value, Ex. Mine price and production cost	None	None	None
9h	Scrutiny of Annual return on fixed assets	None	None	None
9k	Scrutiny of Annual return on mining machineries	None	None	None

Details of violations observed during current inspection and compliance position of violation pointed out

Violation observed			Show cause position		
Rule NO.	Issued on	Compliance on	Rule NO.	Issued on	Compliance on

Date :

10-06-2025


(A.V. Ramesh Kumar)

Indian Bureau of Mines