

BY REGD POST/E-MAIL

भारत सरकार GOVERNMENT OF INDIA
 खान मंत्रालय MINISTRY OF MINES
 भारतीय खान ब्यूरो INDIAN BUREAU OF
 MINES
 क्षेत्रीय खान नियंत्रक के कार्यालय
 OFFICE OF THE REGIONAL CONTROLLER
 OF MINES



VIOLATION LETTER
 Phone: 0674-2352463
 Tele Fax: 0674-2352490
 E-mail:
 ro.bhubaneswar@ibm.go
 v.in
 Plot No.149, Pokhariput
 BHUBANESWAR-751020

File No.:MCDR-MiFLOFE/3/2023-BBS-IBM_RO_BBS

Dated-03/07/2025

To,
 Shri D.R. Patnaik, Owner,
 Deojhar Iron Mine
 M/s. Tarini Minerals Pvt. Limited,
 A/6 Commercial Estate, Civil Township,
 Rourkela E-mail: diom.tmpl@gmail.com.

Sub: Violation of provisions of MCDR, 2017 read with MCDR (Amendment), 2021 in respect of your Deojhar Iron Mine (Mine Code-30ORI08069) of M/s. Tarini Minerals Pvt. Limited over an area of 34.365 ha in Village-Deojhar, Taluka- Barbil, Keonjhar district of Odisha State.

Sir,

The following provisions of Mineral Conservation and Development Rules, 2017 read with MCDR (Amendment), 2021 were found violated in respect of the above said mine during inspection on 10.06.2025 by the undersigned, in presence of Sh. Rajesh Kumar, Mines Manager, and other mining officials.

Review of the Mining Plan was approved vide letter no. No. MCDR-MiFLOFE/3/2023-BBS-IBM_RO_BBS dated 22/03/2024 for the period 2024-25 to 2028-29. The mining operations are not being carried out in accordance with the approved mining plan. The deviations observed in mining operations vis-à-vis the approved document are given below.	
Rule No.	Observations
11(1)	<p>During the year 2024-25, it was proposed to backfill 0.72ha. in the northern part of the lease area, during the site inspection it is observed that no such back filling work has been carried out. Also it is observed that during the fiscal year 2024-25 complete over burden (34800m³) generated have been disposed in dumps instead of backfilling.</p> <p>(ii) As per the proposal for the year 2024-25 the lessee has to be constructed retaining wall of 266m and garland drain of 268m. However, it is observed during the inspection that retaining wall and garland drain has not yet been constructed.</p> <p>(iii) During the site inspection it is observed that development of benches at north western portion of the pit between section A-A' to E-E' have not been developed systematically with 10m benches as per the proposal.</p>

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR, 2017.

03. The violation of Rule 11(1) may also attract provisions of Rule 11(2) of MCDR, 2017 regarding suspension of mining operations till the compliance of violations.

04. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (forty five) days from the date of issuance of this letter.

Yours faithfully,
Digitally signed by
Rohita Sethi
Date: 03-07-2025
12:22:38
(Rohita Sethi)
Assistant Controller of Mines

Copy for kind information:-

1. The Controller of Mines (EZ), Indian Bureau of Mines, CP-13, Sector V, Salt Lake City, Kolkata- 700 091.
2. The Director of Mines, Directorate of Mines, Government of Odisha, Bhubaneswar, Odisha-751 001.