

**भारत सरकार / GOVERNMENT OF INDIA**  
**खान मंत्रालय / MINISTRY OF MINES**  
**भारतीय खान ब्यूरो / INDIAN BUREAU OF MINES**  
**क्षेत्रीय खान नियंत्रक कार्यालय / OFFICE OF THE REGIONAL CONTROLLER OF MINES,**  
**DEHRADUN**

File No.: MCDR-MiFL0LST/15/2023-DDN-IBM\_RO\_DDN

Date : 19/12/2025

To: Shri/M/s. Mr Riaz Ahmad Panjra,  
 Nominated Owner, Cemtac Cements Pvt.  
 Ltd., RCC PLAZA, NEAR PETROL PUMP  
 NOWGAM, BYE PASS, Srinagar ,Srinagar,  
 Srinagar, Khrewa Village & Mandal,  
 Pulwama district, Jammu And Kashmir,-  
 190014

**Subject:** Violation of provision of Mineral Conservation and Development Riles, 2017 in respect of your 38J&K14003(38J&K14003) over an extent of 29.4151 ha in Khrewa in DEHRADUN, Pulwama, Jammu And Kashmir

Sir, The above mine was inspected on 29.08.2025 by the undersigned in the presence of Shri Mehraj, Geologist and during the inspection, the following provisions of the Mineral Conservation and Development Rules, 2017 were found to be violated.

**Summary of Violations :**

Items for Reporting	As Per Plan	Actual	Deviation	Rule	Reason
Annual Return: Whether incomplete or false or wrong returns submitted (Rule 45(7))	Submitted	produced ROM has been subtracted from the the reserve and resources	yes	Rule 45(7),	
Exploitation - Opencast Mine: Quantity of ROM mineral production proposed (in T)	128750 T	17225 T	111525 T	Rule 11(1),	
Development - Opencast: Location of development w.r.t. lease area	Development work was proposed from 1934mRL to 1886 mRL in single pit only in North Eastern part	Development work was proposed to be carried out from 1934 mRL to 1886 mRL in a single pit located in the north-	yes	Rule 11(1),	Development work was proposed to be carried out from 1934 mRL to 1886 mRL in a single pit located in the north-eastern part of the Mining Lease (ML) area, as per the approved Mining Plan. However, during the reporting year, the production of ROM has not been fully achieved, which clearly indicates that the development work in the proposed pit within the lease area is lagging behind the approved schedule. The shortfall in ROM production suggests that the systematic

	of the ML	eastern part of the Mining Lease (ML) area, as per the approved Mining Plan. However, during the inspection, the development work was not found to be confined to the proposed single pit nor carried out within the specified north-eastern portion of the lease area.			development of the lease area, particularly in the north-eastern portion where the single pit was proposed, has not progressed as planned. Consequently, the development work in the lease area has not been carried out in accordance with the approved proposals.
Exploration: UNFC category wise reported Resources/Reserves as per MP/MMP ROMP    Total Reserves (111, 121 & 122) and Total Mineral Resources (331, 332 & 333 upto 334)				<div style="border: 1px solid black; padding: 2px; display: inline-block;">           Esigned by: NITIN            Date: 27/01/2026 12:37:23 PM         </div>	
Exploration: Number of DTH Boreholes	1 DTH of the 15 m depth has been proposed for the year 2024-25	no DTH has been done	yes	Rule 11(1),	During the inspection, it was observed that no DTH drilling was carried out during the reporting year.

1) In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of Mineral Conservations and Development Rules, 2017. 2) The mining operations can be suspended under the rule 11(2) of MCDR-2017, if compliance of rule 11(1) and 45(7) of MCDR-2017 is not found satisfactory. 3) You are advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty-Five) days from the date of issue of this letter.

Yours faithfully,

(NITIN SINGH, DEHRADUN)  
JMG