

Violation Notice Letter

By e-mail

भारत सरकार / GOVERNMENT OF INDIA
खान मंत्रालय / MINISTRY OF MINES
भारतीय खान ब्यूरो / INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक कार्यालय / OFFICE OF THE REGIONAL CONTROLLER OF MINES,
DEHRADUN

File No.: MCDR-MiFL0LST/20/2022-DDN-IBM_RO_DDN

Date : 10/02/2026

To: Shri/M/s. Mr Deepak Bhatnagar,
Nominated Owner, JANKI MINES &
MINERALS, Village : Kamroo ,Post : Trilor
Dhar, Ponta Sahib, Kamrou (24) Village &
Mandal, Sirmaur district, Himachal
Pradesh,- 173029

Subject: Violation of provision of Mineral Conservation and Development Rules, 2017 in respect of your
38HPR10079(38HPR10079) over an extent of 5.61 ha in Kamrou (24) in , Sirmaur, Himachal Pradesh

Sir, The above mine was inspected on 09.01.2026 by the undersigned in the presence of Shri Kedareshwar Mishra, Mine Manager and during the inspection, the following provisions of the Mineral Conservation and Development Rules, 2017 were found to be violated.

Summary of Violations :

Items for Reporting	As Per Plan	Actual	Deviation	Rule	Reason
Annual Return: Appointment of Mining Engineer & Geologist as per provisions of Rule 55 of MCDR,2017	Geologist : Arun Dhiman & Date of App ointment : 2022-01-31	Geologist or mining engineer was not present during the inspection.		Rule 55(1),	Geologist was not present during the inspection.
Progressive Mine Closure Plan: Compliance on reclamation and rehabilitation by backfilling/Other means Total area and numbers of plantation proposed.	No reclamation & rehabilitated proposed in the approved mining plan. Plantation : Location :Safety Zone BP08 to BP10, Area : 0.056 Ha, No. of Plant : 30 Plantation : Location :Safety Zone BP06 to BP08, Area : 0.056, No. of Plant : 30. Plant survival rate is 80%	Plantation proposal has been carried out broadly. But the survival rate of the plants are poor. Most of the plants have died.	Yes. Survival rate is around 30%	Rule 11(1),	Survival rate is around 30%
Exploitation - Dump Working: Quantity of mineral reject generation	2251.5 tonne	0 tonne as per annual return for the reporting year	2251.5. Please clarify why no mineral reject is being generated although it was anticipated to be generated.	Rule 11(1),	A clarification is required as why no mineral reject is being generated although it was anticipated to be generated.
Exploitation - Dump Working: Quantity of dump material handling Proposed (in Tonne)	225 tonnes proposed	0 tonnes generated as per annual returns	Yes. Please clarify why no waste is being generated although it was anticipated to be generated.	Rule 11(1),	A clarification is required as why no waste is being generated although it was anticipated to be generated.
Exploitation - Opencast Mine: Whether height of benches in Overburden& mineral suitable for	Opencast method of mining proposed	Opencast method of mining proposed		Rule 11(1),	Bench development not done as per Proposal.

method of mining proposed in mining plan	with bench height 5m and bench width 5m proposed.	but proper bench development not done. Proposal not followed for development.			
Exploitation - Opencast Mine: Quantity of mineral reject/Sub-grade generation	2089.50	0	2089.500 No mineral reject is being generated as per annual return.	Rule 11(1),	No mineral reject is being generated as per annual return.
Exploitation - Opencast Mine: Number of pits / Blocks proposed for production	Pit ID : Pit-3	Production not done from Pit-3. It is done from area close to Pit-2	Yes	Rule 11(1),	Production not done from proposed pit area.
Development - Opencast: Quantity of overburden generation in m3	90 m3 (225 tonne)	No overburden produced as per annual report of the reporting year.	No overburden produced as per annual return.	Rule 11(1),	No overburden produced as per annual return. A clarification is required.
Development - Opencast: Location of development w.r.t. lease area	Pit : 3 & Direction : North West	Development not done as per proposal. Development is done in the southern part of the lease area close to Pit-2.	Significant Deviation observed.	<div style="border: 1px solid black; padding: 2px; display: inline-block;"> Signed by: Matiul Date: 19/07/2018 03:30:16 PM </div> Rule 11(1),	Development not done as per proposal. Development is done in the southern part of the lease area close to Pit-2.

1) In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of Mineral Conservation and Development Rules, 2017. 2) The mining operations can be suspended under the rule 11(1) of MCDR-2017, if compliance of 11(1) and 55 of MCDR-2017 is not found satisfactory. 3) You are advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty-Five) days from the date of issue of this letter.

Yours faithfully,

(Matiul Islam, DEHRADUN)
Sr ACOM