



भारत सरकार Government of India
खान मंत्रालय Ministry of Mines
भारतीय खान ब्यूरो Indian Bureau of Mines
क्षेत्रीय खान नियंत्रक का कार्यालय Office of the Regional Controller of Mines
100, ओल्डनेहरू कालोनी, देहरादून (उत्तराखण्ड) 248001 / 100 Old Nehru Colony, Dehradun (U.K.) 248001
TEL- 0135-2676350 / 2671896, E-mail – ro.dehradun@ibm.gov.in



फाईल संख्या File No: UP/ALM/MAG-1-DDN

Mine Code: 39UPR04001

दिनांक 28 Jan 2021

सेवा में To : मेसर्स अल्मोड़ा मैग्नेसाइट लिमिटेड.

Email: almoramagnesite@gmail.com

गाँव-माटेला, पोस्ट- विलोरी

जिला- बागेश्वर,

उत्तराखण्ड-263630

विषय Sub: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Jhiroli Magnesite Mine, Mining Lease over an area of 165.08 ha located near Village-Jhiroli, District- Bageshwar of Uttarakhand State.

महोदय Sir,

The following provisions of the Mineral Conservation & Development Rules, 2017 were found violated in your above mine during the inspection made by the undersigned on 29-11-2020 in the presence of Shri Kunal Joshi, Geologist and Anil Kumar, Mine Manager.

RULE

NATURE OF VIOLATION OBSERVED

NO.

11(4)

The holder of a mining lease shall submit the mining plan to the competent authority for review at least on hundred and eighty days before the expiry of five years period for which it was approved on the last occasion, for mining operations for a period of five subsequent years. Review and Updation of Mining plan with PMCP was approved vide letter no. 614(2)/MP-B-135/2000-DDN dated 28-11-2016 but lessee has not submitted the next Review & Updation of Mining Plan with PMCP till date.

33

The holder of a mining lease shall, on or before the 30th day of June every year submit to the authorized officer a digital copy along with a print copy of the surface geological plans and sections maintained under Rule 32. However, the lessee has not submitted the copies of the plans and sections as per Rule 32 for the years 2019-20.

2. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017.
3. Mining operation can be suspended as per rule 11(2) in case of non-compliance of any sub-rule of 11 of MCDR 2017.
4. You are advised to rectify the above violations immediately and intimate the compliance position to this office within 45 days from the date of issue of this letter.

भवदीय Yours faithfully,

28.01.2021

(दामोदर प्रसाद शर्मा / D P Sharma)

सहायक खान नियंत्रक / Assistant Controller of Mines

भारतीय खान ब्यूरो / Indian Bureau of Mines

प्रतिलिपि सूचनार्थ प्रेषित :-

- 1- खान नियंत्रक (उत्तर), भारतीय खान ब्यूरो, उदयपुर। (zo.udaipur@ibm.gov.in)
- 2- निदेशक, भूतत्व एवं खनिकर्म इकाई, उद्योग निदेशालय, देहरादून, उत्तराखण्ड (adir-dgm-uk@nic.in)
- 3- गार्ड फाइल
- 4- Mine file

सहायक खान नियंत्रक / Assistant Controller of Mines