

Registered/Speed Post

Violation letter



**GOVERNMENT OF INDIA
MINISTRY OF MINES
INDIAN BUREAU OF MINES
OFFICE OF REGIONAL CONTROLLER OF MINES**



**FAX : 080- 23371027 /
23373287
Tel : 080-23371027 /
23375366 / 67
Email ID:
ro.bangalore@ibm.gov.in**

**29, Industrial Suburb, II Stage,
Tumkur Road, Gorguntapalya,
Yeshwantpur,
Bangalore- 560 022.**

rcombng@rediffmail.com
No.KNT/BLR/Fe/437/BNG

Date: 24.10.2017

To,

The Owner/Nominated owner/Agent,
Haddinpade Iron Ore Mine,
M/s B. Rudra Gouda
#2199, BKG Mansion,
KHB Colony,Sandur
Dist: Ballari,
Karnataka – 583119

Sub: Violation of provisions of Mineral Conservation and Development Rules, 2017 in respect of your Haddinpade Iron Ore Mine , ML 2516 (79.806Ha) located in SM Block,Sandur Taluk, Ballari district, Karnataka state.

Sir,

The following provisions of the Mineral Conservation & Development Rules 2017 were found violated in your above mine during the inspection carried out by the undersigned in presence of Shri. P.Sreenivasa Rao, Manager Mines, Shri. Pramod S Ritti, Geologist and Shri. Naresh Kakumanu, Mining Engineer on 10.10.2017.

Rule	Nature of violations observed
11(1)	Modification in the approved Mining Plan with PMCP was approved vide letter no.279/767/2003/BNG dated 14.10.2016 for a period of 2016-17 to 2020-21. The deviation observed in mining operation vis-a-vis approved document are given below As per the approved document, production was proposed in section lines FF', GG' & HH'. It was observed that there is very little movement of benches towards southern side i.e in between section line GG' & HH' distorting the stripping ratio.

19(1)	<p>Where heavy earth moving machinery is used in mines, the holder of a mining lease shall maintain log books duly authenticated by the manager or mining engineer of such mines in respect of each machine showing date-wise account of hours worked, hours not worked, reasons for non-working, consumption of fuel or energy and lubricants and output of the machine during the corresponding working hours.</p> <p>The same is not maintained.</p>
-------	---

02. In this connection it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017. Further, the violation of Rule 11(1) may also attract provisions of Rule 11(2) of MCDR, 2017 regarding suspension of mining operations till the compliance of violations.

03. You are advised to rectify/explain the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

Yours faithfully,

Sd/-
(Arun Kumar)
Deputy Controller of Mines

Copy forwarded to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Department of Mining & Geology, No.49, Khanijabhavan, R.C. Road, Bangalore-560 001

Sd/-
(Arun Kumar)
Deputy Controller of Mines