

## भारत सरकार /GOVERNMENT OF INDIA खान मंत्रालय /MINISTRY OF MINES

# भारतीय खान ब्यूरो /INDIAN BUREAU OF MINES

### ग्वाहाटी क्षेत्रीय कार्यालय/GUWAHATI REGIONAL OFFICE

क्षेत्रीय खान नियंत्रक का कार्यालयाOFFICE OF THE REGIONAL CONTROLLER OF MINES

दूरभाष सं.:/फॅक्स सं:.0361 2656184, Tel/Fax – 0361-2656184 E-mail – ro.guwahati@ibm.gov.in House No. 216, 3<sup>rd</sup> Floor, Above IDBI Bank Chandmari, Post – Bamunimaidan, Dist – Kamrup (M). Guwahati. Assam-781021

No. IBM/GHY/MEG/JNH/LST-14

Date: 04.01.2021

To

Shri Venkatesan Tyagarajan (Nominated Owner), M/s. Dalmia Cement Bharat Ltd., Vill. Thangskai, P.O- Luhmsnong, East Jaintia Hills, Meghalaya – 793210.

Email - t.venkatesan@dalmiacement.com

Sub: Violation of the provisions of MCDR, 2017 in respect of your Umsoo Mootang Block-V mine (38MEG03015) over an area of 128.52 Ha. in Thangskai Village, Taluka- Narpuh, East Jaintia Hills district of Meghalaya state.

Sir,

Rule No.

The following provision of MCDR, 2017, was found violated in your above mine during the inspection carried out on 16th December 2020 by the undersigned in presence of your mine officials Shri Sanjay Kumar (Mine Agent) & Shri Chandra Shekhar Sharma (Geologist).

# 11(1): No holder of a mining lease shall commence or carry out mining operations in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines or prepared and certified in accordance with the system established by the State Government pursuant to the proviso to clause (b) of sub section (2) of section 5 or approved by the competent authority of the Atomic Minerals Directorate for Exploration and Research, in respect of the minerals specified in Part B of the First Schedule to the Act where the Grade of such atomic minerals is equal to or above the threshold value limits

declared under Schedule-A of the Atomic Mineral

Concession Rules, 2016.

### Nature of violation observed

Following provision of MCDR 2017 have been found violated in your mine:

- 1) It was observed during the inspection that a quarry of approximately 240 m x 300 m x 20 m has been developed towards N-NW side of the CF (Mining Lease) pillar, however no such proposal has been given in the approved mining plan in year 2019-20 and 2020-21.
- 2) Configuration, pattern, height & width of existing soil and waste dumps are not as per the proposal given in approved development plans and sections. Systematic development of waste & soil benches has not been carried out as per the approved review of mining plan document.
- O2 In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of Mineral Conservation and Development Rules, 2017.
- The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.
- You are therefore advised to rectify the above violation immediately and intimate the position to this office within a period of 45 (Forty Five) days from the date of issue of this letter.

Yours faithfully,

Asst. Controller of Mines

Copy forwarded for kind information to –

The Regional Controller of Mines, IBM, Ranchi & IBM, Guwahati. The Director, Directorate of Minerals Resources, Govt. of Meghalaya, Risa Colony, Shillong,

Meghalaya-793003

Vikas Kumar Asst. Controller of Mines

170 May