INDIAN BUREAU OF MINES MINERALS DEVELOPMENT AND REGULATION DIVISION

MCDR INSPECTION REPORT

Bhubaneshwar regional office

Mine file No : ORI/IRON/KJR/MCDR-74-BBS Mine code : 300RI08063

(i) Name of the Inspecting: DEY) NARENDRA MOHAN DEY

Officer and ID No.

(ii) Designation : Assistant Mining Engineer(iii) Accompaning mine : REPRESENTATIVE OF LESSEE

Official with
Designation

(iv) Date of Inspection : 18/07/2014

(v) Prev.inspection date :

PART-I : GENERAL INFORMATION

1. (a) Mine Name : DALPAHAR

(b) Registration NO. : IBM / 8424 / 2011

(c) Category : B Manual
(d) Type of Working : Opencast

(e) Postal address

State : ORISSA
District : KEONJHAR
Village : DALPAHAR

Taluka : N.A

Post office : Pin Code :

FAX No. : 26259576

E-mail : avinjain@rediffmail.com
Phone : 26253002 / 41642414

(f) Police Station : JODA

(g) First opening date : 09/06/1986

(h) Weekly day of rest : SUN

2. Address for : VILLAGE : DALPAHAR, P.O: JODA, DISTT: KEONJHAR

correspondance PIN: 758 034

SHRI AVIN JAIN, SON & LEGAL HEIR OF LATE D C JAI

3. (a) Lease Number : ORI0160 (b) Lease area : 89.96 (c) Period of lease : 20

(d) Date of Expiry : 08/06/2006

4. Mineral worked : IRON ORE Main

PAGE: 2

5. Name and Address of the

Lessee : DHARAM CHAND JAIN

KEONJHAR ORISSA KEONJHAR

ORISSA Phone: FAX :

: SHRI DHARAM CHAND JAIN Owner

KEONJHAR ORISSA KEONJHAR

ORISSA Phone: FAX :

6. Date of approval of Mining : Renewal under rule 24 MCR1960 11/01/2008 Plan/Scheme of Mining : Modif.of approved Mining Plan 11/10/2010

PAGE : 3

PART - II : OBSERVATION/COMMENTS OF INSPECTING OFFICERS

Exploration :

Sl.No.	Item	Proposals	Actual work	Remarks
1a	Backlog of previous year	SCHEME OF MINING APPROVED ON 24.05.2011 FOR THE PERIOD 2011- 12 TO 2015- 16.PROPOSAL OF PREVIOUS YEARS WAS AS FOLLOWS: 2011-12: 4 BH, 2012-13: 4 BH. 2013- 14: 4 BH	NIL	MINING OPERATION HAS BEEN CLOSED SINCE 1993 AS REPORTED BY THE REPRESENTATIVE OF THE LESSEE. SUBSEQUENTLY THE STATE GOVT DECLARED THE LEASE HAS STOOD LAPSED W e f.01.09.1997 VIDE LETTER DATED 01.05.2015.
1b	Exploration over lease area for geological axis 1 or 2	MINING	NIL HOWEVER DETAILED GEOLOGICAL SURVE Y HAS ALREADY BEEN CARRIED OUT EARLIER, SURFACE EXPOSURE HAVE BEEN FOUND, EXPLORATION DONE IN PAST BY TRIAL PITS WHICH LATER ON CONVERTED INTO QUARRIES, NUMBER OF PITS WERE OPENED. THESE SCATTERED SMALL QUARRIES SHOWING PRESENCE OF IRON AND MANGANESE ORE COVERS THE EXTENSIVE PART OF THE LEASE AREA AND THUS THE MINERALASIED ZONE HAS BEEN DEMARCATED BASED ON THAT. THE PROVED RESERVE HAS BEEN ESTIMATED BASED ON THE ACTUAL THICKNESS OF THE	SINCE 1993 AS REPORTED BY THE REPRESENTATIVE OF LESSEE. SUBSEQUENTLY THE STATE GOVT DECLARED THE LEASE HAS STOOD LAPSED W e f.01.09.1997 VIDE LETTER

Remarks

1d	Balance area to be explored to bring Geological axis in 1 or 2		NIL	NO MINING OPERATION SINCE 1993.
1e	Balance reserve as on 01/04/20	AS PER S O M APPROVED ON 24.05.2011 THE RESERVE ESTIMATED AS PER UNFC WAS AS FOLLOWS:	IRON: 111: NIL, 121: 1005000 MT, 122: 444375 MT (+ 57% FE) , 211: 201000 MT, 222: 88875 MT (+45 TO 57% FE) , 333 : 564750 MT MANGANESE: 111: NIL, 121: 870000 MT, 122: 1335625 MT (+20% MN) , 211: 348000 MT, 222: 534250 MT (+ 10 TO 20% MN), 333: 1288000 MT	
1f	General remarks of inspecting officers on geology, exploration etc	THE S O M APPROVED ON	NO BH HAS BEEN DRILLED IN THE LEASE AREA. PROVED RESERVE HAS ESTIMATED BASED ON THE ACTUAL THICKNESS OF THE ORE BODY AS ALREADY EXPOPSED IN QUARRY FACES.	OPERATIION SINCE 1993 AS REPORTED BY THE

Propasals Actual work

Development :

Item

Sl.No.

2a	Location of	THERE WERE 11 NIL	NO MINING
	development	QUARRIES IN	OPERATION SINCE
	w.r.t.lease area	THE LEASE .	1993.
		BUT PROPOSAL	
		FOR	
		DEVELOPMENT IN	
		3 QUARRIES	
		ONLY NAMELY	
		QUARRY-1,	
		QUARRY-4 AND	
		QUARRY-7 IN	
		THE SCHEME	
		PERIOD , AS	
		PER S O M	
		APPROVED ON	
		24.05.2011 FOR	
		THE PERIOD	
		2011-12 TO	
		2015-16.	
2f	General remarks	QUARRY 1,4 & 7 NIL	THE STATE GOVT
	of inspecting	WERE PROPOSED NO WORK SINCE 1993	DECLARED THE LEASE
	officers on	FOR	HAS STOOD LAPSED
	development of		w e f 01.09.1997
	pit w.r.t. type	THE SCHEME	VIDE LETTER
	of deposit etc	PERIOD.	DATED01.05.2015.

Exploitation:

Sl.No.	Item	Propasals Actual work	Remarks
3a	Number of pit proposed for production	3 (QUARRY -1, NIL 2 & 3)	MINING OPERATION HAS BEEN DISCONTINUED SINCE 1993 AS REPORTED BY THE LESSEE. SUBSEQUENTLY THE STATE GOVT. DECLARED THE LEASE HAS STOOD LAPSED W e f 01.09.1997 VIDE LETTER DATED 01.05.2015.

```
mineral
                      AS FOLLOWS :
    production
                      IRON ORE
    proposed
                      :2011-12:
                      130184 CUM,
                      2012-13:
                      131120 CUM,
                      2013-14:
                      132072 CUM,
                      2014-15:
                      135020 CUM,
                      2015-16:
                      135062
                      CUM.
                      MANGANESE:
                      2011-12:
                      111399 CUM,
                      2012-13:
                      111403 MT,
                      2013-14:
                      111439 CUM,
                      2014-15:
                      111481 CUM,
                       2015-16:
                      111561 MT
                      PROPOSAL OF
3с
   Recovery of
                                      NIL
                                                                  NO MINING
    sailable/usable SALEABLE
                                                                  OPERATION SINCE
    mineral from ROM MINERAL FROM
                                                                  1993
    production
                      ROM PRODUCTION
                      AS PER S O M
                      APPROVED ON
                      24.05.2011.
                      IRON : 2011-
                      12: 195276 MT,
                      2012-13:
                      196684
                      MT,2013-14:
                      198108 MT,
                      2014-15:
                      202530 MT,
                      2015-16:
                      202593 MT
                      MANGANESE:
                      2011-12: 69624
                      MT, 2012-13:
                      69627 MT,
                       2013-14: 69627
                      MT, 2014-15:
                      69676 MT,
                      2015-16: 69726
```

3b

Quantity of ROM PROPOSAL WAS

МТ

Total area put 30 in use under different heads at the end of year

AREA ALREADY PUT IN USED UNDER MINING : 8.698 HA, USED FOR DUMP

: 5.620 HA,

INFRASTRUCTURE: 0.607 HA, OCCUPIED BY ROAD: 1.539 HA TOTAL: 16.464

General remarks OPENCAST OTHER NIL 3q of inspecting officers on method of mining METHOD OF

THAN FULLY MECHANISED

MINING BY DEPLOYING EXCAVATOR , JCB LOADER, JACK HAMMER,

COMPRESSOR, TIPPER. 3 NOS OF QUARRIES PROPOSED TO BE

WORKED, ONE IN IRON AND TWO IN MANGANESE.

HARD ROCK MASS PROPOSED TO BE

LOOSENED BY DRILLING &

BLASTING. DRILLING OF BLAST HOLES

PROPOSED TO BE

DONE BY WAGON DRILL & JACK

HAMMER.DUMPERS PROPOSED TO BE

DEPLOYED FOR

TRANSPORTATION

OF IRON ORE . EXCAVATION &

LOADING FOR

MANGANESE ORE PROPOSE TO BE

DONE MANUALLY.

Solid Waste Management - Dumping:

Sl.No. Item Propasals Actual work Remarks

NO MINING

NO MINING

1993.

OPERATION SINCE

OPERATION SINCE 1993 AS REPORTED

BY THE

REPRESENTATIVE OF

LESSEE.

SUBSEQUENTLY STATE GOVT DECLARED THE LEASE HAS STOOD LAPSED w e f 01.09.1997 VIDE LETTER DATED

01.05.2015.

4a	Separate dumping of topsoil, OB and mineral rejects (Rule 32,33)	SEPARATE DUMPING OF OB / WASTE	NIL	NO MINING OPERATION SINCE 1993
4c	Number of dumps within lease area and outside of lease area	ONE DUMP WITHIN LEASE AREA AND NO DUMP OUTSIDE LEASE	NIL	
4k	Specific comments of inspecting officer on waste dump management		NIL HOWEVER ALREADY 5.620 HA LAND HAS BEEN BROKEN DUE TO WASTE DUMPING.	NO MINING OPERATION SINCE 1993. SUBSEQUENTLY STATE GOVT DECLARED THE LEASE HAS STOOD LAPSED w e f 01.09.1997 VIDE LETTER DATED 01.05.2015.

Solid Waste Management - Backfilling:

Sl.No.	Item	Propasals	Actual work	Remarks
5a	Status of part or full extraction of mineral from mined out area before starting backfilling.	NO PROPOSAL	NIL	NO MINING OPERATION SINCE 1993.
5e	General remarks of inspecting officers on backfilling and reclamation etc.	AS ORE IS NOT	1 NIL	NO MINING OPERATION SINCE 1993

Progressive Mine Clousre Plan:

Sl.No.	Item	Propasals	Actual work	Remarks
	ıcem	Propasars	ACTUAL WOLK	

6a	Whether Annual report on PMCP submitted on time and correctly. Rule 23 E(2).	NOT SUBMITTED	AS THE MINE IS NOT IN OPERATION SINCE 1993, THE PROPSAL WAS NOT CARRIED OUT	STATE GOVT DECLARED THE LEASE HAS STOOD LAPSED w e f 01.09.1997 VIDE LETTER DATED 01.05.2015.
бе	Cumulative no .of plants	1000 NO OF PLANTS TO BE PLANTED OVER AN AREA 0.495 HA DURING 2011-12 TO 2015-16	NIL	NO MINING OPERATION SINCE 1993.
6q	General remarks of inspecting officers on PMCP compliance and progressive closure operations etc.	WALL, GARLAND		STATE GOVT DECLARED THE LEASE HAS STOOD LAPSED W e f 01.09.1997 VIDE LETTER DATED01.05.2015.

Mineral Conservation:

Sl.No.	Item	Propasals	Actual work	Remarks
7a	ROM Mineral dispatch or	PROPOSED IN	NIL	NO MINING OPERATION SINCE
	grade-wise sorting within lease area	ALLOVED ON 24.05.2011.		1993

7d	Any beneficiation process at mines .		NIL NO MINING OPERATION SINCE 1993.	
		RAISED FROM THE MINE PROPOSED TO BE SIZED, SORTING / SCREEINING, BLENDING		
7e	General remarks of inspecting officer on Mineral conservation and beneficiation issues	THE SUB-GRADE MATERIAL PROPOSED TO BE GENERATED SHALL BE BLENDED WITH HIGH GRADE ORE TO MAKE IT MARKETABLE. REGARDING BENEFICIATION , ORE RAISED FROM THE MINE REQUIRE SIZING, DRESSING, SORTING / SCREENING, BLENDING ETC	NO MINING OPERATION	STATE GOVT. DECLARED THE LEASE HAS STOOD LAPSED W e f 01.09.1997 VIDE LETTER DATED 01.05.2015.

Environment:

Sl.No.	Item	Propasals	Actual work	Remarks
8a	Separate removal and utilization of topsoil (Rule 32)		NIL	NO MINING OPERATION SINCE 1993.
8c	Separate dumps for overburden, waste rock, rejects and fines (Rule 33)	SEPARATE DUMP FOR OB / WASTE,	NIL ALREADY 5.620 HA OF LAND HAS BEEN BROKEN DUE TO WASTE DUMP.	NO MINING OPERATION SINCE 1993.

8f	Baseline information on existence of plantation and additional plantation done (Rule 41)	HA IS UNDER FOREST. 1000 SAPLINGS	NIL ;	NO MINING OPERATION 1993.
8i	General remarks of inspecting officer on aesthetic beauty in and around mines area			TOTAL LEASE AREA IS UNDER FOREST, MINING OPERATION HAS NOT BEEN CARRIED OUT SINCE 1993. SO AESTHERTIC BEAUTY IN AND AROUND THE MINES AREA HAS BEEN MAINTAINED.

Compliance of Rule 45:

Sl.No.	Item	Propasals	Actual work	Remarks
9a	Status of submission of Monthly and Annual returns	NOT SUBMITTED.	SCHEME OF MINING APPROVED ON 24.05.2011 FOR THE PERIOD 2011-12 TO 2015-16 OVER AN AREA 101.171 HA COVERING 5 BLOCKS NAMELY A, B1, B2, B3 & C. THE FOUR BLOCKS B1, B2, B3 & C OVER AN AREA 0.607 HA, 7.689HA, 1.012 HA & 2.002 HA RESPECTIVELY HAVE ALREADY BEEN LAPSED AND TREATED AS INFRACTUOUS AND DEVOID OF ANY MERIT FOR CONSIDERATION BY GOVT. OF ODISHA DATED 09.07.2013 AND THE REMAINING BLOCK A OVER AN AREA 89.961 HA DECLARED AS LAPSED W e f 01.09.1997 VIDE LETTER DATED 01.05.2015.	

9g Scrutiny of ANNUAL RETURN NO MINING OPERATION
Annual return on NOT RECEIVED SINCE 1993.

sale value, Ex.
Mine price and
production cost

STATE GOVT
DECLARED THE LEASE
HAS STOOD LAPSED
w e f. 01.09.1997
VIDE LETTER DATED
01.05.2015.

PAGE: 13

Details of violations observed during current inspection and compliance position of violation pointed out

Violation observed			Show couse position		
Rule NO.	Issued on	Compliance on	Rule NO.	Issued on Compliance on	
Rule 13(1)	22/08/2014	10/03/2016			

Date:

(NARENDRA MOHAN DEY)

Indian Bureau of Mines