



भारत सरकार
GOVERNMENT OF INDIA
खान मंत्रालय
MINISTRY OF MINES
भारतीय खान ब्यूरो
INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक कार्यालय



OFFICE OF REGIONAL CONTROLLER OF MINES

29, इंडस्ट्रियल सबर्ब, II स्टेज, तुमकुर रोड,
गोरगुंटापाल्या येशवंतपुर
बेंगलुरु -560022

दूरभाष: (080) 39505368 / 29720499
Email ID: ro. bangalore@ibm.gov.in

सं/No.: KNT/RCH/G-4/BNG

Mine-code: 27KAR16004

दिनांक/Dated:04/02/2022

To,
Sri. M. Prakash,
Executive Director(I/C),
M/s The Hutti Gold Mines Co. Ltd.,
Hutti Camp, Hutti
Taluka-Lingasugur,Dist.- Raichur-584115,
Karnataka State.

विषय/Subject: **Violation of provisions of MCDR 2017 in respect of your Hirabuddini Gold Mine, ML 2578 over an extent of 22.18 ha(as per lease dead) in Hirabuddini Village, Manvi Taluk , Raichur District of Karnataka State.**

Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mine during inspection on 12.01.2022 by Sri Sandeep Kumar Singh, ACOM and Shri K. Srinivas, JMG in presence of Sri Kumar Mohan Singh, Mines Manager, Sri Jhonson, Mining Engineer and other mine officials:

Rules	Nature of Violations observed
11 (1)	<p>Scheme of Mining Plan was approved by IBM vide letter no. 279/717/2001/BNG dated 23.06.2016 for the period 2016-17 to 2020-21 & Review and updation of Mining Plan was approved by IBM vide letter no. 279/717/2001/BNG dated 30/12/2020 for the period 2021-22 to 2025-26.The deviations observed in mining operations vis-à-vis approved document are given below:</p> <p>i) It was observed during site inspection that no exploration has been carried out against the proposed surface diamond drilling of 5 boreholes with meterage of 1210m for the year 2020-21. Further for the year 2021-22, the surface diamond drilling of 1 borehole with depth of 300 m & one trench (20mx2mx2m) are proposed, against which till date no exploratory work is carried out.</p> <p>ii) It was observed that against the total proposed development of 473 m (383 m on lode & 90 m off lode development), the development of only 216m has been carried out for the year 2020-21.Thus, there is a deviation of 55% less in the development.</p> <p>iii) It was observed that against the proposed ROM production of 60,000 tonnes for the year 2020-21, however only 25681tonnes of production has been reported as per the Annual Return for the year 2020-21. Thus, there is a deviation of 58% less in ROM production.</p>
33	<p>The holder of a mining lease shall on or before the 30th day of June every year submit a digital copy along with a print copy of the surface geological plans and sections maintained under rule 32 along with the annual return. The surface geological plans and sections have not been submitted as per the provision of this rule.</p>

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR (Amendment), 2021.
03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.
04. You are advised to rectify the above violations immediately and intimate the position to this office **within 45 (Forty-Five) days** from the date of issue of this letter.

भवदीय/Yours faithfully,

Sd/-

(K.Srinivas)

Junior Mining Geologist
Indian Bureau of Mines

Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. Sri. Prabhuling Kavalikatti, IAS, The Managing Director, The Hutti Gold Mines Co. Ltd., 3rd Floor, KHB shopping Complex, National Games Village, Koramangla, Bangalore-560 047.
3. The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560001.
4. Sri Hanumanthappa, Agent, M/s The Hutti Gold Mines Co.Ltd., Hutti -584115,Lingasugur taluk, Raichur district, Karnataka. E-mail : hanumanthappa1964@gmail.com

Sd/-

(K.Srinivas)

Junior Mining Geologist
Indian Bureau of Mines