



भारत सरकार  
GOVERNMENT OF INDIA  
खान मंत्रालय  
MINISTRY OF MINES  
भारतीय खान ब्यूरो  
INDIAN BUREAU OF MINES  
क्षेत्रीय खान नियंत्रक कार्यालय



OFFICE OF REGIONAL CONTROLLER OF MINES

29, इंडस्ट्रियल सबर्ब, II स्टेज, तुमकुर रोड,  
गोरगुंटापाल्या येशवंतपुर  
बेंगलुरु -56002

दूरभाष: (080) 39505368 / 29720499  
Email ID: ro. bangalore@ibm.gov.in

सं/No.: KNT/RCH/G-2/BNG

Mine-code: 27KAR16002

दिनांक/Dated: 03/02/2022

To,  
Sri. M. Prakash,  
Executive Director(I/C),  
M/s The Hutti Gold Mines Co. Ltd.,  
Hutti Camp, Hutti  
Taluka-Lingasugur,  
Dist.- Raichur-584115, Karnataka

विषय/Subject: **Violation of provisions of MCDR 2017 read with MCDR(Amendment),2021 in respect of your Uti Gold Mine, ML 2126 over an extent of 47.96 ha(as per lease dead), in Uti Village, Deodurga Taluk , Raichur District of Karnataka State.**

Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 read with Mineral Conservation and Development (Amendment) Rules, 2021 were found violated in your above mine during inspection on 10.01.2022 by the undersigned along with Shri K. Srinivas, JMG in presence of Sri Nagaraj, Mine Manager, Sri Ganesh, Geologist, Sri G. Shiva Krishna, Mining Engineer and other mine officials:

Rules	Nature of Violations observed
<b>11 (1)</b>	<p>Scheme of Mining Plan was approved by IBM vide letter no. 279/493/96/BNG dated 15/06/2016 for the period 2016-17 to 2020-21 and Review and updation of Mining Plan was approved by IBM vide letter no. 279/493/96/BNG dated 30/12/2020. The deviations observed in mining operation vis-à-vis approved document are given below.</p> <p>i) It was observed during site inspection that no exploration has been carried out against the proposed underground drilling of 6 boreholes with meterage of 360m for the year 2020-21. For the year 2021-22 also 3 surface boreholes with 640 m drilling are proposed against which till date no drilling has commenced.</p> <p>ii) It was observed that against the total proposed development of 936 m (598 m on lode &amp; 338 m off lode development) no development has been carried out for the year 2020-21.</p> <p>iii) It was observed that "Nil" quantity of waste generated against the proposed waste generation of 17,669 tonnes for the year 2020-21.</p> <p>iv) The ROM production has not been reported correctly in AR 2020-21. However as reported in the monthly returns for the year 2020-21, total</p>

	<p>quantity arrives to "28738" tonnes from Underground working against the proposed production of 60,000 tons which is 52 % less than the approved proposal.</p> <p>v) It was observed that the retaining wall and garland drain construction along proposed waste dumps, D-1 &amp; D-2 have not been carried out as per the proposal.</p>
<b>33</b>	<p>The holder of a mining lease shall on or before the 30<sup>th</sup> day of June every year submit a digital copy along with a print copy of the surface geological plans and sections maintained under rule 32 along with the annual return. The surface geological plans and sections have not been submitted as per the provision of this rule.</p>

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR (Amendment), 2021.

03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.

04. You are advised to rectify the above violations immediately and intimate the position to this office **within 45 (Forty-Five) days** from the date of issue of this letter.

भवदीय/Yours faithfully,

Sd/-

(Sandeep Kumar Singh)  
Assistant Controller of Mines  
Indian Bureau of Mines

Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. Sri. Prabhuling Kavalikatti, IAS, The Managing Director, The Hutti Gold Mines Co. Ltd., 3rd Floor, KHB shopping Complex, National Games Village, Koramangla, Bangalore-560 047.
3. The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560001.
4. Sri Hanumanthappa. H, Agent, Uti Underground Gold Mine, The Hutti Gold Mines Co. Ltd., Hutti Camp, Hutti Taluka-Lingasugur, Dist.- Raichur-584115- [hanumanthappa1964@gmail.com](mailto:hanumanthappa1964@gmail.com)

Sd/-

(Sandeep Kumar Singh)  
Assistant Controller of Mines  
Indian Bureau of Mines