

भारत सरकार/Government of India खान मंत्रालय/Ministry of Mines भारतीय खान ब्यूरो/Indian Bureau of Mines हैदराबाद क्षेत्रीय कार्यालय/Hyderabad Regional Office



Phone No. : (040)-27539992/2753993

Fax No.(TF): (040)-27539991

: ro.hyderabad@ibm.gov.in E-Mail :AP/KNL/Lst-182/Hyd

F.No. Mine code: 38APR11133

To,

Sri S Subose, Lessee,

Kamalapuram Limestone & Dolomite Mine,

H.No. 104-1, Kothapeta,

Dhone, -518222,

Kurnool Dist, A.P.

603, 6th Floor,

CGO Towers, Kavadiguda, Secunderabad - 500 080.

Date:03-03-2023

Sub: - Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Kamalapuram Limestone & Dolomite Mine, over an extent of 4.213Ha. Situated in Kamalapuram, villages, Mandal-Dhone, District- Kurnool of Andhra Pradesh State.

The following provision of Mineral Conservation & Development Rules, 2017 were found violated in your above mine during the inspection on 06/02/2023, by the undersigned, in presence of Shri SVVS Ramakrishna Rao, Qualified person.

1	Nature of Violation observed
Rule	and the approved Modified mining plan, dated
11(1)	The following deviations were observed from the approved Modified mining plan, dated
	22-02-2021. 2) There was a proposal to drill 07 core boreholes in the year 2021-22, but the said
	exploration is not carried out so fail. b) In the approved mining plan for limestone there was a proposal to work between the co-ordinates N 1699870 to 1699960 & E 814930 to E815080. However, during inspection, it was observed that in the Northern part of the lease However, during inspection, it was observed that in the Northern part of the lease.
	Not submitted yearly report on implementation of progressive mine closure for the year
26(2)	
	2021-22.
27	As per the approved document area put to use at the end of the plan period was shown as 1.925Ha only, however during inspection it was observed that entire lease area is



76 Sept. 2005	utilized for mining and other allied activities. So, a fresh bank guarantee for the entire broken up area as per Rule 27(1) of MCDR 2017 amended up to 03-11-2021, need to be submitted to this office.
55(3)(ii)	Not appointed Mining Engineer and Geologist for the purpose of carrying out mining operations.

- 02. In this connection, it is brought to your notice that the above violation constitutes an offence, punishable under Rule 62 of MCDR, 2017.
- 03. The mining operations can be suspended under Rule 11(2), if compliance of MCD Rules 2017 is not found satisfactory, or prosecution can be made, or both can be done.
- 04. Rules whose contravention shall be punishable with fine as per the schedule-III of MCDR 2017, Amended upto 3rd nov-2021.
- 04. You are advised to rectify the above violation immediately and intimate the position to this office within 45 (Forty-five) days from the date of issue of this letter.

Yours faithfully,

2/0

(Ramakishan Ravula)
Deputy Controller of Mines,
Indian Bureau of Mines.

Copy forwarded to: -

1) खान नियंत्रक(द), भारतीय खान ब्यूरो, बंगलूरण

 The Director of Mines & Geology, Govt. of Andhra Pradesh, Sri Anjaneya towers, D. No-7-104, Block B-5, 6th floor, Ibrahimpatanam, Vijayawada (Krishna District)-521456.

(Ramakishan Ravula)
Deputy Controller of Mines,

Indian Bureau of Mines.