

GOVERNMENT OF INDIA  
MINISTRY OF MINES  
INDIAN BUREAU OF MINES

Office of the Regional Controller of Mines

File No. AP/KNL/Fe-28/Hyd

Room No.603, 6<sup>th</sup> Floor,  
CGO Tower, Kavadiguda  
Hyderabad - 500 080.  
Date: 13.1.2017

To:

Sri G.Venkata Rami Reddy, Mine Owner,  
H.No.9/282, Gowripet,  
AT&Post: Bethamcherla 518599.  
District – Kurnool.  
Andhra Pradesh – 521 438

Sub: Violation of provisions of Mineral Conservation and Development Rules, 1988 in respect of your Brahmeswara Iron Ore & Steatite Mine over an extent of 33.01 ha in Sy.No.865 situated in Veldurthy village & mandal in Kurnool district of Andhra Pradesh state.

Sir,

The following provisions of Mineral Conservation and Development Rules 1988 (MCDR, 1988), were found violated in your above mine during the inspection of the mine on 02.01.2017 by Sri Y.M.Shiva Prasad, Assistant Mining Engineer of this office, accompanied by Sri Purusotham, Mines Manager of your mine.

Rule no.	Rule position	Nature of violation
13(1)	Every holder of a mining lease shall carry out mining operations in accordance with the approved mining plan with such conditions as may have been prescribed under sub-rule (2) of rule 9 <del>or with such modifications, if any, as permitted under rule 10 or the mining plan or scheme approved under rule 11 or 12 as the case may be.</del>	Mining operations are not carried out in accordance with the proposals given in approved Mining Plan for Renewal vide letter no. AP/KNL/MP/St&Fe-44/Hyd dated 29.04.2014 to the extent indicated below: i. No exploration was carried out so far; against the approved exploration by 8 no. of Core bore holes during the year 2015-16.
23E(2)	The Owner, agent, manager, or mining engineer shall submit to the Regional Controller of Mines or the officer authorized by the State Government in this behalf, as the case may be, a yearly report before First July of every year setting forth the extent of protective and rehabilitative works carried out as envisaged in clouser plan, and if there is any deviation, reasons thereof.	The yearly report as required under the provision of this rule for the years 2014-15 & 15-16 have not been submitted so far to the Regional Controller of Mines, Indian Bureau of Mines, Hyderabad..

In this connection, it is brought to your notice that the above violation constitutes an offence punishable under rule 58 of MCDR, 1988.

02. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (forty-five) days from the date of issue of this letter.

Yours faithfully,

(IBRAHIM SHARIEF)  
Sr. Assistant Controller of Mines.

*Not on the original:*

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangaluru for kind information.
2. The Director of Mines & Geology, Government of Andhra Pradesh, Sri Anjaneya Towers, D.no.7-104, Block B, 5<sup>TH</sup> & 6<sup>TH</sup> floors, Ibrahimpatnam-521456, Vijawada, Krishna District.
3. The Assistant Director of Mines & Geology, Government of Andhra Pradesh, Kurnool District; A.P.

(IBRAHIM SHARIEF)  
Sr. Assistant Controller of Mines