

मेल/त्वरितडाकद्वारा



भारतसरकार /GOVERNMENT OF INDIA  
खानमंत्रालय/ MINISTRY OF MINES  
भारतीयखानब्यूरो /INDIAN BUREAU OF MINES  
क्षेत्रीयखाननियंत्रककार्यालय/ OFFICE OF THE REGIONAL  
CONTROLLER OF MINES

फैक्स: (080) 23371027 / 23373287  
दूरभाष: 080-23371027 / 23375366/67  
Email ID: ro. bangalore@ibm.gov.in.

29, इंडस्ट्रियलसबर्बाIIस्टेज,,तुमकुरोड,  
गोरगुंटापाल्यायेशवंतपुर,  
बेंगलुरु -560022

सं.KNT/GLB/LST-48/BNG

दिनांक:24.02.2021

सेवामें/To,

Shri. Anoop Kumar Saxena,  
Nominated Owner and Chief Operating Officer,  
M/s. Kalburgi Cement Private Limited,  
(formerly Vicat Sagar Cement Private Limited)  
Reliance Majestic Building, Door No:8-2-626,  
Road No:11, Banjara Hills, Hyderabad – 560 034.

विषय/Sub: Violation of provisions of Mineral Conservation and Development Rules, 2017 in respect of your Kalburgi Cement Limestone Mine (ML 2612) over an area of 446.77 Ha located in Chatrasala (Vil), Kherchikhed (P), Chincholi (Tq) Kalaburagi Dist. Karnataka – 585 320

महोदय/Sir,

The following provisions of the Mineral Conservation & Development Rules 2017 were found violated in your above mine during the inspection carried out by the undersigned in presence of Shri. G.Sudhakar - Manager Mining & Shri. K.Nagaraja Rao - Geologist on 18.02.2021.

Rule	Nature of violations observed
11 (1)	Modified Review & updation of Mining Plan with PMCP was approved vide letter no. 279/1030/2009/BNG/1118 dated:20/11/2018 for a period of 2019-19 to 2023-2024. The deviation observed in mining operation vis-a-vis approved document are given below:  i)During the year 2019-20, only 1,45,227 Tons of overburden was handled against the proposal of 2,05,654 Tons, thereby resulting in (-) 29.38 % deviation & distorting the stripping ratio. ii) It was proposed to consume 2, 10,000 Tons of limestone from the stock. During the inspection it was observed that no limestone was handled from the stock.

26(1)	During the year 2019-20, 407 Mts of retaining wall was proposed to be constructed whereas only 130 Mts have been constructed so far.
45(7)	In Part VI, Sec 1 of the annual returns, Opening stock & closing stock of ROM ore at mine head have not been reflected & shown.

02. In this connection it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017. Further, the violation of Rule 11(1) may also attract provisions of Rule 11(2) of MCDR, 2017 regarding suspension of mining operations till the compliance of violations.

03. You are advised to rectify/explain the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

भवदीय/Yours faithfully,

Sd/-

(अरुणकुमार)

उपखाननियंत्रक

भारतीयखानब्यूरो

प्रतिलिपिसूचनार्थ'/Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Department of Mining & Geology, No.49, Khanijabhavan, R.C. Road, Bangalore-560 001

Sd/-

उपखाननियंत्रक

भारतीयखानब्यूरो