

भारत सरकार/ Government of India खान मंत्रालय / Ministry of Mines भारतीय खान ब्यूरों / Indian Bureau of Mines क्षेत्रीय खान नियंत्रक का कार्यालय / Office of the Regional Controller of Mines



रजिस्टर्ड ए०डी० उल्लंघनपत्र

Scheme No.-11, Kamla Nehru Nagar Jabalpur, dated: - 11/12/2020

File No.: MP/Jabalpur/Iron Ore-06

सेवा मे,

M/s. Nirmala Minerals Yash Tower, Pathak Ward, Tahil-Sihora, Dist-Katni (M.P.)-483501 Email- infonmkatni@gmail.com

विषय – म०प्र० राज्य के Jabalpur जिले में स्थित आपकी Agariya Iron Ore Mine, (क्षेत्रफल. 20.141 है0) में खिनज संरक्षण एवं विकास नियमावली, 2017 के नियमों का उल्लंघन। (Mine Code-30MPR18002)

महोदय,

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mentioned mine during the inspection by Shri Sanjay M. Girhe, Regional Mining Geologist on 01.10.2020 in presence of Shri. V.K. Pandey, GM (Mines), Shri G.P. Garg, Liasoning Officer and Shri. Sandeep Kumar, Geologist as under-:

नियम स.	पाए गए उल्लंघन की विस्तृत प्रकृति
Rule 11 (1)	According to this rule-No holder of a mining lease shall commence or carry out mining operation in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines or prepared and certified in accordance with the system established by the State Govt. pursuant to the provisions to caluse (b) of Sub Section (2) of Section 5 or approved by the competent authority of the Atomic Minerals Directorate for exploration and Researching respect of minerals specified in Part B of the First Schedule of the Act where the grade of such atomic minerals is equal to or above the threshold value limit declared under schedule-A of the Atomic Mineral Concession Rules 2016
	The Modified Mining Plan of above mentioned mine was approved vide this office letter No-MP/Jabalpur/Iron Ore/MPLN/MOD-36/16-17 dtd 24.03.2017 incorporating the proposals of working from 2017-18 to 2021-22. During the inspection, it was found that following provisions of rule have been violated
	During the year 2019-20, it was proposed to extend Quarry-2 towards south and excavation of iron ore was proposed by forming the benches from 415 mRL to 391mRL. (Ref Plate No-7) of approved document. But, during inspection it is noticed that working were carried out in both the Quarry-1 & 2 and attended the level of 368mRL which more than the proposals. Therefore, remarkable deviations with respect to mine working faces (both vertically and laterally) were noticed. Thus, the mining operations in the mine were not carried out in accordance with the approved proposals for the year 2019-20.
Rule 26(2)	The holder of mining lease shall submit a yearly report as per the format specified before 1 st July of every year setting forth the extent of protective and rehabilitative work carried out as envisaged in the approved mine closure plan, and if there is any deviation, reason thereof But, in your case the aforesaid Report in prescribe Form for the year 2019-20 not submitted to the Regional Controller of Mine, Jabalpur till the date of inspection.
Rule 45(5)(c)	The holder of a mining lease shall submit online returns in respect of each mine to the Regional Controller of Mine or any other authorized officer of the Indian Bureau of Mines in the following manner-
	An annual Return which shall be submitted before 1st day of July each year for the preceding financial year in electronic form, along with signed print copy of the same if it is digitally signed, in the respective Form
	But, during inspection it was observed that, you have not submitted online Annual Return for the year 2019-20 within stipulated time to this Regional office. Therefore, you are directed to submit aforesaid return in online system immediately through www.ibm.gov.in/index.php/auth/login .
Rule 55(1)(c)(i)	For the purpose of carrying out reconnaissance, prospecting or mining operations in accordance with these rules, – every holder of a mining lease shall employ, in case of– category 'A' mines, a whole-time mining engineer and a geologist; But, in your case a full time Geologist has not been appointed for the purpose of carrying out the

mining operations in accordance with these rules

- 02. In this connection it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR-2017.
- 03. Non-compliance of the rule 11(1) & of MCDR-2017 may lead to suspension of Mining operations under the provisions of rule 11(2) of MCDR-2017. Further, for the non-compliance of Rule 45(5)(C) of MCDR-2017, necessary action shall be initiated as deemed fit under the provision of rule 45(7) of MCDR,2017.
- 04. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty-Five) days from the date of issue of this letter.

भवदीय,

उप.खान नियंत्रक भारतीय खान ब्यरो

पता : योजनाकमांक 11, कमलानेहरू नगर, जबलपुर 482002 (भ०प्र०)/फोन2416780 / 2416589 / 2416231 फैक्स0761- 2416780 Address : Scheme No 11, Kamla Nehru Nagar, Jabalpur 482002 (M.P) Phone 2416780 / 2416589 241631 Fax : (0761) 2416780