भारत सरकार /Government of India खान मंत्रालय/Ministry of Mines भारतीय खान ब्यूरो/ Indian Bureau of Mines

क्षेत्रीय खान नियंत्रक का कार्यालय/Office of the Regional Controller of Mines

Phone No.: (0832)- 2741757 Opp.Old R.T.O.'s Office, Fax No. : (0832) -2741758 P.O. FATORDA - 403602,

E-Mail : <u>ro.goa@ibm.gov.in</u> Margao-GOA

File No:- KNT/BGK/LST-51/Goa Date:- 01.01.2021

MINE CODE: 38KAR26021

To,

Shri S.V Deogiri, Mine Owner M/s Amba Minerals Village Muddapur Mudhol Taluka, Bagalkot District, Karnataka-587122

Sub: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Muddapur Limestone & Dolomite Mine, (ML No. 2316) situated in Village – Muddapur, Mudhol - Taluka, Bagalkot - District of Karnataka State.

Sir,

The following provision of Mineral Conservation & Development Rules, 2017 were found violated in your above mine during the inspection on 10/12/2020 by the undersigned in presence of Shri Mohamed Shoheb Dangi, Mines Manager & Mining Engineer,

Rule	Nature of Violation observed
11(1)	Mining Operation have not been carried out in accordance with the Modification in Mining Plan(MMP) approved vide letter no. RMP/OTF.Mech-101(KNT)/Goa/2016-17, dated 03.02.2017 to the extent indicated below: (i) In the year 2019-20, it has proposed to dump the waste material as generated systematically in the northen side of the pit of specified dump location as mentioned in the table at page no. 29 of approved MMP. However, during the inspection it was observed that the waste material are being dumped in the unspecified places, within the 7.5 m of the lease boundary.
55(1)(c)	The Geologist required under these rule are not appointed.
45(7)	The domestic sale of mineral were carried out to the some buyers without having registration number as allotted by Indian Bureau of Mines.

- 02. In this connection, it is brought to your notice that the above violation constitutes an offence, punishable under Rule 62 of MCDR, 2017.
- 03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.
- 04. You are advised to rectify the above violation immediately and intimate the position to this office within 45 (Fourty five) days from the date of issue of this letter.

Yours faithfully,

(S.Prasad)
Deputy Controller of Mines & Officer Incharge
Indian Bureau of Mines

Copy forwarded to: -

- 1. The Controller of Mines, SZ, Indian Bureau of Mines, Bengaluru.
- 2. The Dy.Director General (Stat), IBM, Nagpur
- 3. The Director, Directorate Mines and Geology, Govt.of Karnataka 49, Khanij Bhavan,Race Course Road, Bengaluru.

(S.Prasad)
Deputy Controller of Mines & Officer Incharge
Indian Bureau of Mines