

भारत सरकार
खान मंत्रालय
भारतीय खान ब्यूरो
क्षेत्रीय खान नियंत्रक का कार्यालय
Mine Code-30ORI08027

फाईल सं.: ORI/IRON/KJR/MCDR-32/BBS / 2937

दि: 01/03/2019

सेवा में,

Shri Rajesg Kumar, Agent
M/s Tata Steel Ltd.
At/po.- Joda
Dist- Keonjhar-758034

Sub: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Joda east iron ore mine, over an area of 671.093 hectare in Keonjhar district of Odisha State.

Sir,

The following provisions of MCDR,2017 were found violated in your above mine during inspection on 17/02/2019 by undersigned in presence of Shri Rajesh kumar, Agent and Shri D. Vijayendra, Mines manager.

Rule No.	Nature of violations observed
11(1)	Mining operations have not been carried out in accordance with the Modified Review of Mining Plan, approved vide this office letter number MSM/FM/41-ORI/BHU/2017-18, dated 21.02.2018 to the extent given below: i) In 2017-18, retaining wall of 400*1*1.3m and garland drain of 400*1*1m was proposed around the sub grade dump-1A however it has been observed during inspection that the proposed retaining wall and garland drain have not been constructed. ii) Mineral reject/Sub grade for the year 2017-18 was proposed to stack on sub grade dump-1A however it has been observed that the sub grade/mineral reject generated during 2017-18 is stacked on sub grade dump-2A. iii) In 2017-18, about 3.6 ha was proposed for backfilling with reclamation & rehabilitation by 13500 nos. of plantation. However it has been observed during inspection that proposed backfilling and reclamation & rehabilitation has not been carried out.
45(5)(c)	The Annual returns submitted by you for the year 2017-18 has been scrutinized and following deficiencies has been observed: Part-VI, the closing stock of 1533315.0 furnished under item-2 is not synchronized with monthly returns submitted to this office. Yearwise generation of sub grade/mineral reject is not taking into consideration under item production and stocks of ROM ore at mine head.

02 In this connection, it is brought to your notice that the above violations constitute an offence punishable under rule 62 of Mineral Conservation and Development Rules, 2017.

03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory and may recommended for suspension/termination of mining lease under rule 45(7)(a), if rule 45(5)(c) is not complied.

04. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (forty-five) days from the date of issue of this letter.

Yours faithfully

Dayanand Upadhyay
01.03.19

(D. Upadhyay)

Senior Assistant Controller of Mines
Indian Bureau of Mines

ok

2938 Copy forwarded to:

1. The Controller of Mines (EZ) / Indian Bureau of Mines / Kolkata.
2. The Director of Mines / Directorate of Mines / Government of Orissa / Heads of Department Building / New Capital / Bhubaneswar-751 001.

2939

Dayanand Upadhyay
01.03.2019

(D. Upadhyay)

Senior Assistant Controller of Mines
Indian Bureau of Mines

ok

Issued

M

5/3/19