



भारत सरकार Government of India
खान मंत्रालय Ministry of Mines
भारतीय खान ब्यूरो Indian Bureau of Mines
क्षेत्रीय खान नियंत्रक का कार्यालय Office of the Regional Controller of Mines
100, ओल्ड नेहरु कॉलोनी, देहरादून (उत्तराखण्ड) 248001 / 100 Old Nehru Colony, Dehradun (U.K.) 248001
TEL- 0135-2676350 / 2671896, E-mail – ro.dehradun@ibm.gov.in



फाइलसंख्या File No: HP/SRM/LST-17

Mine Code: 38HPR10010

दिनांक, -03-2022

सेवा में To : श्री कुंवर मंगेन्द्र सिंह
पता- हाउस नं 460, सिरमौर मार्ग,
कौलागढ़ रोड, राजेन्द्र नगर,
देहरादून, उत्तराखण्ड-248001

E-mail: dksinha528@gmail.com
hemangsinghbhatee@gmail.com

विषय Sub: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Durga Limestone Mine, Mining Lease over an area of 4.444 ha located near Village: Borli, Tehsil-Renuka Ji District-Sirmour, H.P State.

महोदय Sir,

The following provisions of the Mineral Conservation & Development Rules, 2017 and read with amended rules 2021 were found violated in your above mine during the MCDR inspection made by the undersigned on 17-12-2021 and communicated to you vide our letter of even number dated 30.12.2021.


<u>RULE NO.</u>	<u>NATURE OF VIOLATION OBSERVED</u>
11(1)	Mining operations were not carried out in accordance with the approved mining plan with PMCP vide letter no 614(2)/76- DDN dated 14.09.2017 to the following extent: (i) As per proposal during the year 2021-22, it was proposed to carry out mining operations in pit no. I by making development of single bench at 1890 to 1885 mRL with a height of five meter. However, during the inspection, it was observed that the only single bench of more than 15 meters height has been formed leading to vertical escarpment. (ii) During the year 2021-22, it was proposed to carry out two boreholes with a cumulative meterage of 40m. During the inspection it was observed that no such exploration has been commenced so far.
26(2)	The holder of mining lease shall submit to the competent authority a yearly report as per the format specified by the Indian Bureau of Mines, before 1 st day of July every year setting forth the extent of protective and rehabilitative works carried out as envisaged in the approved mine closure plan, and if there is any deviation, reasons thereof : On perusal of office records it is observed that yearly report for the year 2020-21 has not been submitted to the competent authority by the holder of the lease in the prescribed in this office till date.
35(2) Read with rule 35(4)	Every holder of a mining lease shall monitor his mining and allied activities as per the notified template of star rating in the format prescribed in this behalf by the Indian Bureau of Mines from time to time, and shall submit online its self assessment report before the 1st day of July every year for the previous financial year, to the Regional Controller or the authorized of the Indian Bureau of Mines. Whereas holder of the mining lease has not submitted the online self assessment report as per rules for financial years 2020-21. Further as the star rating template has not been filled by you thus it is considered that you haven't scored any points and thus based on nil points your mine falls under "No Rating" category as per the Criteria for Star Rating mentioned in the notified template.
55 (1)(c)(ii)	Every holder of mining lease shall employ Part-time Mining Engineer and part-time Geologist in the mine. Both Part-time Mining Engineer and part-time Geologist have not been appointed in the mine.

2/15/3/22

2. Your letter dated 14.02.2022 on compliance of above violated rules was duly considered and examined. Since neither the boreholes have been drilled/completed nor any documents and photographs have been submitted regarding reduction of bench height; the compliance of violations can not be taken.
3. In this connection, it is brought to your notice that the violation of rules 11,26(2), 33 & 35 constitute an offence punishable under Rule 62(1) and rule 55 constitute an offence punishable under Rule 62(2) prescribed at Schedule III of MCDR Amendment Rules 2021.
4. Mining operations can also be suspended as per rule 11(2) in case of non compliance of rules 11(1) of MCDR 2017.
5. May initiate appropriate action in accordance with any competent orders/ directives etc.
6. You are therefore directed to show cause within a period of thirty days from the date of issue of this letter, as to why you should not be prosecuted and/ or why mining operation be suspended under statutory provisions and/or why not any other action be initiated in accordance with any competent orders/ directives.

Please note that no further notice shall be given to you in this regard.


भवदीयYours faithfully,

 15/3/22

एस. सकलानी/ S.Saklani
कनिष्ठखनन भूविज्ञानी JMG
भारतीय खान ब्यूरो/Indian Bureau of Mines

तिलिपि सूचनार्थ प्रेषित :-

- 1- खान नियंत्रक (उत्तर), भारतीय खान ब्यूरो, उदयपुरा(zo.udaipur@ibm.gov.in)
- 2- निदेशक उद्योग निदेशालय, हि0 प्र0 सरकार, उद्योग भवन, शिमला (हि0 प्र0). (geologicalwing@gmail.com)
- 3- गार्ड फाइल


कनिष्ठखनन भूविज्ञानी JMG