



भारत सरकार Government of India

खान मंत्रालय Ministry of Mines

भारतीय खान ब्यूरो Indian Bureau of Mines

क्षेत्रीय खान नियंत्रक का कार्यालय Office of the Regional Controller of Mines

100, ओल्डनेहरू कालोनी, देहरादून (उत्तराखण्ड) 248001 /100 Old Nehru Colony, Dehradun (U.K.)248001

TEL- 0135-2676350 / 2671896, E-mail – ro.dehradun@ibm.gov.in

VIOLATION LETTER
E-MAIL / REGD A.D.



फाईल संख्या File No: HP/SRM/LST- 49

Mine Code: 38HPR10076

दिनांक, 04, Feb 2022

सेवा में To : Mr. Rakesh Chaudhary
Banour Limestone Mine
R/O Vill- Jogiwala, Main Haridwar Road
(opp. Raj Banquet), PO- Nehrugram,
Dehradun, Uttarakhand- 248014

E-mail: oasisddun@gmail.com

विषय Sub: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Banour Limestone Mine, Mining Lease over an area of 4.75 ha located near Village –Banour Tehsil- Paonta Sahib, District- Sirmour H.P State.

महोदय Sir,

The following provisions of the Mineral Conservation & Development Rules, 2017 were found violated in your above mine during the inspection made by the undersigned on 30.12.2021 in the presence of Mr. K.N Pant Mine Manager.

<u>RULE NO.</u>	<u>NATURE OF VIOLATION OBSERVED</u>
11(1)	Mining Operation has not been carried out in accordance with the approved Review and Updation of Mining Plan of vide letter no. 614(2)/MP-B-243/14-DDN dated 31-03-2020 to the following extent: 1. As per proposals approved vide above referred letter, you were suppose to carry out exploration by means of 5 boreholes with 164 metrage in 2021-22, but during inspection it was found that the said exploration has not been carried out and even not yet started till date. This may lead to further violation of rule 12(4) of MCDR 2017 which binds the lessee to undertake detailed exploration (G1 level) over the entire potentially mineralized area under the mining lease within a period of five years from the date of commencement of these rules i.e, upto 26.03.2022.

2. In this connection, it is brought to your notice that the violation of rule 11 an offence punishable under Rule 62(1) of MCDR Amendment Rules 2021.
3. Mining operation can also be suspended as per rule 11(2) in case of non-compliance of any Rule/sub-rule of 11 of MCDR 2017.
4. You are advised to rectify the above violations immediately and intimate the compliance position to this office within 45 days from date of issue of this letter.

भवदीय Yours faithfully,

04.02.2022

(दामोदर प्रसाद शर्मा /D P Sharma)

सहायक खान नियंत्रक /Assistant Controller of Mines
भारतीय खान ब्यूरो / Indian Bureau of Mines

प्रतिलिपि सूचनार्थ प्रेषित :-

- 1- खान नियंत्रक (उत्तर), भारतीय खान ब्यूरो, उदयपुर। (zo.udaipur@ibm.gov.in)
- 2- निदेशक उद्योग निदेशालय, हि0 प्र0 सरकार, उद्योग भवन, शिमला (हि0 प्र0). (geologicalwing@gmail.com)
- 3- गार्ड फाइल

सहायक खान नियंत्रक /Assistant Controller of Mines