



भारत सरकार Government of India
खान मंत्रालय Ministry of Mines
भारतीय खान ब्यूरो Indian Bureau of Mines
क्षेत्रीय खान नियंत्रक का कार्यालय Office of the Regional Controller of Mines
100, ओल्डनेहरू कालोनी, देहरादून (उत्तराखंड) 248001 /100 Old Nehru Colony, Dehradun (U.K.)248001
TEL- 0135-2676350 / 2671896, E-mail – ro.dehradun@ibm.gov.in



फाईल संख्या File No: HP/SOLAN/LST- 02

Mine Code: 38HPR11004

दिनांक, 12 March 2020

सेवा में To : Nominated Owner,
Baga Limestone Mine,
M/s Ultratech Cements Ltd
Village: Baga, PO: Kandhar,
Tehsil: Arki, Dist.: Solan,
HP-173208

E-mail: chandrakant.dhandale@adityabirla.com

विषय Sub: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Baga-Bhalag Limestone Mine, Mining Lease over an area of 324.479 ha located near Village – Baga, Tehsil- Arki, District-Solan, H.P State.

महोदय Sir,

The following provisions of the Mineral Conservation & Development Rules, 2017 were found violated in your above mine during the MCDR inspection made by the undersigned on 17.02.2021 in the presence of Shri Chandrakant Dhandale , Mine Manager.

RULE NO.	NATURE OF VIOLATION OBSERVED
11(1)	Mining Operation were not carried out in accordance with the approved Review and Updation of Mining Plan vide letter no. 614(2)/MP-A-216/05-DDN dated 25-01-2019 to the following extent: 1. As per proposal during the year 2019-20, it was proposed to carry out mining operation from 1220 to 1210 mRL. During the inspection height of bench has been observed more than 10 meters at location of local grid coordinates N3468300, E681400. Whereas, as per approved Review and Updation of Mining Plan it should be 10 meters
45(7)	The holder of a mining lease has submitted incomplete or wrong information in Annual Returns 1. Ex. Mine Price is not matching with cost of production which shall be same in case of captive mines. 2. Part-VII Cost of Production –Reported production cost of Limestone is Rs.279/Tonnes which is very high.

2. In this connection, it is brought to your kind notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017.
3. Mining operations can be suspended as per rule 11(2) in case of non compliance of rules 11(1) and any other relevant rules of MCDR 2017 as these rules ensures systematic scientific and responsible mining.
4. Advise the State Government to order suspension of all mining operations in the mines as per provision of Rule 45(7), in case if it is found that the holder of a mining lease has submitted incomplete or wrong or false information in statutory returns or fails to submit such return within the date specified under Rule 45.
5. You are advised to rectify the above violations immediately and intimate the compliance position to this office within 45 days from the date of issue of this letter.

भवदीय Yours faithfully,

12.03.2021

(दामोदर प्रसाद शर्मा / D P Sharma)

सहायक खान नियंत्रक / Assistant Controller of Mines

प्रतिलिपि सूचनार्थ प्रेषित :-

- 1- खान नियंत्रक (उत्तर), भारतीय खान ब्यूरो, उदयपुर। (zo.udaipur@ibm.gov.in)
- 2- निदेशक उद्योग निदेशालय, हि0 प्र0 सरकार, उद्योग भवन, शिमला (हि0 प्र0). (geologicalwing@gmail.com)
- 3- गार्ड फाइल

सहायक खान नियंत्रक / Assistant Controller of Mines