भारत सरकार /GOVERNMENT OF INDIA खान मंत्रालय/ MINISTRY OF MINES

भारतीय खान ब्यूरो/ INDIAN BUREAU OF MINES

क्षेत्रीय खान नियंत्रक का कार्यालय,गोवा /OFFICE OF THE RCOM, GOA (आईएसओ ISO-9001:2015)

Phone No.: 0832-2741757 Opp. Old R.T.O. Office,

Fax No. : 0832-2741758 P.O. Fatorda,

E-mail: ro.goa@ibm.gov.in MARGAO, GOA. -403 602

No. KNT/BJP/LST-61/Goa Dated 26th February 2019

Mine code: 38KAR26058

To, Shri R.B.M.Tripathi, Agent J.K.Cements Works, Muddapur Limestone Mines P.O.Muddapur-587 122 Dist. Bagalkot, Karnataka

Sub: Violation of provisions of Mineral Conservation and Development Rules, 2017 in respect of your Muddapur Limestone {ML No. 2343(A)} over an extent of 161.87 Ha. in Bagalkot district, Karnataka State. Sir,

The following provision of the Mineral Conservation and Development Rules, 2017 was found violated in your above mine during the inspection on **19/02/2018** by undersigned in presence of the mine officials Shri R.C. Purohit, Asstt. Vice President-Mines, Shri Pawankumar Deshmukh, Mining Engineer and other officials of the mines.

| Rule | Nature of Violations observed |
|-------|--|
| No. | |
| | The mining operations are required to be carried out in accordance |
| | with the mining plan approved, modified or reviewed by the Indian |
| 11(1) | Bureau of Mines (IBM). The following deviations are observed from |
| | the proposals approved in the modified Mining Plan by IBM vide |
| | letter No. MMP/Mech-01(KNT)/Goa/2018-19 dated 25.05.2018. |
| | It is proposed to construct a retaining wall of 225 meters |
| | having height and width of 1 meter each around overburden/side |
| | burden/intermittent burden during the year 2018-19. However, no |
| | such construction progress has been observed during the |
| | inspection. |

- 02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of Mineral Conservations and Development Rules, 2017.
- 03. The mining operations can be suspended under rule 11(2) if compliance of rule 11(1) is not found satisfactory.
- 04. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

Yours faithfully

(Dr. Y.G.KALE)

Regional Controller of Mines Indian Bureau of Mines

Copy forwarded to:

- 1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
- 2. The Director, Department of Mines & Geology, Government of Karnataka, No.49, Khanija Bhavan, Race Course Road, Bangalore-560 001.

(**Dr. Y.G.KALE**) Regional Controller of Mines Indian Bureau of Mines