09.04.2019

माखुपुरा औद्वोगिक क्षेत्र,

Makhupura Industrial Area

Ajmer- 305 002 (Rajasthan) फैक्स नं 0145.2695202 फोन नं 2695165

अजमेर.—305 002 (राजस्थान)

दिनांक :





भारत सरकार Government of India खान मंत्रालय Ministry of Mines

Ministry of Mines भारतीय खान ब्यूरो

Indian Bureau of Mines

Mine Code: 34RAJ27002

संख्या: RAJ/UDP/LEAD ZINC-02/Vol-II

प्रेषित: एजेंट,सिन्देसर खुर्द लेड जिंक माइन,

मैसर्स हिंदुस्तान जिंक लिमटेड, पोस्ट-दरीबा,तहसील-रेलमगरा, जिला-राजसमन्द (राजस्थान)

ईमेल-sanjay.sharma@vedanta.co.in

विषय : Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Sindesar

Khurd Lead Zinc Mine (Lease area 199.8425Hect.) in Rajsamand District of Rajasthan State.

महोदय,

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mine during the joint inspection made on 16.03.2019 & 17.03.2019 by Dr. A.Z. Khan, Senior Mining Geologist and undersigned in presence of Sh. Dushyant Tailor, Mining Engineer & Sh. Pankaj Choudhary, Geoloist:

Geologist and undersigned in presence of Sh. Dushyant Tailor, Mining Engineer & Sh. Pankaj Choudhary, Geoloist:			
Rule No.	Nature of violation observed in detail		
Rule 11(1)	The mining operations are carried out in violation of following provisions of approved Review of Mining Plar		
	(Approved on 23.01.2018): -		
	(i)		
	Year	Proposed Surafce Exploratory Drilling	Actual Surafce Exploratory Drilling (up to Feb.19)
	2018-	Nos. of Boreholes-50	Nos. of Boreholes-22
	19	Meterage-20000m	Meterage-13607.4m
	It shows that shortfall in exploration.		
	(ii <u>)</u>		
	Year	Proposed UG Development(m)	Actual UG Development(m)
	2018-19	33676m	19707m(up to Feb.19)
	It shows that shortfall in UG development.		
	(iii) Waste dumping has also been carried out between grid 7170N to 7380N & 1120E to 1250E which was not proposed in the approved review of mining plan.		
	(iv) Construction of 200m parapet wall was proposed at the base of waste dump during the year 2018-19 but till inspection date no such wall has been constructed.		

- 02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR, 2017 and in case of non compliance of the above rules following action may be initiated under MCDR, 2017:
 - (a) Mining operations may be suspended under rule 11(2) of MCDR, 2017.
 - (b) Prosecution may be launched against you.
- O3. You are advised to rectify the above violations immediately and intimate the compliance to this within 45 (forty-five) days from the date of issue of this letter

भवदीय

(डी. आर. गुर्जर) वरिष्ठ सहायक खान नियंत्रक भारतीय खान ब्युरो

प्रतिलिपि सूचनार्थ प्रेषित :--

- 1 खान नियंत्रक (उत्तर), भारतीय खान ब्यूरो, उदयपुर (ई मेल द्वारा)
- 2 निदेशक, खान एवं भूविज्ञान विभाग, राजस्थान सरकार, उदयपूर।
- 3 खनि अभियंता, खान एवं भूविज्ञान विभाग, राजस्थान सरकार, राजसमन्द।
- ४ रक्षित पत्रावली।