

भारत सरकार/ Government of India खान मंत्रालय / Ministry of Mines भारतीय खान ब्यूरो / Indian Bureau of Mines क्षेत्रीय खान नियंत्रक का कार्यालय / Office of the Regional Controller of Mines



File No: MP/Satna/LST---

To.

1) Shree K.C. Jhanwar (Nominated Owner)
B- wing, Ahura Centre, 2nd Floor,
Mahakali Caves Road Andheri East,
Mumbai- 400093

Scheme No.-11, Kamla Nehru Nagar Jabalpur, Dated: 29 / 04 /2021

2) M/S Ultra Tech Cement Ltd. Aditya Vihar, P.O.- Bharatpur Tehsil-Rampur Naikin Distt-Sidhi (M.P.)- 486776

Subject: - Violation of provisions of Mineral Conservation & Development Rules, 2017, in respect of your Hinauti extension Limestone Mines (area-258.867 Hect.) in District of Satna in M.P. State.

Dear Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mentioned mine during MCDR inspection on 13.02.2021 by the undersigned in presence of Shree Mukesh Kumar, Mines Head and Mr Gaurav Sharma, Geologist.

Rule 11(1) MCDR 2017

- (1). Mining operations under mining lease.-(1) No holder of a mining lease shall commence or carry out mining operations in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines or prepared and certified in accordance with the system established by the State Government pursuant to the proviso to clause (b) of **sub-section (2) of section 5** or approved by the competent authority of the Atomic Minerals Directorate for Exploration and Research, in respect of minerals specified in Part B of the First Schedule to the Act where the grade of such atomic minerals is equal to or above the threshold value limits declared under Schedule-A of the Atomic Minerals Concession Rules, 2016.
- (2) If the mining operations are not carried out in accordance with the approved or certified mining plan or any information contained in the mining plan is found to be incorrect, misleading or non-compliant with applicable laws including these rules, the competent authority may by order, suspend all or any of the mining operations and permit continuance of only such operations as are required to restore the conditions in the mine as envisaged under the approved or certified mining plan or modified mining plan, for the purpose of restoration to the extent possible:

During inspection, for the year 2019-20, it is observed,

- 1. Only 31075 Tonnes of production is raised against proposal of 10,00,000 tonnes during 2019-20.
- 2. Earthen bund at toe with drain to prevent washoff was not maintained all along waste Dump created in direction away/opposite from hill side.
- 3. Only 3 nos exploratory borehole are done against proposed 13 nos.

Thus, there is violation of this rule.

- 02. In this connection it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR-2017.
- 03. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty-Five) days from the date of issue of this letter.

भवदीय

उप खान नियंत्रक

भारतीय खान ब्यूरो