

Registered/Speed Post

Violation letter



**GOVERNMENT OF INDIA
MINISTRY OF MINES
INDIAN BUREAU OF MINES
OFFICE OF REGIONAL CONTROLLER OF MINES**



**FAX : 080- 23371027 /
23373287
Tel : 080-23371027 /
23375366 / 67
Email ID:
ro.bangalore@ibm.gov.in
rcombng@rediffmail.com**

**29, Industrial Suburb, II Stage,
Tumkur Road, Gorguntapalya,
Yeshwantpur,
Bangalore- 560 022.**

No.KNT/BLR/FE/51/BNG

Date: 01.02.2018

To,

Shri.Gogga Vishwanath Swamy,
Nominated Owner,
M/s Gogga Gurushanthaiah & Bros.,
P.B.No.4,Nehru Co-Operative Colony,
Hoset Taluk,
Ballari Dist.
Karnataka- 583203

Sub: Violation of provisions of Mineral Conservation and Development Rules, 2017 in respect of your Jambunatha Iron Ore & Red Oxide Mine (ML-2522) of M/s Gogga Gurushanthaiah & Bros. over an area of 43.91 Ha located in Jambunatha Village, Sandur Taluk, Ballari District of Karnataka State.

Sir,

The following provisions of the Mineral Conservation & Development Rules 2017 were found violated in your above mine during the inspection carried out by the undersigned in presence of Shri. K.V.Bhaktavatsala Naidu, Sr. General Manager (Mines) and Shri. Mekala Peddanna, Geologist on 08.01.2018.

Rule	Nature of violations observed
11(1)	<p>Modification in the approved scheme of Mining with PMCP was approved vide letter no.279/21/88/BNG dated 04.09.2015 for a period of 2015-16 to 2018-2019. The deviation observed in mining operation vis-a-vis approved document are given below</p> <p>As per the approved document, the benches of 7.5 Mts height and width more than the height was proposed in the working benches. It was observed that the adequate width of the benches was not maintained.</p>

31(4)	<p>General requirements about plans and sections.- The plans and sections required under these rules shall be maintained up to date within three months in case of category 'A' mines as referred to in clause (a) of sub-rule (2) of rule 55, and within twelve months in the case of any other mine.</p> <p>The plan & sections were not maintained & updated within three months as this is a category 'A' mines.</p>
-------	---

02. In this connection it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017. Further, the violation of Rule 11(1) may also attract provisions of Rule 11(2) of MCDR, 2017 regarding suspension of mining operations till the compliance of violations.

03. You are advised to rectify/explain the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

Yours faithfully,

Sd/-
(Arun Kumar)
Deputy Controller of Mines

Copy forwarded to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Department of Mining & Geology, No.49, Khanijabhavan, R.C. Road, Bangalore-560 001

Sd/-
(Arun Kumar)
Deputy Controller of Mines