



GOVERNMENT OF INDIA
MINISTRY OF MINES
INDIAN BUREAU OF MINES
OFFICE OF REGIONAL CONTROLLER OF MINES

FAX : 080- 23371027 / 23373287
Tel : 080-23371027 / 23375366 / 67
Email ID: ro.bangalore@ibm.gov.in
rcombng@rediffmail.com



29, Industrial Suburb, II Stage,
Tumkur Road, Gorguntapalya,
Yeshwantpur,
Bangalore- 560 022.

NO: KNT/MYS/Mgst-13 /BNG

04.04.2018

To: Shri N. Rajashekhar.
"SRI NANJUNDESWARA NILAYA"
No 38, Housing Board Colony, Udaya Ravi Road,
Kuempunagar,
MYSURU – 570 023.

Sub: Violation of provisions of MCDR, 2017 in respect of your Taloor Magnesite mine, ML 2484(12.10 Ha) in Taloor village, Mysuru taluk and district, Karnataka state.

Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mine during the inspection on 20.03.2018 by Sri K. Srinivas. Asstt. Mining Geologist, accompanied by Sri Y. Narayana Rao, Agent.

Rule No.	Violations observed
11(1)	Scheme of Mining was approved vide letter no. 279/770/2003/BNG dated 29.09.2015 for the period 2015-16 to 2019-20. The deviations observed in mining operations vis-à-vis approved document are given below. It was proposed to dig 9 exploratory pits and 3 trenches during three years i.e., 2015-16 to 2017-18, whereas only five trial pit have been dug.
46	As per the rule, every holder of mining lease shall send a notice of appointment of a whole-time mining engineer and a geologist under sub-rule (1) of rule 55 of MCDR 2017, but no such notices have been sent to this office.

02. In this connection it is brought to your notice that the violation of rule 11(1) may also attract provision of rule 11(2) of MCDR, 2017 regarding suspension of mining operations till the compliance of violations.

03. You are advised to rectify/explain the valid reasons for the above violations immediately and intimate the position to this office within 45 (forty five) days from the date of issue of this letter

Yours faithfully,

Sd/-

(C. Parameswaran)
Dy.Controller of Mines

Copy for information to:

1. The Controller of Mines(SZ), IBM, Bangalore
2. The Director, Department of Mining & Geology, No. 49, Kanijabhavan,R.C.Road,
Bangalore – 560 001.

Sd/-

(C. Parameswaran)
Dy.Controller of Mines