

भारत सरकार
खान मंत्रालय
भारतीय खान ब्यूरो
क्षेत्रीय खान नियंत्रक का कार्यालय
कर्मयोगी भवन, सेक्टर-10A, चतुर्थ माला,
ब्लॉक-2, सी विंग, गांधीनगर
ई-मेल: gandhinagar.ibm@gmail.com



GOVERNMENT OF INDIA
MINISTRY OF MINES
INDIAN BUREAU OF MINES
Office of Regional Controller of Mines
Karmayogi Bhavan, 4th Floor, Block-2, Sector-10A,
Gandhinagar-382010, Gujarat

मिसिल सं. GUJ/JUNA/LST-303

दिनांक: 05.03.2019

प्रेषित : **M/s. Gujarat Heavy Chemicals Ltd**
Taluka-Sutrapada,
Dist-Junagadh, Gujarat-362275.
Email: manishkumar@ghcl.co.in

विषय : गुजरात राज्य के Junagadh जिले के Sutrapada तालुका में स्थित आपकी Bhimdeol Limestone Mine, सर्वे नं-[88/P] क्षेत्रफल-56.3517 में खनिज संरक्षण व विकास नियमावली 2017 के प्रावधानों का उल्लंघन | (**Mine Code-38GUJ08348**)

महोदय,

अधोहस्ताक्षरी द्वारा दिनांक 02/02/2019 को आपकी उपरोक्त खान के निरीक्षण के दौरान खनिज संरक्षण एवं विकास नियमवाली 2017 के प्रावधानों का उल्लंघन पाया गया।

नियम सं.	पाए गए उल्लंघन की विस्तृत प्रकृति
Rule 31(4)	<i>The plans and sections required under these rules shall be maintained up to date within three months in case of category 'A' mines as referred to in clause (a) of sub-rule (2) of rule 55</i> But in your case, required plans & sections under these rules are not updated on quarterly basis and not maintained at mines site office.
Rule 35(2)	<i>Every holder of a mining lease shall monitor his mining & allied activities as per the notified template of star ratings in the format prescribed in this behalf by Indian Bureau of Mines from time to time, and shall submit online its self-assessment report before the first day of July every year for the previous financial year, along with the soft copy of high resolution satellite images from CARTOSAT-2 satellite LISS-IV sensor on the scale of cadastral map, as on the 31st day of March for that financial year, covering the mining lease and an area of two kilometers from the lease boundary, to the Regional Controller of Mines.</i> But, in your case, you have submitted the online Star Rating Templates for the year 2017-18 but soft copy of high resolution satellite images from CARTOSAT-2 satellite LISS-IV sensor not submitted to the Regional Controller of Mines, Gandhinagar.
Rule 45(5)(c)	<i>In annual Return submitted for the year 2017-18 in form H-8 to the Regional Controller of Mines found following discrepancies –</i> i) Part-I under item-12, Utilization of lease area not shown correctly & mismatching with figures furnished in Review of Mining Plan. ii) Part-II under item-1, Appointment of Geologist is incorrectly marked as “Partly employed”. iii) Part-V under item-1, Proved mineral reserves & resources are not furnished correctly & mismatching with given draft Review of Mining Plan figures. iv) Part-VI under item-1, Ex-mine furnished for Chemical grade limestone as Rs-345.25/Tonne appears to be on higher side. iii) Part-VII: Under the cost of production for the year 2017-18, details of DMF & NMET

	contribution details have not been incorporated.
Rule 54(a)	<p><i>The holder of the mining lease or a holder of prospecting license or prospecting cum mining lease shall maintain details of contribution made to District Mineral Foundation and National Mineral Exploration Trust</i></p> <p>But, in your case, it is observed during inspection that you have not maintained relevant documents as required under prescribed rules.</p>

2. इस संदर्भ में आपका ध्यान आकर्षित किया जाता है की उपरोक्त नियमों का उल्लंघन खनिज संरक्षण व विकास नियमावली, 2017 के नियम 62 के अंतर्गत दंडनीय अपराध है तथा इन नियमों के उल्लंघन की अनुपलना नहीं होने पर खनिज संरक्षण व विकास नियमावली, 2017 के नियम 45(7)(a)(i) के अंतर्गत खदान की सारी संक्रियाएं बंद की जा सकती है / आपके विरुद्ध अभियोग दायर किया जा सकता है और/या राज्य सरकार से खदान की सारी संक्रियाएं बंद करने और/या आपके विरुद्ध अभियोग दायर करने की सिफारिश की जा सकती है |
03. अतः आपको सलाह दी जाती है कि आप उपरोक्त उल्लंघनों का तत्काल सुधार कर इसकी सूचना इस पत्र के जारी होने की तिथि से 45 (पैंतालीस) दिनों के अंदर इस कार्यालय को भेजे

भवदीय,

(संजय गिरहे)
वरिष्ठ खनन भूविज्ञानी
भारतीय खान ब्यूरो

प्रतिलिपि सूचनार्थ हेतु प्रेषित:-

1. खान नियंत्रक (उ.) भारतीय खान ब्यूरो, उदयपुर को सूचनार्थ हेतु |
2. उप महानिदेशक 1/4lk Wfj;dh½ खनन एवं खनिज 1/4lk Wfj;dh½ प्रभाग, भारतीय खान बुरों, इन्दिरा भवन, नागपुर-440001
3. आयुक्त, भूविज्ञान व खनन विभाग, ब्लॉक-1, 7वा माला, उद्योग भवन, गांधीनगर (गुज.),
4. रक्षित पत्रावली |

वरिष्ठ खनन भूविज्ञानी
भारतीय खान ब्यूरो