



**VIOLATION LETTER**

**भारत सरकार GOVERNMENT OF INDIA**  
**खान मंत्रालय MINISTRY OF MINES**  
**भारतीय खान ब्यूरो INDIAN BUREAU OF MINES**  
**क्षेत्रीय खान नियंत्रक के कार्यालय**  
**OFFICE OF THE REGIONAL CONTROLLER OF MINES**



Phone: 0674-2352463;  
TeleFax: 0674-2352490;  
eMail:

ro.bhubaneshwar@ibm.gov.in  
Plot No.149, Pokhariput  
BHUBANESWAR-751020

No.: ORI/IRON/SNG/MCDR-5/BBS/III / 2448  
सेवा में,  
Shri M.D.Rustagi, Director & Nominated Owner  
M/s Rungta Sons (p) Ltd.,  
Rungta office, main road,  
At/Po: Barbil, District: Keonjhar  
State: Odisha Pin Code: 758035

Date: 05/03/2019

**Sub: Violation of provisions of MCDR, 2017 in respect of your Oraghat Iron ore Mines, over an area of 82.961 Ha in Sundergarh district of Odisha**

Sir,

The following provisions of Mineral Conservation and Development Rules, 2017 were found violated in your above said mine during inspection on 17.02.2019 by the undersigned accompanied by S/Shri A.S.Mohapatra, Agent, A.K.Choudary, Mine Manager of your mine:

Rule No.	Proposed in the approved mining plan / Rule	Violation
11 (1)	<p>As per the approved mining scheme dated 28/02/2016 and 10/10/2017</p> <p>i) It is proposed to generate 951159 cu.m. of waste material with production of 6.62 million tonnes of Iron ore, 0.73 million tonnes of mineral reject, and both combined as ROM of 7.35 million tonnes of iron ore from in-situ excavation of 4 nos of pits with a stripping ratio of 1:0.13 t/cu.m. of ROM during the year 2017-18.</p> <p>ii) It is proposed to produce 1 million tonnes of Iron ore ROM from dump re-handling viz., dump-2, dump-1 and SG-2 during the year 2017-18.</p> <p>iii) It is proposed wet beneficiation 1.5 million tonnes of ROM during the year 2017-18.</p> <p>iv) It is proposed to dump the waste generated during the year 2017-18 in Dump-4.</p> <p>v) it is proposed to backfill the kendu pit during the year 2018-19 by the waste generated during mining in the year 2018-19.</p> <p>vi) It is proposed to construct 438 m length of retaining wall and 288 m length of garland drain around Dump-3 &amp; 4 and SG-2 during the year 2017-18 as protective measures around dump.</p>	<p>i) During inspection it is observed that 885251 cu.m. of waste was generated by producing 3007794 tonnes of ROM with Nil production of Mineral reject from 3 nos of pits and with a stripping ratio of 1:0.03 t/cu.m. which is not as per the proposal in the mining plan.</p> <p>ii) During inspection it is observed that production of ROM of iron ore from dump re-handling is 9820 tonnes only.</p> <p>iii) During inspection it is observed that no wet beneficiation of ROM was carried out during the year.</p> <p>iv) During inspection it is observed that waste generated during the year 2017-18 was not dumped in the designated area of Dump-4, whereas it was stacked in between Dump-1 and Kendu Pit which is not as per proposal in the mining plan.</p> <p>v) During inspection it is observed that waste generated during the year 2018-19 was not backfilled in the Kendu pit, whereas it was stacked in between Dump-1 and Kendu Pit which is not as per proposal in the mining plan.</p>

*OR*



		vi) During inspection it is observed that only 341 m length retaining wall and 180 m length of garland drain was constructed during the year.
--	--	---

02. It is brought to your notice that these violations constitute an offence punishable under Rule 62 of MCDR, 2017.

*Besides, inability to comply with the provision of Rule 11 (1) is liable for suspension of mining operations according to the provisions of Rule 11 (2) of MCDR, 2017.*

03. You are advised to rectify the above violations immediately and intimate the position to this office within **45 (forty-five) days** from the date of issue of this letter.

Yours faithfully,

*R. Kishan*  
(Ramkishan R) 5/3/19

Senior Assistant Controller of Mines  
Indian Bureau of Mines

*R*

मूल प्रति पर नही / Not on Original प्रतिलिपि निम्न को सादर सूचनार्थ अग्रेषित

(1) **The Controller of Mines (EZ), भारतीय खान ब्यूरो / Indian Bureau of Mines, Kolkata-700091.**

(2) **डायरेक्टर ऑफ माइन्स / The Director of Mines, डायरेक्टोरेट ऑफ माइन्स / Directorate of Mines, उड़ीसा सरकार / Government of Orissa, हेड्स ऑफ डिपार्टमेंट बिल्डिंग / Heads of Department Building, न्यू कैपिटल / New Capital, भुवनेश्वर / Bhubaneswar-751 001 : For information & further necessary action on following :**

*R. Kishan*  
(Ramkishan R) 5/3/19

Senior Assistant Controller of Mines

कृते क्षेत्रीय खान नियंत्रक / For Regional Controller of Mines

*R*

*Issued*

*5/3/19*