



भारत सरकार Government of India

खान मंत्रालय Ministry of Mines

भारतीय खान ब्यूरो Indian Bureau of Mines

क्षेत्रीय खान नियंत्रक का कार्यालय Office of the Regional Controller of Mines

100, ओल्डनेहरू कालोनी, देहरादून (उत्तराखण्ड) 248001 /100 Old Nehru Colony, Dehradun (U.K.)248001

TEL- 0135-2676350 / 2671896, E-mail – ro.dehradun@ibm.gov.in



फाईल संख्या File No: HP/SRM/LST-50 Mine Code: 38HPR100079 दिनांक, 13 March 2020  
 सेवा में To : M/s Janki Mines & Minerals E-mail: janakiminesminerals@gmail.com  
 R/o- Village-Kamroo,  
 Tehsil-Paonta Shaib,  
 Distt.-Sirmour (H.P)

विषय Sub: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Bhimgoda Limestone Mine over an area of 5.61 ha located near Village-Kamroo, Tehsil-Paonta Sahib in Sirmour district of HP State.

महोदय Sir,

The following provisions of the Mineral Conservation & Development Rules, 2017 were found violated in your above mine during the inspection made by the undersigned on 24.01.2020 in the presence of Shri Kedareshwar Mishra Mine Manager.

<u>RULE NO.</u>	<u>NATURE OF VIOLATION OBSERVED</u>
11(1)	Mining operation were not carried out in accordance with the approved modified mining plan vide letter no 614(2)/MP-B-182/02- DDN dated 4/1/2018 to the following extent: (i) As per proposal during the year 2018-19, it was proposed to carry out mining operation by formation of 2 benches of 5 meter each in height from 1845 mRL to 1835 mRL. During the inspection it was observed that benches have not been developed from 1845 mRL downward so far. (ii) As per proposal during the year 2018-19, it was proposed to carry out 02 bore holes total metrage 135.7 mtr , but during the inspection it was observed that no bore hole has been carried out so far.
26(2)	The holder of mining lease shall submit to the competent authority a yearly report as per the format specified by the Indian Bureau of Mines, before 1 <sup>st</sup> day of July every year setting forth the extent of protective and rehabilitative works carried out as envisaged in the approved mine closure plan, and if there is any deviation, reasons thereof : On perusal of office records it is observed that yearly report for the year 2018-19 has not been submitted to the competent authority by the holder of the lease in the prescribed in this office till date.
33	The holder of a mining lease shall, on or before the 30 <sup>th</sup> day of June every year submit to the authorized officer a digital copy along with a print copy of the surface geological plans and sections maintained under rule 32. However, the lessee has not submitted the copies of the plans and sections as per rules.
35(2)	Every holder of a mining lease shall monitor his mining and allied activities, as per the notified template of star rating in the format prescribed in this behalf by the Indian Bureau of Mines from time to time, and shall submit online its self assessment report before the 1 <sup>st</sup> day of July every year for the previous financial year, along with the soft copy (in standard format), of high resolution satellite images obtained from CARTOSAT-2 satellite LISS-IV sensor on the scale of cadastral map, as on the 31 <sup>st</sup> day of march for that financial year, covering the mining lease and an area of two kilometers from the lease boundary, to the Regional Controller or the authorized of the Indian Bureau of Mines. Whereas holder of the mining lease has not submitted by the online self assessment report and the satellite images as per rules.

45(7)	The holder of a mining lease has submitted incomplete or wrong information in Monthly return as follows: 1. Ex Mine Price report is not correct from June 2019 to Feb 2020
55	Every holder of mining lease shall employ a geologist in the mine. But geologist has not been appointed in the mine.

2. In this connection, it is brought to your kind notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017.
3. Mining operations can be suspended as per rule 11(2) in case of non compliance and it constitutes non compliance of Rule 11(1) of MCDR, 2017.
4. The mining operation may be advice to the State Govt. for suspension of all the mining operation in this mine as per provision of Rule 45(7), in case of non compliance of Rule 45(7).
5. You are advised to rectify the above violations immediately and intimate the compliance position to this office within 45 days from the date of issue of this letter.

भवदीय Yours faithfully,

*D P*  
13.03.2020

(दामोदर प्रसाद शर्मा / D P Sharma)

सहायक खान नियंत्रक / Assistant Controller of Mines

प्रतिलिपि सूचनार्थ प्रेषित :-

- 1- खान नियंत्रक (उत्तर), भारतीय खान ब्यूरो, उदयपुर। (zo.udaipur@ibm.gov.in)
- 2- निदेशक उद्योग निदेशालय, हि० प्र० सरकार, उद्योग भवन, शिमला (हि० प्र०). (geologicalwing@gmail.com)
- 3- गार्ड फाइल

सहायक खान नियंत्रक / Assistant Controller of Mines  
भारतीय खान ब्यूरो / Indian Bureau of Mines