

## Government of India Ministry of Mines Indian Bureau of Mines Office of the Regoinal Controller of Mines, Jabalpur

File No. MP/BGT/MN-70/NGP/ 787 - 791

Date: 16/04/2020

To.

Shri Pradyuman Kumar Trivedi GFSR (Gulla) Mn Mine (10 Hect) M/s J. K. Minerals, Main Road, Balaghat Dist – Balaghat (MP) 481001

M/s J. K. Minerals, GFSR (Gulla) Mn Mine (10 Hect) P.O. Box no. 01, Main Road, Balaghat Dist – Balaghat (MP) 481001

**Subject:** Violation of provisions of Mineral Conservation and Development Rules, 2017, in respect to GFSR (Gulla) Mn Mine (10 Hect), M/s J. K. Minerals, Mine code 40MPR01074 at Vill: Sonewani, The-Lalburra, Dist – Balaghat (MP) 481332

Sir,

Undersigned has inspected your mine in the presence of Shri B.S. Setty (Mine Manager), P.L. Uikey (Mining Engineer), Sh. R.K. Nageshwar (Mine Geologist) and Sh Pawan kumar on 06/03/2020. Following provisions of MCDR 2017 were found violated in your mines during inspection.

Rule No

Nature of violation observed in detail

Rule 26(2) The holder of mining lease shall submit to the competent authority a yearly report as per the format specified by the Indian Bureau of Mines, before 1<sup>st</sup>day of July every year setting forth the extent of protective and rehabilitative works carried out as envisaged in the approved mine closure plan, and if there is any deviation, reasons thereof:

During scrutiny of the office records, it has been observed that the yearly report in respect of rule 26(2) of MCDR 2017 has not been submitted for the year 2018-19.

Rule 31 (4) The plans and sections required under these rules shall be maintained up to date within three months in case of category 'A' mines as referred to in clause (a) of sub-rule (2) of rule 55, and within twelve months in the case of any other mine.

During inspection it has been observed that the plans and sections have not been up to dated as per provisions of the rules.

Rule 33 Copies of plans and sections to be submitted – The holder of mining lease shall on or before the 30<sup>th</sup> day of the June every year submit to the authorized officer, as the case may be, and the State Govt. a digital copy along with a print copy of the surface geological plans and sections maintained under rule 32.

During scrutiny of office records, it has been observed that the documents have not been submitted to this office as per rule.

1. In this connection, it is brought to your notice that the above violations constitute an offered punishable under Rule 62 of Mineral Conservations and Development Rules, 2017.

2. The mining operations can be suspended under the rule 11(2) of MCDR-2017, if compliance of rule 11(1) of MCDR-2017 is not found satisfactory.

3. You are advised to rectify the violations of abovementioned rules immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

> उप खान नियंत्रक भारतीय खान ब्यूरो

## NOO:

## प्रतिलिपि प्रेषित : :

01. The Director of Geology & Mining, Govt .of Madhya Pradesh, Khanij Bhavan, 29-A, Arera Hills, Bhopal(M.P.) for information and further necessary action.

02. The District Collector, Balaghat (M.P.) for information.

उप खान निय भारतीय खान ब्यूरो

प्रतिलिपि प्रेषित :

खान नियंत्रक (मध्य), भारतीय खान ब्यूरो, नागपुर को सूचनार्थ प्रेषित।

उप खान नि भारतीय खान ब्यूरो