



## भारत सरकार Government of India खान मंत्रालय Ministry of Mines

## भारतीय खान व्यूरो Indian Bureau of Mines





TEL- 0135-2676350 / 2671896, E-mail - ro.dehradun@ibm.gov.ln

March 2020

सेवा में To:

फाईल संख्या File No: HP/BLS/LST- 9-DDN, CV-WFH Mine Code: 38HPR01003 General Manager (Mines)

E-mail: pankaj.nayan@acclimited.com

Gagal Cement Works M/s ACC Limited

PO-Barmana, Bilaspur, HP-174013

विषय Sub:

Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Gagal Limestone Mine over an area of 231.25 ha located near Village -Barmana, Tehsil-

Sadar, District-Bilaspur, H.P State.

महोदय Sir,

The following provisions of the Mineral Conservation & Development Rules, 2017 were found violated in your above mine during the check-up inspection made by the undersigned on 16.02.2020 in the presence of Mr.Rizwan Jamil, Mining Engineer and Shri LSK Prasad Geologist;

RULE

## NATURE OF VIOLATION OBSERVED

NO. 11(1)

Mining operations are not carried out in accordance with the approved modified mining plan vide letter no. 614(2)/MS-A-138/2003-DDN Date:- 09.02.2018 to the following extent: Area of around 1.05 ha is found less as compared to total area put to use by end of mining plan period, , including proposed area. Thus additional FA need to be furnished as per Rule 27 of MCDR 2017 for such area.

The Holder of Mining lease Shall Maintain the Royalty assessment Register. Whereas the same 54 was not found maintained

2. In this connection, it is brought to your kind notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017.

3. Mining operations can be suspended as per rule 11(2) in case of non compliance and it constitutes non

compliance of Rule 11(1) of MCDR, 2017.

4. You are advised to rectify the above violations immediately and intimate the compliance position to this office within 45 days from the date of issue of this letter.

क्षेत्रीय खान नियंत्रक / Regional Controller of Mines

प्रतिलिपि स्चनार्थ प्रेषित :-

1- खान नियंत्रक (उत्तर), भारतीय खान ब्यूरो, उदयपुर। (zo.udaipur@ibm.gov.in)

- 2- निदेशक उद्योग निदेशालय, हि0 प्र0 सरकार, उद्योग भवन, शिमला (हि0 प्र0). (geologicalwing@gmail.com)
- 3- गार्ड फाइल

क्षेत्रीय खान नियंत्रक / Regional Controller of Mines भारतीय खान ब्यूरो / Indian Bureau of Mines