

भारत सरकार /GOVERNMENT OF INDIA खान मंत्रालय/ MINISTRY OF MINES भारतीय खान ब्यूरो /INDIAN BUREAU OF MINES

क्षेत्रीय खान नियंत्रक कार्यालय/ OFFICE OF THE REGIONAL CONTROLLER OF MINES

फैक्स: (080) 23371027 / 23373287

29, इंडस्ट्रियल सबर्ब II स्टेज,, तुमक्र रोड,

दूरभाष: 080-23371027 / 23375366/67 Email ID: ro. bangalore@ibm.gov.in. गोरगुंटापाल्या येशवंतपुर,

Email ID: ro. bangalore@ibm.gov.in

बेंगलुरु -560022

सं.KNT/BLR/Fe-455/BNG

दिनांक :11.09.2019

सेवा में

Shri. Md. Abdul Saleem, Vice President & Agent (Mines), Satyalaya, Door No 266(Old No 80), Behind Taluka Office, Palace Road, Ward No 1, Sandur-583119, Ballari District, Karnataka.

विषय/Sub: Violation of provisions of Mineral Conservation and Development Rules, 2017 in respect of your of Ramghad Manganese and Iron Ore Mine (ML-2679) over an area of 139.20 Ha (As per Lease Deed) located in Ramgad village, Sandur taluka, Bellary district of Karnataka State.

महोदय/Sir,

The following provisions of the Mineral Conservation & Development Rules 2017 were found violated in your above mine during the inspection carried out by the undersigned in presence of, Shri Shridhar P Hegde – Mines Manager, Shri Karthik A K-Mining Engineer & Shri Subramanyam-Geologist on 30.08.2019.

Rule	Nature of violations observed
35(2)	The Online self assessment template of Star Rating has been sent to the Regional Controller of Mines, IBM but high resolution Satellite image obtained from CARTOSAT-2,LISS IV sensor of the previous financial year (2018-19) covering the mining lease and an area of two kilometers from the lease boundary has not been submitted.
45(7)	Following deficiencies were observed in the Annual Returns submitted: i) Sale Value & Ex mine price of Manganese Ore submitted in Part - VI (Production, Dispatches and Stock) of the Annual Return is not matching. ii) Fixed Assets is shown as Zero & the details like land, building, plant, machineries, capitalized expenditures in Part- IIA are not furnished in the AR 2018-19.

- 02. In this connection it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017. Further, the violation of Rule 11(1) may also attract provisions of Rule 11(2) of MCDR, 2017 regarding suspension of mining operations till the compliance of violations.
- 03. You are advised to rectify/explain the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

भवदीय/Yours faithfully,

(अरुण कुमार) उप खान नियंत्रक भारतीय खान ब्यूरो

प्रतिलिपि सूचनार्थ'/Copy for kind information to:

- 1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
- 2. The Director, Department of Mining & Geology, No.49, Khanijabhavan, R.C. Road, Bangalore-560 001

उप खान नियंत्रक भारतीय खान ब्यूरो