

Hkkjr ljdkj/Government of India [kku ea=ky;/Ministry of Mines Hkkjrh; [kku C;wjks/Indian Bureau of Mines हैदराबाद {ks=h; dk;kZy;/Hyderabad Regional Office



No. AP/CDP/Fe-3/HYD

Room No.603,CGO Towers,6th Floor, Kavadiguda, Secunderabad-500080. 22/5/2020

To

Owner/Agent Chabali Iron Ore Mine M/s. Benita Industries Limited Chabali Village Pendlimarri Mandal, YSR Kadapa District, Andhra Pradesh State.

Sub: Violation of provisions of Mineral Conservation and Development Rules, 2017 in respect of Chabali Iron Ore Mine Of M/s. Benita Industries Limited over an extent of 163.482 ha in Chabali Village, Pendlimarri Mandal, YSR Kadapa District, Andhra Pradesh.

Sir,

The following provisions of Mineral Conservation and Development Rules 2017 (MCDR, 2017), were found violated in your above mine during the inspection on 22.02.2020 by the undersigned in the presence of Shri. Y.M.Mahesh, Mines Manager.

Rule No-	Nature of violation					
55(1)	For the purpose of carrying out reconnaissance, prospecting or mining operations in accordance with these rules – every holder of a mining lease shall employ, in case of (i) category 'A' mines, a whole-time geologist. However during inspection it was noticed that Geologist appointed was not having					
	experience of 5 years geologist as per the Rule No. 55 (1) 3 of MCDR 2017.					
19 (1)	Where heavy earth moving machinery is used in mines, the holder of a mining lease shall maintain log books duly authenticated by the Manager or Mining engineer of such mines in respect of each machine showing date-wise account of hours worked, hours not worked, reasons for non-working, consumption of fuel or energy and lubricants and output of the machine during the corresponding working hours. However during inspection it was noticed that the log books were not maintained as per the contents mentioned in the Rule No.19 (1).					
31 (4)	The plans and sections required under these rules shall be maintained up to date within three months in case of category 'A' mines as referred to in clasue (a) of sub-rule of rule 55, and within twelve months in the case of any other mine. However it was noticed that plans and sections were not updated as per Rule No. 31(4).					

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule- 62 of MCDR, 2017.

03.	You are advised to rectify the above v	iolations ir	mmediately	and intimate	the position	to this	office
with	nin 45 (Forty five) days from the date of	of issue of the	his letter.				

Yours faithfully,

(Madhu Sudhan Yadav.M) Assistant Controller of Mines

Copy for information &further necessary action to

- 1. The Director of Mines & Geology, Sri Anjaneya Towers, D.No.7-104,B-Block,5th & 6th Floors, Ibrahimpatnam, Vijayawada,Govt. of Andhra Pradesh-521 456.
- 2. The Assistant Director of Mines & Geology, Kadapa district, Andhra Pradesh.

(Madhu Sudhan Yadav. M) Assistant Controller of Mines

मूल प्रति पर नहीं:

1 खान नियंत्रक महोदय (द), भारतीय खान ब्यूरो, बैंगलूरू.

(मधु सुधन यादव. एम) सहायक खान नियंत्रक